


Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



[> Back to OneMotoring](#)

Enquire Road Tax Payable / Prerequisite(s) To Fulfil

Please Note :

- Vehicle is on GIRO.
- The information contained herein is correct as at 19 Jun 2018.

Vehicle Particulars

Vehicle No.:	SGN8209G
Current Road Tax Expiry Date:	28 Nov 2018
New Road Tax Start Date:	29 Nov 2018
New Road Tax Expiry Date:	28 Nov 2019

Prerequisites (Updating of records may take about 3 working days)

Sufficient Insurance Coverage :	No
Vehicle Inspection Required :	Yes

Net Road Tax Amount

Road Tax Amount:	Amount
	(S\$)
Nett Road Tax Amount:	890.00
Amount Payable	890.00

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Nett Road Tax Amount:	890.00	-	890.00
Total Amount Payable			
Late Renewal Fees Payable From			890.00

	Late Renewal Fees (S\$)	Total Amount with Late Renewal Fee (S\$)
29 Nov 2018	50.00	940.00
29 Dec 2018	100.00	990.00
12 Feb 2019	120.00	1,010.00
01 Mar 2019	270.00	1,160.00

[Previous](#)

[OK](#)

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 20 Jun 2018 / 11:52:56

Receipt Date/Time : 20 Jun 2018 / 11:52:56

Tax Invoice/Receipt

Receipt No. : ITNET-0C000-180620-000892

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SFV7711Z As at 18 Jun 2018/18:50:00 Insurance Co: AXA INSURANCE PTE LTD			
1	Insurance Enquiry - SFV7711Z Enquiry Fee 20180620115214357607	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx0257 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

K & t Cars

53 Ubi Ave 1 #01-23 Paya Ubi Ind Park
Singapore 408934
Tel: 6844 5938 Fax: 6285 5228
Email: kntcars@gmail.com
Biz Reg. No.: 53208965X

VEHICLE RENTAL AGREEMENT

NO.: KT-03592

Veh. No.: <u>SGN 8209G</u>	Replace Veh. No.: <u>SKK 8607J</u>
Veh. M / M: <u>TOYOTA VIOS</u>	Replace Veh. M / M: <u>TOYOTA ACTIS</u>

HIRER'S PARTICULAR		☐ SAME AS HIRER DRIVER'S PARTICULAR	
Name: <u>Robert Limousine Services Pte Ltd.</u>	Name: <u>Ng Yen How Wifred Valentine</u>		
Address: <u>53 Ubi Ave 1, #03-47.</u> <u>Paya Ubi Industrial Park (408934)</u>	Address: <u>Blk 205, Tampines ST 21,</u> <u># 06-1277, S (520205)</u>		
U/C: <u>2004 067227</u>	D.O.B:	U/C: <u>S 8020859 F</u>	D.O.B: <u>27.06.1980</u>
Contact:	Pass Date:	Contact: <u>9155 2255</u>	Pass Date: <u>15.05.2004</u>

	A - ACCIDENT	Hirer's acceptance
	C - CRACKED	
	D - DENTS	Driver's acceptance
	S - SCRATCHES	

RENTAL DETAILS					
Mileage Out		REMARKS	Mileage In		REMARKS
Date Out	<u>19.06.18</u>		Date In	<u>29.06.18</u>	
Time Out	<u>12:20</u>		Time In	<u>1700</u>	
ASSIGNED BY			CHECKED BY		

RENTAL CHARGES				PETROL / DIESEL LEVEL					
Daily	@ \$	<u>120</u>	<u>10</u> Days @ \$ <u>1200</u>	OUT	E	¼	½	¾	F
Weekly	@ \$		Wks @ \$						
Monthly	@ \$		Mth @ \$	IN	E	¼	½	¾	F
Hours	@ \$		Hrs @ \$						
*Inclusive of additional charges (if any)				Petrol Charges YES NO AMT: _____ CDW YES NO AMT: _____ Security Deposit YES NO AMT: _____ Advance Payment YES NO AMT: _____					
Payment: ☐ CASH ☐ NETS ☐ CHQ ☐ VISA ☐ MAST Bank / Cheque No.:				Amt payable* \$ <u>1200</u>					

I/We have read and agree to the terms and conditions stated on this page and overleaf. I/We am/are also aware that should there be any parking and/or traffic offence committed during the leasing period when the vehicle is in my/our possession, we will be billed accordingly. Subsequently, our personal details may be tendered accordingly to the government parking and/or traffic offence department. With us undersigning below, I/We am/are sure that all information I/We have given to K & t CARS in connection with this agreement are true and accurate.

IMPORTANT INFORMATION (To be go through by the personnel of K & t CARS to the hirer and/or driver upon leasing of vehicle)

- Only persons above 26 and below 60 years of age with 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the company K & t CARS.
- Use of the vehicle illegal purpose such as in connection with theft, drug peddling or trafficking, smuggling is strictly prohibited.
- Additional drivers are required to register with us before they are allowed to drive the vehicle. Otherwise, he/she will not be protected by the insurance cover.
- The hirer shall be liable for excess charges for any late return of the rate shown per hour or on a per day basis.
- In case of any accident, the hirer MUST report to K & t CARS immediately regardless of the seriousness of the impact occurred. If there are bodily injuries, a police report MUST be made within the next 24 hours.
- In view of all accident, the hirer will bear the full responsibility for the SGD\$3,500/- excess payable to K & t CARS and also the first SGD\$3,500/- excess for damaged to the third party vehicle.

ACKNOWLEDGEMENT	
Signature of hirer / driver (company stamp if any)	For and on behalf of K & t CARS (authorised signature only)

K & t Cars

53 Ubi Ave 1 #01-23 Paya Ubi Ind Park Singapore 408934
Tel: 6844 5938 Fax: 6285 5228 Email: kntcars@gmail.com
Biz Reg. No.: 53206963X

No.:

OFFICIAL RECEIPT

Date: 04/10/18

Received from Roset Limousine Services PTE LTD

The Sum of Dollars One Thousand Two Hundred Dollars

Being payment of S\$K86073 19/06/18 to 29/06/18

\$ 1200 / 00

K & t Cars

Cheque No.:

12

Authorised Signature

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: Winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

Our Ref:	WG/TP/2018-223	Date 10 July 2018
Invoice No:	TP/TWG/2018-223	
Vehicle No:	SGN8209G	
Attn:	ROSET LIMOUSINE SERVICES PTE LTD	
Company:	TEAMWORK GARAGE PTE LTD	
Address:	53 Ubi Ave 1, #01-24, Paya Ubi Industria Park . Singapore 408934	

Invoice

Surveyor Fee:	S\$330
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$47/- (@ \$1 per photo, total 47 photos)
Total:	S\$477

Surveyor: *Winsen Goh*
Signature: *ka*
Date: *10/7/2018*



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : ROSET LIMOUSINE SERVICES PTE LTD
C/O TEAMWORK GARAGE PTE LTD
53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park
Singapore 408934

Date : 10 July 2018
Our Ref : WG/TP/2018-223

REFERENCE PARTICULARS

Date of Accident : 18 June 2018
Date of Inspection : 21 June 2018

Type of Inspection : Third Party Claim
Date of F.e-Inspn : 21 June 2018

VEHICLE PARTICULARS

Registration No : SGN8209G
Make : TOYOTA
Model : VIOS 1.5E A
Year : 2006

Engine No : 1NZX498232
Chassis No : MR053HY4204210345
Odometer : 203373km
Colour : Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>
Front Near side	: Goodyear	195/45R15
Front Off Side	: Goodyear	195/45R15
Rear Near Side	: Goodyear	195/45R15
Rear off Side	: Goodyear	195/45R15

Thread Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the right side portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$9,500.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Twelve (12) working days.

Enclosed Forty-seven (47) photographs depicting damage to the vehicle.

Inspection conducted at : TEAMWORK GARAGE PTE LTD
53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, Singapore 408934

In accordance to your instruction, we have not authorise repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SGN8209G
MODEL : VIOS 1.5E A

Our Ref : WG/TP/2018-223

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY	ASSESSED	ORIGINAL	REVISED
	PC/SET	CONDITION	QUOTATION	QUOTATION
1 FRONT RH DOOR	1	DENTED	\$ 1,081.50	\$ 1,081.50
2 FRONT RH DOOR STICKER	1	NECESSARY	\$ 121.40	\$ 121.40
3 FRONT RH DOOR PROTECTOR	1	NOT NECESSARY	\$ 182.30	\$ -
4 FRONT RH DOOR TOP MOULDING	1	NOT NECESSARY	\$ 133.40	\$ -
5 REAR RH DOOR	1	DENTED	\$ 1,087.70	\$ 1,087.70
6 REAR RH DOOR FRAME STICKER	1	NECESSARY	\$ 181.10	\$ 181.10
7 REAR RH DOOR HANDLE	1	NOT NECESSARY	\$ 121.35	\$ -
8 REAR RH DOOR HINGE TOP	1	NECESSARY	\$ 80.10	\$ 80.10
9 REAR RH DOOR HINGE BOTTOM	1	NECESSARY	\$ 86.70	\$ 86.70
10 REAR RH DOOR WEATHERSTRIP	1	NECESSARY	\$ 187.30	\$ 187.30
11 REAR RH DOOR GLASS REGULATOR	1	BENT	\$ 287.70	\$ 287.70
12 REAR RH DOOR GLASS REGULATOR MOTOR	1	MALFUNCTION	\$ 381.50	\$ 381.50
13 REAR RH DOOR LOCK	1	JAMMED	\$ 481.40	\$ 481.40
14 REAR RH DOOR INNER TRIM	1	CRACKED	\$ 561.50	\$ 561.50
15 REAR RH DOOR TOP MOULDING	1	NOT NECESSARY	\$ 20.40	\$ -
16 REAR RH FENDER	1	DENTED	\$ 1,811.40	\$ 1,811.40
17 REAR RH FENDER INNER SHIELD	1	NOT NECESSARY	\$ 89.40	\$ -
18 REAR WINDSCREEN MOULDING	1	NECESSARY	\$ 81.50	\$ 181.50
19 REAR BUMPER	1	DEFORMED	\$ 510.30	\$ 510.30
20 REAR BUMPER SIDE RETAINER	2	NECESSARY	\$ 64.10	\$ 64.10
21 REAR BUMPER BRACKET	2	NECESSARY	\$ 93.30	\$ 93.30
22 REAR RH SHOCK ABSORBER	1	BENT	\$ 581.60	\$ 581.60
23 REAR RH WHEEL HUB WITH BEARING	1	JAMMED	\$ 656.30	\$ 656.30
24 REAR AXLE BEAM	1	BENT	\$ 1,904.56	\$ 1,904.56
			\$ 10,577.81	\$ 9,710.96
			Less 25%	\$ 2,427.74
			\$ 7,283.22	\$ 7,283.22
B) S/NETT ITEM				
25 REAR BUMPER CLIP	1 SET	NECESSARY	\$ 60.00	\$ 50.00
26 REAR RH DOOR INNER TRIM CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
27 RIM	1	GRAZED	\$ 600.00	\$ 500.00
28 BRAKE FULID	1 BOT	NECESSARY	\$ 50.00	\$ 40.00
29 JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00
30 WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00
			\$ 1,040.00	\$ 870.00
			Parts Total :	\$ 8,808.36 \$ 8,153.22
C) LABOUR CHARGES & MISC				
31 CHECK WIRING AND LIGHTNING SYSTEM			\$ 50.00	\$ 50.00
32 REMOVE AND REFIT REAR LINING, TRIM AND GARNISH			\$ 230.00	\$ 180.00
33 REMOVE AND REFIT REAR WINDSCREEN			\$ 150.00	\$ 120.00
34 REMOVE AND REFIT REAR REVERSE SENSOR			\$ 150.00	\$ 120.00
35 TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO NEW			\$ 230.00	\$ 180.00
36 TRANSFER PARTS, ATTACHMENT FROM OLD REAR DOOR TO NEW			\$ 230.00	\$ 180.00
37 CHECK REAR WHEEL ALIGNMENT			\$ 150.00	\$ 130.00
38 REMOVE AND RENEW REAR UNDERCARRIAGE PARTS			\$ 230.00	\$ 180.00
39 PANEL BEATING ON AFFECTED AREAS			\$ 1,230.00	\$ 1,000.00
40 SPRAY PAINTING ON AFFECTED AREAS			\$ 1,530.00	\$ 1,400.00
41 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00
			Labour Total :	\$ 4,150.00 \$ 3,670.00
			Total Parts and Laboure :	\$ 12,968.36 \$ 11,823.22

FINAL LUMP SUM ADJUSTMENT

\$ 9,500.00

POINT OF IMPACT

The impact was confined to the right side portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$9,500.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

WG APPRAISAL SERVICE

Winson Goh
Automotive Appraiser



Claim S8M00L87

Reference CS3/ASM18011304/Deb3s2-1

Loss Date June 18, 2018

Report Date Jun 20, 2018 12:59:00 PM

Request Date February 23, 2019

Due Date February 25, 2020

Vendor Name LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Re-inspection

Actions

Next Step Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration # SGN8209G

Make TPVD TOYOTA

Model VIOS 1.5E A

Service Address 51 Ubi Avenue 1, #01-25, 408933

Primary Contact/Insured LIM ENG HOCK
BLK 94 HAVELOCK ROAD, #17-577, 160094, Singapore
hamhamlin71@gmail.com

Claim Handler

CHEN Xinyou

chen.xinyou@axa.com.sg

Additional Instructions

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKPreRepairInspection[1] - Est COR S\$1,500.00 / 05 days repair.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 11, 2019

HOME SERVICE REQUESTS MESSAGES CLAIMS

Claim	S8N00L87
Reference	CS3/ASM18011304/Deb3s2.1
Loss Date	June 18, 2018
Report Date	Jun 20, 2018 12:59:00 PM
Request Date	February 23, 2019
Due Date	February 25, 2020
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Re-Inspection

Vehicle Information	
Incident Vehicle Registration #	SGN8209G
Make	TPVD TOYOTA
Model	VIOS 1.5E A
Service Address	
51 Ubi Avenue 1, #01-25, , 408933	
Primary Contact/Insured	
LIM ENG HOCK BLK 94 HAVELOCK ROAD, #17-577, 160094, Singapore	
hamhamlim71@gmail.com	

Claim Handler	
CHEN Xinyou	
chen.xinyou@axa.com.sg	

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Audit						
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	4/24/19 4:01 PM	5000	5000	Open	Share	Clone
CHEN Xinyou	2/23/19 3:01 AM	8046.03	8046.03	Open	Share	Clone

Vehicle & Driver Details

Vehicle Registration#	SGN8209G	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	11/29/2006
Mileage	232092	Age of Vehicle	
CATEGORY	POLICY INFORMATION	Driver Details	
Manufacturing Year	2006	CATEGORY	FNOL INFORMATION
Make	TPVD TOYOTA	Driver Name	NG YEN HOW WILFRED
Model	VIOS 1.5E A	Date of Birth	June 27, 1980
Type		Age	38
Type of Paint		Occupation	Unknown
Chassis No	MR053HY4204210345	Education Qualification	Other
Engine No	1NZX498232	Driving Experience	0
Engine Capacity	1497cc	Driver License #	
Sum Insured	0	License Type	
		POST SURVEY INFORMATION	

Detailed Assessment

Inspection Date *

02/26/2019



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unarmed Driver Excess

0

Other Excess

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

175/65R14

Rear Tyre Size

175/65R14

Front left side

RADIAL 5mm

Rear left side

GITI 5mm

Front right side

RADIAL 5mm

Rear right side

GITI 5mm

SERVICE REQUESTS MESSAGES CLAIMS

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

	EDIT	S# NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC COUNTY	SALV AGES%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT RH DOOR			Repair	0		25		0	Reviewing	
		2	1			FRONT RH DOOR STICKER			Replaced	121.4		25		91.05	Reviewing	
		3	1			FRONT RH DOOR PROTECTOR			Serviceable	0		25		0	Reviewing	
		4	1			FRONT RH DOOR TOP MOULDING			Serviceable	0		25		0	Reviewing	
		5	1			REAR RH DOOR			Replaced	1087.7		25		815.78	Reviewing	
		6	1			REAR RH DOOR FRAME STICKER			Replaced	181.1		25		135.83	Reviewing	
		7	1			REAR RH DOOR HANDLE			Serviceable	0		25		0	Reviewing	
		8	1			REAR RH DOOR HINGE TOP			Serviceable	0		25		0	Reviewing	
		9	1			REAR RH DOOR HINGE BOTTOM			Serviceable	0		25		0	Reviewing	
		10	1			REAR RH DOOR WEATHERSTRIP			Replaced	187.3		25		140.48	Reviewing	

REAR AXLE BEAM

Service Requests Messages Claims

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RGR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		CHECK WIRING AND LIGHTING SYSTEM.	30	0	0	Reviewing		
	2		REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.	80	0	0	Reviewing		
	3		REMOVE AND REFIT REAR WINDSCREEN.	120	0	0	Reviewing		
	4		REMOVE AND REFIT REAR REVERSE SENSOR.	0	0	0	Reviewing		
	5		TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO NEW.	60	0	0	Reviewing		
	6		TRANSFER PARTS, ATTACHMENT FROM OLD REAR DOOR TO NEW.	60	0	0	Reviewing		
	7		CHECK REAR WHEEL ALIGNMENT.	60	0	0	Reviewing		
	8		TO REMOVE AND RENEW REAR UNDERCARRIAGE PARTS.	150	0	0	Reviewing		
	9		PANEL BEATING ON AFFECTED AREAS.	800	0	0	Reviewing		
	10		SPRAY PAINTING ON AFFECTED AREAS.	800	0	0	Reviewing		
	11		APPLY ANTI RUST ON AFFECTED AREAS.	40	0	0	Reviewing		

English (default) * LKK AUTO CONSULTANTS PTE LTD (TP) *

🏠 SERVICE REQUESTS MESSAGES CLAIMS

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR	Reviewing		6	
		2	SET REAR BUMPER CLIP	Reviewing	30	REPLACED	
		3	SET REAR RH DOOR INNER TRIM CLIP	Reviewing	20	REPLACED	
		4	RIM	Reviewing	350	REPLACED	
		5	BOT BRAKE FULID	Reviewing	0	NOT NECESSARY	
		6	WINDSCREEN SEALANT	Reviewing	40	REPLACED	
		7	JOINT SEALANT	Reviewing	40	REPLACED	

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount		\$8,046.03		Claim Amount		\$8,046.03	
CATEGORY			ESTIMATE	REVISED AMOUNT			
Spare Parts			\$5,366.03	\$5,366.03			
Labour			\$2,200.00	\$2,200.00			
Miscellaneous			\$480.00	\$480.00			

Submit for Review

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

	1	FINAL LUMP SUM	Reviewing	5000		
---	---	----------------	-----------	------	--	---