

🏠 SERVICE REQUESTS MESSAGES CLAIMS

PART NAME		PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DIAGN / BTRK	DISC COUNT	SALV AGES	PART PRICE(NET)	ACTION (PARTS)	REMOVE
REAR RH DOOR GLASS REGULATOR				Serviceable	0		25		0	Reviewing	🗑
🗑	🔧	12	1	Serviceable	0		25		0	Reviewing	🗑
REAR RH DOOR GLASS REGULATOR MOTOR				Serviceable	0		25		0	Reviewing	🗑
🗑	🔧	13	1	Serviceable	0		25		0	Reviewing	🗑
REAR RH DOOR INNER TRIM				Replaced	561.5		25		421.13	Reviewing	🗑
🗑	🔧	14	1	Replaced	561.5		25		421.13	Reviewing	🗑
REAR RH DOOR TOP MOULDING				Serviceable	0		25		0	Reviewing	🗑
🗑	🔧	15	1	Serviceable	0		25		0	Reviewing	🗑
REAR RH FENDER				Replaced	1181.4		25		886.05	Reviewing	🗑
🗑	🔧	16	1	Replaced	1181.4		25		886.05	Reviewing	🗑
REAR RH FENDER INNER SHIELD				Serviceable	0		25		0	Reviewing	🗑
🗑	🔧	17	1	Serviceable	0		25		0	Reviewing	🗑
REAR WINDSCREEN MOULDING				Replaced	181.5		25		136.13	Reviewing	🗑
🗑	🔧	18	1	Replaced	181.5		25		136.13	Reviewing	🗑
REAR BUMPER				Replaced	510.3		25		382.73	Reviewing	🗑
🗑	🔧	19	1	Replaced	510.3		25		382.73	Reviewing	🗑
REAR BUMPER SIDE RETAINER				Serviceable	0		25		0	Reviewing	🗑
🗑	🔧	20	2	Serviceable	0		25		0	Reviewing	🗑
REAR BUMPER BRACKET				Serviceable	0		25		0	Reviewing	🗑
🗑	🔧	21	2	Serviceable	0		25		0	Reviewing	🗑
REAR RH SHOCK ABSORBER				Replaced	581.6		25		436.2	Reviewing	🗑
🗑	🔧	22	1	Replaced	581.6		25		436.2	Reviewing	🗑
REAR RH WHEEL HUB WITH BEARING				Replaced	656.3		25		492.23	Reviewing	🗑
🗑	🔧	23	1	Replaced	656.3		25		492.23	Reviewing	🗑



SERVICE REQUESTS

MESSAGES

CLAIMS

ASSESSMENT INFORMATION

0

Claim Portal

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

License Issue
Date

mm/dd/yyyy

License
Expiration
Date

mm/dd/yyyy

Address

BLK 205, TAMPINES STREET 21,
#06-1277, 520205, Singapore

Address type

Personal Correspondence

Gender

Male

Marital
status

Unknown

Identification
#

S9020859F

- SERVICE REQUESTS
- MESSAGES
- CLAIMS

	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Resurvey Photo 1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 3, 2019
 LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 3, 2019
 LOD TP LITIGATION - ROSE LIMOUSINE SERVICES PTE LTD.pdf	Legal	Letter of Demand/Notice of Proceedings	DESHPANDE Prasad	December 11, 2018
 P2041273_CL_00002_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	HO Winnie	June 20, 2018
 P2041273_EN_00002_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	HO Winnie	June 20, 2018
 SGN8209G TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 20, 2018
 SFV7711Z INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 20, 2018