



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Ng Su Feng Sharon
Apt Blk 289D Punggol Place
#04-845
Singapore 824289

*Not Withheld
61 Day 87
Recovery After Paint
5 days*

Dear sir
Estimate cost of repair to vehicle no.SLU 5550T
To supply

1. Rear bumper
2. Rear bumper retainer x2
3. Rear bumper sensor
4. Rear bumper bracket x2
5. Tail gate logo
6. Tail gate badge x2
7. Rear tail gate rubber
8. Rear exhaust box
9. Rear panel
10. Rear panel top garish
11. Rear bumper chips 10

<i>Retain</i>	759.60	✓
<i>Sn</i>	163.80	X
<i>Shot</i>	350.00	<i>2000</i>
	60.00	7
<i>na</i>	45.00	—
<i>na</i>	90.00	—
<i>Sn</i>	361.90	X
<i>n</i>	650.00	X
<i>Pr</i>	580.00	✓
<i>ng 11</i>	180.00	✓
<i>na</i>	15.00	✓

258

Labour charges	
Rust proofing	100.00 <i>300</i>
Panel beating	680.00 <i>600</i>
Spray painting	650.00 <i>600</i>
Total	

Your faithfully

ALBERT POON