

Kj

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112
 Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011
 Co. Reg. No. 201212455W

Date: 22.02.2019 Third Party Insurer: AIG
 Vehicle No: SLK5441C Third Party Veh No: SJH8421E
 Model: TOYOTA AQUA 1.5S A Date of Accident: 21.02.2019
 Chassis: NHP102583993 - 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		<i>Ky</i> \$1,005.90
2	FRONT DOOR BLACK FRAME STICKER RH	1		<i>M</i> \$48.90
3	REAR QUARTER PANEL STONE STICKER RH	1		<i>M</i> \$75.00
4	FRONT FENDER RH	1		REPAIR
5	REAR DOOR RH	1		REPAIR
6	REAR QUARTER PANEL RH	1		REPAIR
SUB TOTAL				\$1,129.80
LESS 25%				-\$282.45
PARTS TOTAL				\$847.35

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING & REPLACE ACCIDENT PORTION & ETC. \$800.00 *4001*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS \$800.00 *4401*

TO REMOVE & REFIT FRONT DOOR INNER TRIM, FRONT DOOR PANEL LOCK, FRONT DOOR GLASS, FRONT DOOR POWER WINDOW GEAR & ETC. TO EFFECT REPLACE ON FRONT DOOR \$150.00 *601*

TO CHECK WIRING, DOOR CENTRAL LOCKING SYSTEM BACK TO PROPER CONDITIONS \$150.00 *601*

LABOUR TOTAL \$1,900.00

ONG TOTAL \$2,747.35

LKK Auto Consultants needs notify the Repairer of the following:

- To resurvey before/after spray painting
- To display the resurvey card during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No legal proceedings allowed
- Supplies must be inspected and is subject to the respective insurance Company

Acknowledged: _____
 Signature: _____
 Date: _____

Not Notified
1.B.1
Resurvey B4 paint

4 days

81747.35