

ASS. REC. BY:

REF: CS/CTI19003418/And302

Special Instruction:

Surveyor: Adrian
Meinmen

ASSIGNMENT (Office)

From (Person):

Wene Tay

of

CTI

Date/Time:

22/2/19 @ 3:19pm

Estimated Cost:

Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCR 6656M

Insured:

at Workshop m/s

Autobolt

Tel:

90687204

of

& Kaki Bkt Ave 4 #08-18 premier

Policy No:

DMPCSA1219661806

Claim No:

SNM19D20089101

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

(Client's Record)

D.O.A.

18/02/2019CA / REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:31am @ 22/2/19

Person Contacted:

AlvinVehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate Insp: 03-55

SCR 6656M - NA/CTI19003034/24D.O.A: 18/2/1921/2/19 @ 4:59pm report to Wene Tay via Meinmen.22/2/19 @ 12:04pm Alfred informed CA & Ex: \$1000 via Meinmen.22/2/19 @ 2:10pm Informed Kai Ling CA & Ex: \$1000 by email. (US basis)
US \$13900, 2 days (led to 22738.40, 67%)

ASS. REC. BY:

REF:

Adrian.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SCR 6656M. Yr Regn: 2007 1 Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar X-Type c.c. 2099Colour: Gold A/C: Insured / Std / Nil / NASp. Reading: 225647 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 8AJA 6SIN57YJ 22440Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 25/02/19Survey held at Auto BoltDes. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08 China

RECEIVED 25 MAR 2019

MV: 67K Based on 9K depreciation.PV: 43.2KNett: 23.8K.

Date/Time, File Pass to?

Date/Time, File Return to?

1) 26/3 12:15

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2019		22 Feb 2019 15:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LEE SIAM KIANG		
Vehicle Reg. No.:	SCR6656M	Date of Loss:	18/02/2019 13:00 - :59
Claim Type:	OD / SNM19D200891C01	Policy/Cover Note No.:	DMPCSN1219661806 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Autobolt Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #08-18 Premier@Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/03/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Friday, 22 February 2019 3:21 PM
To: autoboltsvc@singnet.com.sg
Cc: Admin A; assignments
Subject: CTP REF NO. SNM19D200891C01 - SCR6656M - To arrange for a surveyor
Attachments: img-190220134926.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with Autobolt .

Thank you.

Regards,

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Autobolt Svc [mailto:autoboltsvc@singnet.com.sg]
Sent: Friday, 22 February, 2019 11:22 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>

Cc: 'Autobolt Pte Ltd ' <alvinong@singnet.com.sg>

Subject: SCR6656M - To arrange for a surveyor

Dear Irene,

As conversed, please kindly assist to arrange an inspection for the following. Attached file is our quotation.

Type of coverage: Comprehensive

Vehicle no: SCR6656M

Our workshop address: 8 Kaki Bukit Ave 4 #03-55 Singapore 415875

Appreciate.

Thanks & Regards

Kailing

Auto Bolt Services Pte Ltd

8 Kaki Bukit Avenue 4 #03-55 Singapore 415875

Tel: 90687204

Email: autoboltsvc@singnet.com.sg

Like us on our Facebook page @ Auto Bolt Services Pte Ltd

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 27 February 2019 2:45 PM
To: Autobolt Svc
Cc: SUR; 'Autobolt Pte Ltd '
Subject: RE: CHINA-OD VEHICLE SCR 6656M (DOA: 18/02/2019)

Dear Kai Ling,

Please note that repair the vehicle SCR 6656M at repair cost on Lump Sum basis.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Autobolt Svc <autoboltsvc@singnet.com.sg>
Sent: Wednesday, 27 February 2019 2:12 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Autobolt Pte Ltd ' <alvinong@singnet.com.sg>
Subject: RE: CHINA-OD VEHICLE SCR 6656M (DOA: 18/02/2019)

Hi Shiau Chan,

Noted with thanks.

Thanks & Regards

Auto Bolt Services Pte Ltd

8 Kaki Bukit Avenue 4 #03-55 Singapore 415875

Tel: 90687204 or Tel: 98511300

Email: autoboltsvc@singnet.com.sg

Like us on our Facebook page @ Auto Bolt Services Pte Ltd

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 27 February, 2019 2:10 PM
To: autoboltsvc@singnet.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: CHINA-OD VEHICLE SCR 6656M (DOA: 18/02/2019)

Dear Kai Ling,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SCR 6656M (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

Shiau Chan (LKKAuto)

From: Autobolt Svc <autoboltsvc@singnet.com.sg>
Sent: Wednesday, 27 February 2019 2:12 PM
To: Shiau Chan (LKKAuto)
Cc: SUR; 'Autobolt Pte Ltd '
Subject: RE: CHINA-OD VEHICLE SCR 6656M (DOA: 18/02/2019)

Hi Shiau Chan,

Noted with thanks.

Thanks & Regards
Auto Bolt Services Pte Ltd
8 Kaki Bukit Avenue 4 #03-55 Singapore 415875
Tel: 90687204 or Tel: 98511300
Email: autoboltsvc@singnet.com.sg
Like us on our Facebook page @ Auto Bolt Services Pte Ltd

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 27 February, 2019 2:10 PM
To: autoboltsvc@singnet.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: CHINA-OD VEHICLE SCR 6656M (DOA: 18/02/2019)

Dear Kai Ling,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SCR 6656M (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Virus-free. www.avg.com

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Feb 2019 15:47	Clm Veh Model Changed	(200363) JAGUAR X-TYPE 2.0 (A).	[I] Irene Tay Hui Ping
2	22 Feb 2019 15:47	Clm Created	Reg No: SCR6656M, Policy No: DMPCSN1219661806, Acct Date: 2019/02/18, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Autobolt Pte Ltd (HQ), Ins.Status => Incoming Claim	[I] Irene Tay Hui Ping
3	22 Feb 2019 15:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT	[I] Irene Tay Hui Ping
4	22 Feb 2019 15:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/05	[I] Irene Tay Hui Ping
5	22 Feb 2019 15:49	Adj Mandate Set	Approved:0.00.	[I] Irene Tay Hui Ping
6	22 Feb 2019 16:04	Assignment 1st Accessed		[A] Nivitha Govindasamy
7	25 Feb 2019 14:39	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
8	25 Feb 2019 16:54	Adj Rpt Initiated		[A] SHIAU CHAN
9	25 Feb 2019 16:54	Clm Dtl Modified	Driver Name: -> LEE SIAM KIANG. Circumstances of Loss: -> 7.	[A] SHIAU CHAN
10	25 Feb 2019 16:54	Clm Dtl Modified	Claimant's ID: -> S1382372C.	[A] SHIAU CHAN
11	25 Feb 2019 16:54	Clm Dtl Modified	JPJ Reg. Date: -> 2007/09/19.	[A] SHIAU CHAN
12	25 Feb 2019 16:54	Clm Details Notified		[A] SHIAU CHAN
13	25 Feb 2019 16:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/05	[A] SHIAU CHAN
14	25 Feb 2019 16:59	Adj Mandate Request	Cur.Req:18975.79:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	27 Feb 2019 12:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/05, Mandate Remarks: Please proceed to authorize repairs at \$15,150.00 BEFORE Excess of \$1,000.00	[I] Alfred Toh
16	27 Feb 2019 12:04	Adj Mandate Set	Approved:15150.00:Please proceed to authorize repairs at \$15,150.00 BEFORE Excess of \$1,000.00Reinsp:Adj decides.	[I] Alfred Toh

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2067586	25/02/2019 16:54	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCR6656M		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 25 Feb 2019

Preliminary Advice

Vehicle No	: SCR6656M	Accident Date	: 18/02/2019
Make	: JAGUAR X-TYPE	Policy No.	: DMPCSN1219661806
Assignment Date	: 22/02/2019	Excess	: S\$1,000.00
Date of Inspection	: 25/02/2019	Est. Duration of Repair	: 9.00
Inspection At	: AUTOBOLT PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #08-18 PREMIER@KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,638.40
Revised Amount	:S\$	12,202.67
Check Items (Estimated)	:S\$	6,773.12
Total	:S\$	18,975.79
Lump Sum Repair	:S\$	15,150.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	43,188.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,812.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2372C
Vehicle Details	
Vehicle No.:	SCR6656M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	JAGUAR
Vehicle Model:	X-TYPE 2.0SE
Primary Colour:	Gold
Manufacturing Year:	2007
Engine No.:	557629427YC
Chassis No.:	SAJAG51N57YJ22440
Maximum Power Output:	114.6 kW (153 bhp)
Open Market Value:	\$35,625.00
Original Registration Date:	19 Sep 2007
First Registration Date:	19 Sep 2007
Transfer Count:	0
Actual ARF Paid:	\$39,188.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,355.00
COE Rebate Amount:	\$43,188.00
Total Rebate Amount:	\$43,188.00

The information contained herein is correct as at 20 Feb 2019

OK



Cheap Car Insurance Renewal

Is your car insurance expiring soon?
Receive best quotations from multiple insurers in as little as 2 hours.

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad |
 Advertiser Login |
 Ways of Selling

Mercedes-Benz W205.

Nicely Done Up.
Direct Owner StarAd

AutoInn
An Inspiration For Car Buyers

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category Save Search Print Sort by Date Posted 20 results/page

4 vehicles | Search Advanced Search Search View All

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Jaguar	Any	Any	> 10 year(s) old	Any	Any	Any	Any	Any	Available

Jaguar XJ6 3.2A LWB (COE till 03/2026) **\$84,800** **\$11,950 /yr** **30-May-1996** **3,239 cc** **-** **Luxury** **Available**

Unleashed The Jaguar! A Reliable Unit Made For Grace, Space And Pace, A Classic Model That Will Never Age. This Is One Car That Can Never Get Old As It Was Designed To Be A Classic. The Most Reliable ...

Posted: 20-Jan-2019 Tags: 1996 jaguar XJ6, 1996 jaguar XJ6, jaguar XJ6, jaguar XJ6, Jaguar XJ6, XJ6, Used Jaguar

Jaguar S-Type 3.0SE (New 10-yr COE) **\$63,800** **\$6,370 /yr** **26-Oct-1999** **2,967 cc** **88,995 km** **Luxury** **Available**

The Best Classic Look Jaguar. Genuine Low Mileage Done Only 88995 KM. Smooth And Silent V6 Engine. Car Is In Excellent Original Condition. See To Believe. No Repair Needed At All. Many New Parts Repla...

Posted: 23-Feb-2019 Tags: 1999 jaguar S-Type, 1999 jaguar s-type, jaguar S-Type, jaguar s-type, Jaguar, S-Type, s-type, Used Jaguar

Jaguar XJ6 3.0 Executive LWB (COE till 11/2027) **\$110,000** **\$12,550 /yr** **14-Dec-2007** **2,967 cc** **76,000 km** **Luxury** **Available**

1 Owner, Used For Occasions Only, Careful Driver, Serviced By Agent, Well Maintained. Don't Miss Out This Beautiful Unit, Collector's Car. Last Model Of XJ6 In Town. Don't Miss Out On The Last British...

Monster Motors Pte Ltd
Posted: 19-Jan-2019 Tags: 2007 jaguar XJ6, 2007 jaguar XJ6, jaguar XJ6, jaguar XJ6, Jaguar XJ6, XJ6, Used Jaguar

Jaguar XJ6 3.0A Executive (COE till 11/2028) **\$108,000** **\$11,140 /yr** **03-Nov-2008** **2,967 cc** **39,000 km** **Luxury** **Available**

All Service Done Only In Wearnes. Few Sensors And Parts Replaced. Just Done The 40,000Km Servicing. COE Till Nov 2028. Elegant, Quiet, Smooth And Powerful V6 Engine. The Las T Of XJ6 From British's Pr...

Posted: 26-Jan-2019 Tags: 2008 jaguar XJ6, 2008 jaguar XJ6, jaguar XJ6, jaguar XJ6, Jaguar XJ6, XJ6, Used Jaguar

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads 20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Jaguar, Jaguar Singapore, used Jaguar, used vehicles Singapore or even buy used Jaguar Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#) Download on the **App Store** **GET IT ON Google play**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/02/2019 14:11
Date Of Accident	18/02/2019 13:20
Exact Location Of Accident	KAKI BUKIT AVENUE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCR6656M
Insured/Policyholder	
Name Of Registered Owner	LEE SIAM KIANG
NRIC No	S1382372C
Email Address	CINDY@B-GOLDONLINE.COM
Mobile Phone No	(LOCAL) +65-96386656
Alternative Phone No	OTHERS-96386656

Vehicle Particulars

Manufacturer	JAGUAR
Model	X-TYPE 2.0SE
Exact Purpose for which vehicle was being used at time of accident	PTE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LEE SIAM KIANG
NRIC No	S1382372C
Date Of Birth	20/06/1959
Occupation	INDOOR
Date Of Driving Pass	04/03/1981
Driving Experience	37 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96386656
Fax Number	
Contact Number	OTHERS-96386656
EMail Address	CINDY@B-GOLDONLINE.COM

Address	BLK 578 HOUGANG AVENUE 4 #06-656
Postcode	530578
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DRIVER'S WIFE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER SKETCH DRAWING ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGM44Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

94887451 Han.

AUTO BOLT SERVICES PTE LTD

Jaguar & Land Rover Specialists

Company Reg no: 201436686E
Email: autoboltsvc@Singnet.com.sg

VEHICLE NUMBER : SCR 6656 M

MAKE & MODEL : JAGUAR X TYPE

ITEM	DESCRIPTION	Qty	
1	LHR DOOR PANEL <i>Repair</i>	1	\$ 3,524.50 +
2	LHF DOOR PANEL <i>Disbled</i>	1	\$ 3,524.50 ✓
3	FRONT BONNET PANEL <i>Repair</i>	1	\$ 2,046.70 +.
4	LHF FENDER PANEL <i>Disbled</i>	1	\$ 1,020.30 ✓
5	LHF DOOR SEAL PRIMARY <i>3 new</i>	1	\$ 195.95 ✓
6	LHF DOOR SEAL UPPER	1	\$ 126.00 ✓
7	LHR DOOR SEAL PRIMARY <i>3 new</i>	1	\$ 195.95 +
8	LHR DOOR SEAL UPPER	1	\$ 102.00 +
9	LHR DOOR LATCH HINGE <i>3 new</i>	2	\$ 155.30 +
10	LHF DOOR LATCH HINGE <i>Best</i>	2	\$ 155.30 ✓
11	LHR DOOR CHECK ARM <i>new</i>	1	\$ 621.15 +
12	LHF DOOR CHECK ARM <i>Repd</i>	1	\$ 621.15 ✓
13	LHF DOOR LATCH <i>3 new</i>	1	\$ 712.50 +
14	LHR DOOR LATCH	1	\$ 712.50 +
15	LHF WINDOW REGULATOR AND MOTOR <i>3 new</i>	1	\$ 965.60 +
16	LHR WINDOW REGULATOR AND MOTOR	1	\$ 965.60 +
17	LHF WHEEL ARCH <i>torn</i>	1	\$ 400.00 ✓
22	FRONT BUMPER <i>Disbled</i>	1	\$ 1,546.20 ✓
23	FRONT BUMPER VALANCE PANEL ?	1	\$ 481.30 ?
24	LHF BUMPER MOULDING CHROME <i>crackd</i>	1	\$ 297.00 ✓
25	LHF BUMPER BRACKET <i>new</i>	1	\$ 38.00 ✓
26	FRONT BUMPER SPLITTER VANE ?	1	\$ 225.00 ?
27	LH SIDE DOOR MIRROR <i>Missing</i>	1	\$ 739.50 ✓
28	LH SIDE DOOR MOTOR <i>Repd</i>	1	\$ 173.70 ✓
29	LH SIDE DOOR GLASS <i>New</i>	1	\$ 168.35 +
30	LH SIDE DOOR MIRROR COVER <i>Missing</i>	1	\$ 302.40 ✓
31	LHF RIM 17 INCH <i>6x</i>	1	\$ 1,078.30 ✓
32	LHF TYRE TYRE 225/45R17 GOOD YEAR <i>Replaced</i>	1	\$ 350.00 25)
33	LHF SHOCK ABSORBER ?	1	\$ 373.80 ?
34	LHF SHOCK ABSORBER BEARING ?	1	\$ 137.60 ?
35	LHF SHOCK ABSORBER MOUNTING ?	1	\$ 221.25 ?

36	LHF FENDER INDICATOR SIDE LAMP <i>cracked</i>	1	\$ 80.00	-
37	POWER STEERING RACK ASSY <i>new</i>	1	\$ 4,653.50	+
38	LHF LOWER ARM ?	1	\$ 700.00	?
39	LHF VERTICAL LINK ?	1	\$ 885.00	?
40	LHF ANTI ROLL BAR LINK <i>new</i>	1	\$ 300.00	+
41	FRONT ANTI ROLL BAR <i>new</i>	1	\$ 786.30	+
42	LHF HEADLAMP ASSY	1	\$ 3,168.40	
43	LHF REHOUSING <i>Repis</i>	1	\$ 1,260.00	X
44	LHF BUMPER REFEXTOR <i>new</i>	1	\$ 88.00	+
45	LHF A POST PANEL <i>Repis</i>	1	\$ 1,010.00	+
46	LH SIDE SKIRT <i>Repis</i>	1	\$ 376.40	+
47	LHF DOOR OUTER MOULDING <i>Deland</i>	1	\$ 188.00	-
			Parts Sub Total	
			\$ 35,673.00	
			Discount 10%	
			\$ 7,134.60	
			Parts Total	
			\$ 28,538.40	
			Special Nett	
1	DOOR CLIP AND SIDE SKIRT CLIP <i>new</i>	20	\$ 200.00	60
			Special Nett Total:	
			\$ 200.00	
			Labour	
1	To R & R accident damage parts, to cut/weld, knock and realign accident affected area	1	\$ 2,500.00	1000
2	To putty and respray accident affected area.	1	\$ 2,800.00	1200
3	To rust proof accident affected area.	1	\$ 250.00	50
4	To R & R under carriage system	1	\$ 1,200.00	?
5	To check wheel alignment	1	\$ 150.00	80
6	To check wiring layout and headlamp focus	1	\$ 500.00	50
7	To do diagnostic ,reprogram and scan fault codes	1	\$ 500.00	100
			Labour Total	
			\$ 7,900.00	
			Parts Total	
			\$ 28,538.40	
			Special Nett Total:	
			\$ 200.00	
			Labour Total	
			\$ 7,900.00	
			Grand Total	
			\$ 36,638.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
1/s 25/02/19.
09 Pags.
Excess \$1000
Not Authorised
96893735.

AUTO BOLT SERVICES PTE LTD

Jaguar & Land Rover Specialists

Company Reg no: 201436686E
Email: autoboltsvc@Singnet.com.sg

VEHICLE NUMBER : SCR 6656 M

MAKE & MODEL : JAGUAR X TYPE

ITEM	DESCRIPTION	Qty		
1	LHR DOOR PANEL Repair	1	\$	3,524.50 x
2	LHF DOOR PANEL Dislnd	1	\$	3,524.50 ✓
3	FRONT BONNET PANEL Repair	1	\$	2,046.70 x.
4	LHF FENDER PANEL Dislnd	1	\$	1,020.30 ✓
5	LHF DOOR SEAL PRIMARY <i>Free</i>	1	\$	195.95 ✓
6	LHF DOOR SEAL UPPER	1	\$	126.00 ✓
7	LHR DOOR SEAL PRIMARY <i>Free</i>	1	\$	195.95 +
8	LHR DOOR SEAL UPPER	1	\$	102.00 +
9	LHR DOOR LATCH HINGE <i>Free New</i>	2	\$	155.30 +
10	LHF DOOR LATCH HINGE <i>Best</i>	2	\$	155.30 ✓
11	LHR DOOR CHECK ARM <i>new</i>	1	\$	621.15 ✓
12	LHF DOOR CHECK ARM <i>205</i>	1	\$	621.15 ✓
13	LHF DOOR LATCH <i>Free Paid</i>	1	\$	712.50 ✓
14	LHR DOOR LATCH <i>New</i>	1	\$	712.50 x
15	LHF WINDOW REGULATOR AND MOTOR <i>Free</i>	1	\$	965.60 +
16	LHR WINDOW REGULATOR AND MOTOR	1	\$	965.60 +
17	LHF WHEEL ARCH <i>torn</i>	1	\$	400.00 ✓
22	FRONT BUMPER Dislnd	1	\$	1,546.20 ✓
23	FRONT BUMPER VALANCE PANEL Repair ?	1	\$	481.30 x.
24	LHF BUMPER MOULDING CHROME <i>could</i>	1	\$	297.00 ✓
25	LHF BUMPER BRACKET <i>new</i>	1	\$	38.00 ✓
26	FRONT BUMPER SPLITTER VANE <i>paid</i>	1	\$	225.00 ✓
27	LH SIDE DOOR MIRROR <i>Missing Paid</i>	1	\$	739.50 ✓
28	LH SIDE DOOR MOTOR <i>paid</i>	1	\$	173.70 ✓
29	LH SIDE DOOR GLASS <i>Missing</i> ?	1	\$	168.35 ✓
30	LH SIDE DOOR MIRROR COVER <i>Missing</i>	1	\$	302.40 ✓
31	LHF RIM 17 INCH <i>lot</i>	1	\$	1,078.30 ✓
32	LHF TYRE TYRE 225/45R17 GOOD YEAR <i>Paid</i>	1	\$	350.00 25)
33	LHF SHOCK ABSORBER <i>Best</i>	1	\$	373.80 ✓
34	LHF SHOCK ABSORBER BEARING <i>New</i>	1	\$	137.60 ✓
35	LHF SHOCK ABSORBER MOUNTING <i>New</i>	1	\$	221.25 ✓

36	LHF FENDER INDICATOR SIDE LAMP	<i>cancel</i>	1	\$	80.00	-
37	POWER STEERING RACK ASSY	<i>new</i>	1	\$	4,653.50	+
38	LHF LOWER ARM	<i>Best</i>	1	\$	700.00	✓
39	LHF VERTICAL LINK	<i>Best</i>	1	\$	885.00	✓
40	LHF ANTI ROLL BAR LINK	<i>new</i>	1	\$	300.00	+
41	FRONT ANTI ROLL BAR	<i>new</i>	1	\$	786.30	+
42	LHF HEADLAMP ASSY	<i>cancel</i>	1	\$	3,168.40	✓
43	LHF REHOUSING	<i>Repair</i>	1	\$	1,260.00	X
44	LHF BUMPER REFEXTOR	<i>new</i>	1	\$	88.00	+
45	LHF A POST PANEL	<i>Repair</i>	1	\$	1,010.00	+
46	LH SIDE SKIRT	<i>Repair</i>	1	\$	376.40	+
47	LHF DOOR OUTER MOULDING	<i>cancel</i>	1	\$	188.00	-
				Parts Sub Total	\$ 35,673.00	
				Discount 10%	\$ 7,134.60	
				Parts Total	\$ 28,538.40	

Special Nett						
1	DOOR CLIP AND SIDE SKIRT CLIP	<i>new</i>	20	\$	200.00	60
				Special Nett Total:	\$ 200.00	

Labour						
1	To R & R accident damage parts, to cut/weld, knock and realign accident affected area		1	\$	2,500.00	100
2	To putty and respray accident affected area.		1	\$	2,800.00	120
3	To rust proof accident affected area.		1	\$	250.00	50
4	To R & R under carriage system		1	\$	1,200.00	280
5	To check wheel alignment		1	\$	150.00	80
6	To check wiring layout and headlamp focus		1	\$	500.00	50
7	To do diagnostic, reprogram and scan fault codes		1	\$	500.00	100
				Labour Total	\$ 7,900.00	

				Parts Total	\$ 28,538.40	
				Special Nett Total:	\$ 200.00	
				Labour Total	\$ 7,900.00	
				Grand Total	\$ 36,638.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Paris prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2760.
total: 17386.32
h/s: 13.9K

Adrian Lj
h/s 25/02/19.
09 Pays.
Excess \$1000
Not Authorised
96893735.

August

225642

Customer:		Date:	25/2/2019 2:38 PM
Company:		VIN	
License No:	SCR6656M	Technician:	HANN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

JAGUAR/DAIMLER, X-TYPE, 2001-2010, All Models

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	1°30'	3°00'	---
		Right	---	1°30'	3°00'	---
	Camber	Left	-0°58'	-1°17'	0°13'	-0°58'
		Right	-1°01'	-1°17'	0°13'	-1°01'
	Toe	Left	0°46'	-0°09'	0°03'	0°45'
		Right	0°04'	-0°09'	0°03'	0°05'
Total		0°50'	-0°18'	0°06'	0°50'	
Rear	Camber	Left	-1°12'	-1°27'	0°03'	-1°12'
		Right	-1°17'	-1°27'	0°03'	-1°16'
	Toe	Left	-0°01'	-0°01'	0°16'	-0°01'
		Right	0°14'	-0°01'	0°16'	0°14'
		Total	0°13'	0°03'	0°27'	0°13'
	Thrust Angle		0°08'	-0°08'	0°08'	0°08'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		---	---	---	---
	Right		---	---	---	---
Included Angle	Left		---	---	---	---
	Right		---	---	---	---
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Maximum Turns	Left		---	---	---	---
	Right		---	---	---	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		0.09"	---	---	0.09"
	Rear		-0.47"	---	---	-0.47"
Track Width Diff.			-1.54"			-1.54"
Wheel Base Diff.			0.56"			0.56"
Front Ride Height	Left		0.00"	14.02"	15.20"	0.00"
	Right		0.00"	14.02"	15.20"	0.00"
Rear Ride Height	Left		0.00"	13.98"	15.16"	0.00"
	Right		0.00"	13.98"	15.16"	0.00"
Frame Angle						---

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2019		22 Feb 2019 15:49 Edit Adj Rpt	S\$13,900.00 Edit Estimates	S\$13,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LEE SIAM KIANG , ID: S1382372C								
Vehicle Reg. No.:	SCR6656M	Date of Loss:	18/02/2019 13:00 - :59 [136 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D200891C01	Policy/Cover Note No.:	DMPCSN1219661806 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Autobolt Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #08-18 Premier@Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/03/2019]								
Driver/Custodian:	LEE SIAM KIANG (/ Male) , NRIC: S1382372C Email:								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
• CHINA_TAIPING (27/02/2019): Alert - Adj Mandate Approved (S\$15150.00) - SCR6656M - Claim Handler: Irene Tay ...									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCR6656M (SNM19D200891C01)
OD
Feb 18 2019 1:00PM
[LEE SIAM KIANG]
Autobolt Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	25/02/19 16:58	Adjuster Immediate Advice		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
2	25/02/19 16:49	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
3	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
4	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
5	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
6	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
7	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
8	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
9	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
10	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
11	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
12	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
13	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
14	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
15	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
16	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
17	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
18	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
19	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
20	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
21	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
22	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
23	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
24	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
25	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
26	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
27	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
28	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
29	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
30	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
31	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
32	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
33	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
34	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					
35	25/02/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
36	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
37	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
38	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
39	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
40	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
41	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
42	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
43	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
44	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
45	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
46	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
47	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
48	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
49	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
50	25/02/19 16:49	General View		Load JPG <input checked="" type="checkbox"/>
51	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
75	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
76	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
77	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
78	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
79	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
80	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
81	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
82	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
83	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
84	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
85	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
86	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
87	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
88	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
89	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
90	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
91	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
92	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
93	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
94	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
95	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
96	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
97	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
98	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
99	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
100	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
101	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
102	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
103	26/03/19 09:17	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/02/19 16:49	ESTIMATE		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19003448/AQD3E2

Date: 02/04/2019

REFERENCE

Insured/Claimant: LEE SIAM KIANG Policy No: DMPCSN1219661806
Date of Loss: 18/02/2019 Nature of Claim: OD Claim No: SNM19D200891C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCR6656M**
Make & Model: JAGUAR X-TYPE, 2.0 (A) Engine No: 557629427YC
Reg. Date: 19/09/2007 (Man. Year: 2007) Chassis No: SAJAG51N57YJ22440
Colour: Gold Odometer: 225647 km
Engine Capacity: 2099 cc
Market Value/New Car Price: S\$67,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,305.70	14,626.32	17,679.38	54.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,900.00	2,760.00	5,140.00	65.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,205.70	17,386.32	22,819.38	56.76
Approved Total (Overridden) (S\$)		13,900.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (S\$)	39,205.70	12,900.00	26,305.70	67.10

INSPECTION

Date of Assignment: 22/02/2019
Date Inspected: 25/02/2019 Inspected At: Repairer : 8 KAKI BKT AVE 4#03-55
Autobolt Pte Ltd (HQ)
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts: 143	JAGUAR X-TYPE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCR6656M)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHR DOOR PANEL	Repair	3,524.50 FL	*- FL
2	1		*LHF DOOR PANEL	Distorted	3,524.50 FL	*3,524.50 FL
3	1		*FRONT BONNET PANEL	Repair	2,046.70 FL	*- FL
4	1		*LHF FENDER PANEL	Distorted	1,020.30 FL	*1,020.30 FL
5	1		*LHF DOOR SEAL PRIMARY	Necessary	195.95 FL	*195.95 FL
6	1		*LHF DOOR SEAL UPPER	Necessary	126.00 FL	*126.00 FL
7	1		*LHR DOOR SEAL PRIMARY	Not Necessary	195.95 FL	*- FL
8	1		*LHR DOOR SEAL UPPER	Not Necessary	102.00 FL	*- FL
9	2		*LHR DOOR LATCH HINGE	Not Necessary	155.30 FL	*- FL
10	2		*LHF DOOR LATCH HINGE	Bent	155.30 FL	*155.30 FL
11	1		*LHR DOOR CHECK ARM	Not Necessary	621.15 FL	*- FL
12	1		*LHF DOOR CHECK ARM	Damaged	621.15 FL	*205.00 FL
13	1		*LHF DOOR LATCH	Damaged	712.50 FL	*712.50 FL
14	1		*LHR DOOR LATCH	Not Necessary	712.50 FL	*- FL
15	1		*LHF WINDOW REGULATOR AND MOTOR	Not Necessary	965.60 FL	*- FL
16	1		*LHR WINDOW REGULATOR AND MOTOR	Not Necessary	965.60 FL	*- FL
17	1		*LHF WHEEL ARCH	Torn	400.00 FL	*400.00 FL
18	1		*FRONT BUMPER	Distorted	1,546.20 FL	*1,546.20 FL
19	1		*FRONT VALANCE PANEL	Repair	481.30 FL	*- FL
20	1		*LHF BUMPER MOULDING CHROME	Cracked	297.00 FL	*297.00 FL
21	1		*LHF BUMPER BRACKET	Necessary	38.00 FL	*38.00 FL
22	1		*FRONT BUMPER SPLITTER VANE	Damaged	225.00 FL	*225.00 FL
23	1		*LH SIDE DOOR MIRROR	Damaged	739.50 FL	*739.50 FL
24	1		*LH SIDE DOOR MOTOR	Damaged	173.70 FL	*173.70 FL
25	1		*LH SIDE DOOR GLASS	Missing	168.35 FL	*168.35 FL
26	1		*LH SIDE DOOR MIRROR COVER	Missing	302.40 FL	*302.40 FL
27	1		*LHF RIM 17 INCH	Cut	1,078.30 FL	*1,078.30 FL
28	1		*LHF TYRE 225/45R17 GOOD YEAR	Punctured	350.00 FL	*250.00 FL
29	1		*LHF SHOCK ABSORBER	Bent	373.80 FL	*373.80 FL
30	1		*LHF SHOCK ABSORBER BEARING	Not Necessary	137.60 FL	*- FL
31	1		*LHF SHOCK ABSORBER MOUNTING	Not Necessary	221.25 FL	*- FL
32	1		*LHF FENDER INDICATOR SIDE LAMP	Cracked	80.00 FL	*80.00 FL
33	1		*POWER STEERING RACK ASSY	Not Necessary	4,653.50 FL	*- FL
34	1		*LHF LOWER ARM	Bent	700.00 FL	*700.00 FL
35	1		*LHF VERTICAL LINK	Bent	885.00 FL	*885.00 FL
36	1		*LHF ANTI ROLL BAR LINK	Not Necessary	300.00 FL	*- FL
37	1		*FRONT ANTI ROLL BAR	Not Necessary	786.30 FL	*- FL
38	1		*LHF HEADLAMP ASSY	Cracked	3,168.40 FL	*2,800.00 FL
39	1		*LHF REHOUSING	Repair	1,260.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*LHF BUMPER REFEXTOR	Not Necessary	88.00 FL	*- FL
41	1		*LHF A POST PANEL	Repair	1,010.00 FL	*- FL
42	1		*LH SIDE SKIRT	Repair	376.40 FL	*- FL
43	1		*LHF DOOR OUTER MOULDING	Deformed	188.00 FL	*188.00 FL
44	20		*DOOR CLIP AND SIDE SKIRT CLIP	Necessary	200.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	35,873.00	16,244.80
- List Item Discount on L Items 10.00/10.00% (S\$)	3,567.30	1,618.48
Total Parts (S\$)	32,305.70	14,626.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R & R ACCIDENT DAMAGE PARTS, TO CUT/WELD, KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	2,500.00	1,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,800.00	1,200.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	50.00
4	TO R & R UNDER CARRIAGE SYSTEM	New	1,200.00	280.00
5	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	500.00	50.00
7	TO DO DIAGNOSTIC, REPROGRAM AND SCAN FAULT CODES	New	500.00	100.00
Gross Labour Cost (S\$)			7,900.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >