

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05930

Vehicle Insured : YN7282L
Accident Date : 19-Feb-2019

Date : 21-Feb-2019

Our Ref : 219030 (CHINA) / CHAN

PAGE : 1

REX MARINE & ENGINEERING PTE LTD
61 KAKI BUKIT AVE 1
#01-26
SHUN LI INDUSTRIAL PARK
Singapore 417943

Not Authorized
1/1/19 8?
Resurvey After Paint
3 days

ESTIMATED COST OF REPAIR FOR CITROEN BERLINGO 1.6D GBB4336X

1 pc	Front bumper fascia		<i>Bu 1 Re</i> 750.00	✓
1 pc	Front bumper lower grille		245.00	✓
1 pc	Front bumper top grille		245.00	✓
1 pc	Front bumper top		400.00	✓
6 pcs	Front bumper top rivet	@ S\$ 3.90	23.40	✓
1 pc	Front bumper tow cover		<i>sn</i> 45.00	x
1 pc	Front bumper sponge		178.00	✓
1 pc	Front bumper reinforcement		420.00	✓
			2,306.40	
Less 10% :			230.64	

1 pc Front no.plate with box

By 45 sn 2,075.76
50.00 sn

To putty and spray replaced parts

550.00 *400*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

250
650.00

Total : S\$ 3,325.76

Singapore Dollars Three Thousand Three Hundred
and Twenty Five and Cents Seventy Six Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: