

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YN7282L
Accident Date : 19-Feb-2019

Our Ref : 219030 (CHINA) / CHAN

REX MARINE & ENGINEERING PTE LTD
61 KAKI BUKIT AVE 1
#01-26
SHUN LI INDUSTRIAL PARK
Singapore 417943

No. : 05930

Date : 21-Feb-2019

PAGE : 1

NOT AUTHORIZED

1/1/2019 8?

Repair After Paint

3 days

ESTIMATED COST OF REPAIR FOR CITROEN BERLINGO 1.6D GBB4336X

- 1 pc Front bumper fascia
- 1 pc Front bumper lower grille
- 1 pc Front bumper top grille
- 1 pc Front bumper top
- 6 pcs Front bumper top rivet
- 1 pc Front bumper tow cover
- 1 pc Front bumper sponge
- 1 pc Front bumper reinforcement

Bumper	750.00	✓
ngem	245.00	✓
ngem	245.00	✓
cm	400.00	✓
@ S\$ 3.90	23.40	✓
sn	45.00	x
sn	178.00	xx
sn	420.00	✓

2,306.40
Less 10% : 230.64

2083.40
208.74
1875.06
2,075.76
sn 45.00

1 pc Front no.plate with box

To putty and spray replaced parts

550.00 400

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

250
650.00

Total : S\$ 3,325.76

Singapore Dollars Three Thousand Three Hundred
and Twenty Five and Cents Seventy Six Only

L/Sun
2030.00 ✓/dc
→ 1/1/2019 PLS Costum
tics.

P 1875.06
sn 45
L 650.00
2570.06
514.01
2056.05