

Repairer Estimates

Page 1 of 3

ETHOZ

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00016586	Date of Loss:	16/02/2019
Vehicle Reg. No.:	SLU9448E	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	VENKATRAMAN SUBRAMAIAM	Contact No:	+6594892713
Driver:	VENKATRAMAN SUBRAMAIAM		
Make/Model:	NISSAN TEANA, 2.5 CVT ABS D/AB HID 2WD 4DR (A)	Vehicle Reg. Date:	19/12/2009
Vehicle Colour:	BLUE		
Engine No:	VQ25390611A	Chassis No:	JN1BBUJ32Z0000821
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

*Not Authorized
with
the p/b before party
26/2/19
4 days
Excess?*

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	3,481.00
Labour	35.00
Paintwork Labour	1,290.00
Towing	0.00
	0.00
Gross Total (S\$)	4,806.00
+ GST 7.00% (S\$)	336.42
Nett Amount (S\$)	5,142.42

This claim is handled by: JONATHAN LIM KOK SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Repairer Estimates

REPAIR DETAILS	
Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2019)
Parts: 143	NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ETHOZ Protect Pte Ltd/SLU9448E/22/02/2019 15:57	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>Des</i>	0.00	0.00	*720.00 F
2	10		*FRONT BUMPER CLIPS <i>Des</i>	0.00	0.00	*50.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH <i>17</i>	0.00	0.00	*55.00 F
4	1		*FRONT BUMPER SIDE RETAINER LH <i>3rd</i>	0.00	0.00	*55.00 F
5	1		*FRONT HEADLAMP LH <i>scaler</i>	0.00	0.00	*1,100.00 F
6	1		*HEADLAMP WASHER NOZZLE & MOTOR LH <i>one</i>	0.00	0.00	*300.00 F
7	1		*HEADLAMP WASHER COVER LH <i>from price</i>	0.00	0.00	*95.00 F
8	2		*FOG LAMP COVER LH <i>gms</i>	0.00	0.00	*118.00 F
9	1		*FOG LAMP LH	0.00	0.00	*250.00 F
10	1		*FRONT BUMPER LOWER GRILLE MOULDING LH <i>mis/one</i>	0.00	0.00	*110.00 F
11	1		*FRONT FENDER LH <i>17/18</i>	0.00	0.00	*450.00 F
12	1		*FRONT FENDER INNER SHIELD LH <i>17</i>	0.00	0.00	*130.00 F
13	10		*FRONT FENDER INNER SHIELD CLIPS <i>17</i>	0.00	0.00	*50.00 F

F=Franchise part.

Total Parts (S\$) 3,481.00

ETHOZ Protect Pte Ltd/SLU9448E/22/02/2019 15:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Repairer Estimates

Page 3 of 3

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE & HOLDER	35.00
			11
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New	660.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	600.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00
Gross Labour Cost (S\$)			1,290.00

ETHOZ Protect Pte Ltd/SLU9448E/22/02/2019 15:57. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orlx.com.sg>

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: