

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Lionel Tan

Date: 26 Feb 2019

**Preliminary Advice**

Vehicle No	: SLU9448E	Accident Date	: 16/02/2019
Make	: NISSAN TEANA	Policy No.	: PNPV2018-00016586
Assignment Date	: 22/02/2019	Excess	: S\$600.00
Date of Inspection	: 26/02/2019	Est. Duration of Repair	: 4.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,806.00
Revised Amount	:S\$	3,996.00
Check Items (Estimated)	:S\$	250.00
Total	:S\$	4,246.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	22,000.00
COE / PARF Rebate	:S\$	16,089.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,911.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :