

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 023/IC/TCAC/CCR/2019
DATE : 22-FEB-2019

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : CHEE YEW KUN (ZHU YAOPEN)
ADDRESS : BLK 612 CLEMENTI WEST ST 1
#12-320
S(120612)
TELEPHONE NO : 67775142/93628714

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100487881-02
VEHICLE NO : SGN8855R
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2331786A
CHASSIS NO : SJNFEAJ11U1766144
MILEAGE : 29085 KM
DATE IN : 22/02/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 22/02/2019

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGN8855R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPLACE REAR BUMPER, TOW HOOK COVER, REAR UPPER PANEL, ENERGY ABSORBER ETC. REPAIR PANELS	1170.00	780
5	ZZ/002	RESPRAY REAR BUMPER IN 2 COLORS, REAR UPPER PANEL ETC	1000.00	625
6	ZZ/003	QC, RETUNE & CONSULT CHECK		
7	ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			2445.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGN8855R

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REVERSE SENSOR(J11 & T32) <i>sub ✓</i>	SENSOR-TE5140			360.00	
2	RIGHT BUMPER BRACKET <i>?</i>	85220-4EA0A	35.90			
3	LEFT BUMPER BRACKET <i>ret ?</i>	85221-4EA0A	35.90			
4	ENERGY ABSORBER <i>?</i>	85090-4EA0B	126.40			
5	RIGHT BUMPER RETAINER <i>?</i>	79184-4EA0A	23.80			
6	LEFT BUMPER RETAINER <i>?</i>	79185-4EA0A	23.80			
7	TOW HOOK COVER <i>X</i>	85071-4EA0A	16.80			
8	REAR BUMPER <i>De ✓</i>	85022-4EA0H	717.00			
9	REAR UPPER PANEL <i>repair</i>	G9110-4EAMA	482.60			
SUB TOTAL			1462.20	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			292.44	0.00	0.00	
GRAND TOTAL			1169.76	0.00	360.00	
OVERALL TOTAL			1529.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGN8855R

TOTAL LABOUR CHARGES	2445.00
TOTAL SPARE PARTS CHARGES	1529.76
GRAND TOTAL	3974.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	27/02/19 @ 1110
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 4 days
LIABILITY	:	0.00
REMARKS	:	

Reservy b4 part

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.