

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd

AIG Building

78 Shenton Way #08-16

Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6419 3000 Fax : 6835 7416

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SMG 9604 H

MODEL : HYUNDAI AVANTE 1.6 GLS

POLICY NO : CN027957

CHASSIS NO : KMHD841CMKU809712

YEAR OF MANUFACTURE : 2019

DATE / TIME OF ACCIDENT: 19/02/2019 Time: 1300Hrs at TOA PAYOH EAST.

THIRD PARTY VEHICLE NO: SMA7615X

Not Notified

Resurvey B6 per SM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date: 26/02/2019

Page 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front bumper	1	474.40	Torn <i>Bumper</i>	474.40 ✓
2 Front bumper side retainer LH	1		Necessary NN	X
3 Front bumper side retainer RH	1		Necessary NN	X
4 Front bumper clips	12	3.00	Necessary <i>mm</i>	36.00 ✓
5 Front bumper fog lamp RH	1	164.80	Scratches	164.80 ✓
6 Front bumper fog lamp side garnish RH	1		Scratches <i>mm</i>	✓
7 Headlamp assy RH	1		Cut <i>CR</i>	✓
8 Headlamp lower bracket RH	1	12.00	Torn	12.00 ✓
Sub-Total:				687.20
Less: 20% discount -				137.44
Total Parts after 20% discount:				549.76

Special Nett Items

1 Anti-rust coating	1	80.00	<i>nn</i>	80.00 X
				80.00
Total Parts:				629.76

Labour Charges For RH Side Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.			<i>200</i>	750.00
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities			<i>220</i>	750.00
3 Provide skill labour to disconnect and check electrical wiring			<i>20</i>	60.00
Total Labour:				1,560.00
Total Parts & Labour:				2,189.76
GST 7%				153.28
Grand Total:				2,343.04

ACCIDENT VEHICLE OF : SMG 9604 H

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
Company : UKK
Date : 26/2/19
Time : 12.40pm
Contact No : 96910663
Email : _____