



樹發汽車修理廠 SHU FATT AUTO WORKS

①-11

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
25th February 2019
TP-7

SLV 9735 X SUBARU FORESTER

			SS
Spare Parts	1	Rt firt headlight.	? 2580.40
	1	Rt firt headlight holder.	? 45.30
	1	Rt firt headlight washer.	? 115.90
	1	Rt firt headlight washer cover.	mis ✓ 89.20
	1	Frt bumper.	de ✓ 594.20
	1	Frt bumper reinforcement.	? 298.80
	1	Rt firt bumper bracket.	? 45.10
	1	Frt bumper foam.	? 150.20
	1	Set firt bumper clips.	mi ✓ 42.00
	2	Frt bumper side retainers. @\$45.30	LH-7 RH-8 90.60
			4051.70
		Less 10%	405.17
			3646.53
Labour		To knock rt firt wheel house, rt firt inner panel, rt firt fender, firt lower panel, firt side panel, renew firt light, firt grille, firt bumper and assembly.	250 750.00
		To respray damaged parts.	120 750.00
		To check and reset ECU.	100 150.00
			5296.53

Yokohama 225/60R17
JF1SJ5KC5JG103257
9627

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
u2p
11/3/19 R 245pm
Resurvey before/after painting.
Sir @ LKK Auto con
03 days
To check happen or part by part