

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 27 Feb 2019

Preliminary Advice

Insured Vehicle No	: SKK2646K	Accident Date	: 20/02/2019
TP Vehicle No	: GBJ1569T	Assignment Date	: 25/02/2019
Make	: DAIHATSU MATERIA	Est. Duration of Repair	: 4.00
Date of Inspection	: 25/02/2019		
Inspection At	: SOON SAN MOTOR TRADING (HQ) BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408700		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,564.71
Revised Amount	:S\$	3,992.06
Check Items (Estimated)	:S\$	426.51
Total	:S\$	4,418.57

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.