

ASS. REC. BY:

REF:

MSG19003460/Ktd3ⁿ²

Special Instruction:

Surveyor
MEMMEN

ASSIGNMENT (Office)

From (Person):

Pauline Tham

of

MSG

Date/Time:

22/2/19 4:35pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SJR 6991L

Insured:

SKN 34564

at Workshop in/s

Cheng Hwe Motor

Tel:

67556142

of

B11C1019, Yishun Ind. Park A #01-374/382

Policy No:

27682178

Claim No:

584151

Sum Insured:

Excess:

Make of Vch:

D.O.A

30/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:24am 22/2/19

Person Contacted:

Jane

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SJR 6991L - CC6/AIG/14023621 / KwY3w2 DOA: 15/12/19

SKN 34564 - NA/MSG19002087/19 DOA: 30/01/2019

28/2-

Revised via memmen preli advice

5/5

11 Lm 8'4000 Cabnet (Red: 500.72; 267-)

ASS. REC. BY:

REF: *MSG/**Kenneth*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *\$8500*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *03* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *STR 69914*Yr Regn: *OK 09*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Hyundai Verna*

c.c

*1399*Colour: *White*

A/C:

Insured / Std / NI / NA

Sp. Reading: *141 PP3*

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: *KMH CM 41 AR 9U 307814*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt orModl: *NI* / S/Rim / STD A/Rim orTyre Size: F: *175/65R14*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *8* mmR/Bal. *8* mmL/Bal. *8* mmL/Bal. *8* mmD.O.A. *30/1/19*D.O.I. *26/2/19*

Survey held at _____

Des. of Damages: Frt *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*1**File pass to*

RECEIVED 10 MAY 2019

9/5/2019

Date/Time, File Pass to?

9/5 Typist

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair: *3*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

*TP**1401-**150*
*10**160*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 28 Feb 2019

Preliminary Advice

Insured Vehicle No	: SKN3456U	Accident Date	: 30/01/2019
TP Vehicle No	: SJR6991L	Assignment Date	: 22/02/2019
Make	: BMW 320I	Est. Duration of Repair	: 3.00
Date of Inspection	: 26/02/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,900.72
Revised Amount	:S\$	1,530.80
Check Items (Estimated)	:S\$	219.92
Total	:S\$	1,750.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2019 13:38		22 Feb 2019 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: TAN LAY PENG, ID: S1539032H	
Main Claimant: RRATHNAM, ID: S1142005B	
Vehicle Reg. No.: SJR6991L	Date of Loss: 30/01/2019 20:00 - :59 [58 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / 584151	Policy/Cover Note No.: 27682178 (Comprehensive) Coverage: 27/03/2018 - 26/03/2019
Vehicle Reg. No. (Insured): SKN3456U	Policy No. (Claimant):
	Excess:
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2019]	
Adj Asg. Remarks: LIABILITY 100%. TP AGREE WITH SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD.	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2005B
Vehicle Details	
Vehicle No.:	SJR6991L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	VERNA 1.4 AUTO
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	G4EE8178151
Chassis No.:	KMHCM41AR9U307814
Maximum Power Output:	69.9 kW (93 bhp)
Open Market Value:	\$9,560.00
Original Registration Date:	08 Jul 2009
First Registration Date:	08 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$9,560.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jul 2019
PARF Rebate Amount:	\$4,780.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jul 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,326.00
COE Rebate Amount:	\$281.00
Total Rebate Amount:	\$5,061.00

The information contained herein is correct as at 14 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/02/2019 16:34
Date Of Accident	30/01/2019 20:35
Exact Location Of Accident	TPE TOWARDS WOODLANDS 7KM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR6991L
Insured/Policyholder	
Name Of Registered Owner	RRATHNAM
NRIC No	S1142005B
Email Address	RAAJARATINAM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83396789
Alternative Phone No	OFFICE-83396789

Vehicle Particulars

Manufacturer	HYUNDAI
Model	VERNA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC18S003232
Cover Note Number	

Driver

Name of Driver	RRATHNAM
NRIC No	S1142005B
Date Of Birth	27/07/1954
Occupation	OUTDOOR
Date Of Driving Pass	04/02/1985
Driving Experience	33 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83396789
Fax Number	
Contact Number	OFFICE-83396789
Email Address	RAAJARATINAM@GMAIL.COM

Address

BLK 214 MARSILING LANE #12-800

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKN3456U

Vehicle Make/Model/Colour BMW

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LIM KANG WEI

NRIC/Passport Number S9209618A

Contact Number 96898712

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBF9510E

SKETCH PLAN



A: SJR6991L

B: SKN3456U

C: GBF3510E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along TPF towards at Tkm landmark. Traffic was slow, and stop awhile due to heavy traffic after awhile traffic start moving, and I was about moving slow and suddenly a BMW hit at back of my car and, I stop. we took some photo's exchange the phone numbers and he said he will call me, but didn't, I did call him and he reply saying will call me back.

He did call me back around 17.00 hrs, I did ask him whether he want to settle privately or make report, he told me he will call me back after discussing with someone.

Then he call me back at 18min later and ask me to make claim against his insurance.

There was another lorry which hit the BMW behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date: 5/11/2011

Driver's Signature

Reporting Centre Personnel's Signature

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJR 6991L
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/WL

Claim Type: Third Party

Accident Date: 30/01/2019

TP Veh Reg No: SKN3456U

Estimate No: ES1991198/WL

Date: 26 Feb 2019

Policy No: DMPC18S003232

Veh Reg No: SJR6991L

Make/Model: HYUNDAI VERNA 1.4
AUTO

Chassis No: KMHCM41AR9U307814

Engine No: G4EE8178151

Reg. Date: 08/07/2009

Not Authen'd

11 Sep 8?

Resurvey After Paint

Estimate Repair Cost to Vehicle No :SJR6991L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	489.10	1 PC	489.10	✓
2 REAR BUMPER REINFORCEMENT	270.00	1 PC	270.00	✓
3 REAR BUMPER SPONGE	109.90	1 PC	109.90	✓
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
			890.00	
		Less 20%	178.00	712.00
Special Net				
5 REVERSE SENSOR	200.00	1 SET	200.00	✓
			200.00	200.00
Labour				
6 PANEL BEATING	400.00	1 LA	400.00	
7 PUTTY & RESPRAY	400.00	1 LA	400.00	
			800.00	800.00
			Total	S\$ 1,712.00
			Add GST @ 7%	119.84
			Total Amount Payable	S\$ 1,831.84

1 in rear boot inner lock
emblem VERNA
emblem M 1.4

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJR 6991L
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/WL

Claim Type: Third Party

Accident Date: 30/01/2019

TP Veh Reg No: SKN3456U

Estimate No: ES1991198/WL

Date: 26 Feb 2019

Policy No: DMPC18S003232

Veh Reg No: SJR6991L

Make/Model: HYUNDAI VERNA 1.4
 AUTO

Chassis No: KMHCM41AR9U307814

Engine No: G4EE8178151

Reg. Date: 08/07/2009

Estimate Repair Cost to Vehicle No :SJR6991L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	418.60	1 PC	418.60	—
2 REAR BUMPER REINFORCEMENT	176.10	1 PC	176.10	7 ✓
3 REAR BUMPER SPONGE	98.80	1 PC	98.80	7 ✓
4 REAR BUMPER CLIPS	3.80	6 PCS	22.80	—
5 REAR BOOT INNER LOCK	38.70	1 PC	38.70	—
6 REAR BOOT EMBLEM (VERNA)	32.30	1 PC	32.30	—
7 REAR BOOT EMBLEM (M 1.4)	26.10	1 PC	26.10	—
			813.40	
		Less 20%	162.68	650.72
Special Net				
8 REVERSE SENSOR	200.00	1 SET	200.00	200.00
			200.00	
Labour				
9 PANEL BEATING	500.00	1 LA	500.00	400
10 PUTTY & RESPRAY	550.00	1 LA	550.00	500
			1,050.00	1,050.00

Total S\$ 1,900.72

Add GST @ 7% 133.05

Total Amount Payable S\$ 2,033.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Photo in
folder

Arthur Kenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJR 6991 L
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/WL

Claim Type: Third Party

Accident Date: 30/01/2019

TP Veh Reg No: SKN3456U

Estimate No: ES1991198/WL

Date: 26 Feb 2019

Policy No: DMPC18S003232

Veh Reg No: SJR6991L

Make/Model: HYUNDAI VERNA 1.4
AUTO

Chassis No: KMHCM41AR9U307814

Engine No: G4EE8178151

Reg. Date: 08/07/2009

Estimate Repair Cost to Vehicle No :SJR6991L

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	418.60	1 PC	418.60	—
2 REAR BUMPER REINFORCEMENT	176.10	1 PC	176.10	—
3 REAR BUMPER SPONGE	98.80	1 PC	98.80	—
4 REAR BUMPER CLIPS	3.80	6 PCS	22.80	—
5 REAR BOOT INNER LOCK	38.70	1 PC	38.70	—
6 REAR BOOT EMBLEM (VERNA)	32.30	1 PC	32.30	—
7 REAR BOOT EMBLEM (M 1.4)	26.10	1 PC	26.10	—
			813.40	
		Less 20%	162.68	650.72
Special Net				
8 REVERSE SENSOR	200.00	1 SET	200.00	200.00
Labour				
9 PANEL BEATING	500.00	1 LA	500.00	400
10 PUTTY & RESPRAY	550.00	1 LA	550.00	500
			1,050.00	1,050.00

Total S\$ 1,900.72

Add GST @ 7% 133.05

Total Amount Payable S\$ 2,033.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

#650.72

200

900

#1750.72

✓ S\$ 1400 ✓ ok

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003460/KTD3N2

Date: 10/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27682178
Claimant Vehicle No :	SJR6991L	Insured Vehicle No :	SKN3456U
Date of Loss:	30/01/2019	Nature of Claim:	TP
		Claim No:	584151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6991L	Engine No:	G4EE8178151
Make & Model:	HYUNDAI VERNA, 1.4	Chassis No:	KMHCM41AR9U307814
Reg. Date:	08/07/2009 (Man. Year: 2008)	Odometer:	141993 km
Colour:	White		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65R14	Rear Tyre Size:	175/65R14
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	850.72	850.72	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	900.00	150.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,900.72	1,750.72	150.00	7.89
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	1,900.72	1,400.00	500.72	26.34
+ GST 7.00/7.00% (S\$)	133.05	98.00	35.05	26.34
Nett Amount (S\$)	2,033.77	1,498.00	535.77	26.34

INSPECTION

Date of Assignment: 22/02/2019

Date Inspected: 26/02/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
Parts:	143	HYUNDAI VERNA 1.4 (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR6991L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	418.60 FL	*418.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	176.10 FL	*176.10 FL
3	1		*REAR BUMPER SPONGE	Cracked	98.80 FL	*98.80 FL
4	6		*REAR BUMPER CLIPS	Necessary	22.80 FL	*22.80 FL
5	1		*REAR BOOT INNER LOCK	Dented	38.70 FL	*38.70 FL
6	1		*REAR BOOT EMBLEM (VERNA)	Necessary	32.30 FL	*32.30 FL
7	1		*REAR BOOT EMBLEM (M1.4)	Necessary	26.10 FL	*26.10 FL
8	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,013.40	1,013.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	162.68	162.68
Total Parts (\$\$)	850.72	850.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	500.00	400.00
2	PUTTY & RESPRAY	New	550.00	500.00
Gross Labour Cost (S\$)			1,050.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >