

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 06 Mar 2019

Preliminary Advice

Vehicle No	: GBH9935C	Accident Date	: 31/01/2019
Make	: TOYOTA DYNA 150 D	Policy No.	: DMCVSN1837681800
Assignment Date	: 25/02/2019	Excess	: S\$350.00
Date of Inspection	: 06/03/2019	Est. Duration of Repair	: 4 days
Inspection At	: Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road Singapore 628705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,350.00
Revised Amount	:S\$	13,470.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,470.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	28,640.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,360.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :