

INS. CASE OWNER: Stacy | CC 4 ^{RM} AXA1900 3473; Djb3 | LKK IDAC

Surveyor: Allyn | DOI: ASSIGNMENT | Date/Time: 25/1/19
 Registered in Merimen: _____

Pre-assign / CCU / FTE: _____
 Insured Vehicle No.: SHC 5516K | Claim No.: SMOLEPU/10032
 Name of Insured: THANS - LRB | Policy No.: VA/PL68020
 Insured Tel No.: _____ | HP: _____ | Make / Model: RENAULT
 Excess Sec II : \$\$ _____ | D.O.A.: 27/01/19 | Place of Accident: 7th RAMP ROAD IBERIAN
 Is driver the owner? (YES / NO) : _____ | Nature of Accident: _____
 If NO. Driver Name / Age: TOM KAY WAH | OI GIA REPORT: YES / NO : _____ | TP GIA REPORT: YES / NO : _____
 Driver Tel No.: _____ | (V/L: YES / NO) : _____ | Insured Liability: % _____ | Final ? Yes / No : _____

FBE 9961K → → → → →
 INSRs: WSP: 59 99 | INSRs: WSP: _____ | INSRs: WSP: _____
 Tel: _____ | Tel: _____ | Tel: _____
 Liability: _____ | Liability: _____ | Liability: _____
 RMKS: _____ | RMKS: _____ | RMKS: _____

Date/Time	STAGE	DATE / PIC
	Non-Reporting hr (1st)	
	Non-Reporting hr (2nd)	
	Non-Reporting hr (Final)	
	Notification hr (if non-pickup)	
	Call OI:	
	After call hr to OI:	
	Documentation Check List:	Handler Typist
	Notification hr (if non-pickup)	<input type="checkbox"/>
	After call hr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others: EM TO TP	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirms with: _____ Confirm by: _____
 Repair Cost: \$\$ _____ (days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call
 Final Liability: % 0 (Agreed / Assessed) BOLA S/N No.: NIL
 Repair Cost: \$\$ _____
 Loss of Rental (LOR): \$\$ _____ (days)
 Loss of Use (LOU): \$\$ _____ (S x days) PIR - AGAINST TP
 Loss of Income (LOI): \$\$ _____ (S x days)
 LOR only LOU only LOR + LOU LOR + LO [Tick only one]
 GIALTA Search: \$\$ _____
 Medical: \$\$ _____
 Disbursement: \$\$ _____ (e.g. Tow/ Independent)
 Legal Cost: \$\$ _____
Total: \$\$ _____ **Global Sum \$:** _____
 (1) Claim status: Normal/Reject/Private Settle
 (2) Report Format: \$350
 (3) Survey fee: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call
 Payee 1: \$\$ _____ Name 1: _____
 Payee 2: (Strike if N.A.) \$\$ _____ Name 2: _____
 Payee 3: (Strike if N.A.) \$\$ _____ Name 3: _____


REF:

ASSIGNMENT

02E April 2016

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **FBK 9961K** Yr Reg'd: **2016 April**
 Type: M.Car / **M.Cycle** / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Yamaha Sniper T150 cc 150**
 Colour: **Red / Black** AC: Insured / Std / NI / NA
 Sp. Reading: **104216** T/Radio: Insured / Std / NI / NA
 Eng/No: **G3E6E0184901**
 C/No: **MH3UG0740G0013672**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: Nil / **S/Rm** / STD A/Rim or



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **4** days Res: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: **80/90 R17**
 R: **120/70 R17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Maxxis**
 Front Rear
 P/Bal. **3** mm R/Bal. **3** mm
 L/Bal. mm L/Bal. mm
 D.O.A. **21/02/2019** D.O.I. **26/02/2019**
 Survey held at **8G 98 AMIC**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
0/8 Rev y n/s Patten.
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AXA SHC 5516K
	MV 7.5K
	LTA 4.4K
	NL 3.1K
21/05/19	Insured 2/5 22001 - with 4 days of repair
	R (\$ 2,148.40 / 49%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Days Of Repair:
 Resurvey No. of Trip:
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invz (\$)
 Weekend (\$)
 Report Format :
 Lump Sum / I.B.J: (\$)
 Survey Fee:
 Transportation: _____ \$ + RS. _____ \$
 Photos: _____
 Other: _____
 TOTAL: _____



T/20190221/2057



1 of 3

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

Report No. T/20190221/2057

REPORT OF A TRAFFIC ACCIDENT		Vide Report No.:	Station Diary No.:
Date/Time Report Made: 21/02/2019 12:51		J/20190221/0055	300
Informant's Particulars			
Name of Informant: SUKUMARAN A NAGESRAU		Address: APT BLK 120 HO CHING ROAD #05-101 SINGAPORE 610120	
ID Type / ID No.:		Contact No.:	Mobile: 84983912
NRIC NO / S7869826H		Home/Office:	
Nationality: MALAYSIAN		Email:	
Sex:	Age:	Date of Birth:	Type of Informant:
Male	40	23/05/1978	Rider
Race: Indian		Language:	Institution / School Name:
Occupation: TECHNICIAN		Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/02/2019 08:40	Type of Location: X-Junction
Location: Along Road 1 JALAN BOON LAY JALAN BOON LAY NEAR AYE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed b ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
FBK9961K	Motorcycle	YAMAHA	SNIPER T150	Red	Totally Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Da
FBK9961K	MSIG INSURANCE (SINGAPORE) PTE. LTD.	72085500	22/04/2018	21/04/201

S
NOff.
TP.
Sr &
ConAuthe
NP168/

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 25 February 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FBK 9961K

Sniper T150

ACCIDENT DATE: 23 January 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1 Handle Bar <i>bt/cut</i>	1	155.00	✓
2 Clutch Lever <i>broken</i>	1	98.00	✓
3 Front Top Cover <i>cut</i>	1	125.00	✓
4 Head Lamp <i>NH</i>	1	280.00	X
5 Balancer <i>cut/damaged</i>	1 set	130.00	✓
6 Handle Bar Grip <i>NH</i>	1	110.00	X
7 Mirror <i>Down NS o/s NH</i>	1 set	67.50 135.00	✓
8 Brake Lever <i>NH</i>	1	75.00	X
9 Front Panel <i>cut</i>	1	135.00	✓
10 Inner Shield <i>broken mounting</i>	1	165.00	✓
11 Front Mudguard <i>cut</i>	1	150.00	✓
12 Handle Bar Bracket <i>NH</i>	1	90.00	X
13 Footrest Bracket <i>bt</i>	1	125.00	✓
14 Front Footrest <i>LH bt</i>	1	75.00	✓
15 Gear Pedal <i>bt</i>	1	78.00	✓
16 Fork Tube <i>damaged/bt</i>	1 set	480.00	✓
17 Exhaust Guard <i>cut</i>	1	195.00	✓
18 Rear Mudguard <i>crack/broken</i>	1	185.00	✓
19 Front LH Side Fairing <i>repa</i>	1	185.00	X
20 Front LH Signal <i>broken</i>	1	2283.50 60.00	✓
21 Rear LH Signal <i>broken</i>	1	60.00	✓
22 Rear LH Fairing <i>repa</i>	1	2055.15 185.00	X
	Sub-Total	3,276.00	
	Less 10%	327.60	
	Sub-Total	2,948.40	

VEHICLE NO : FBK 9961K

Sniper T150

Nett Items

1 Towing Fee		40.00	30/-
2 Labour to remove & replace parts, align & etc		300.00	200/-
3 Remove & replace front fork tube & top up fork oil		120.00	80/-
4 Remove & repress rear & front rim		150.00	50/-
5 Supply body decal sticker		120.00	80/-
6 Rear box Cut	635.00	350.00	180/-
7 Rear number plate		15.00	✓
8 Rear box bracket		135.00	X

Special Nett Items

1 IU Unit Cut	120/-	170.00	120/-
		Sub-Total	1,400.00
		Nett Total	4,348.40

2810.15

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

26/02/2019 @ 1100hrs

L/S 2200/-

Not Antwork

L/S work

4 days.

(Signature)
ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(Signature)

*sg 98 motor
- Veh in
after 11.30*

Service Request Details

Claim

S9M01EPU

Reference

None 

Loss Date

February 21, 2019

Report Date

Feb 21, 2019 1:12:00 PM

Request Date

February 22, 2019

Due Date

February 25, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work	Menu 
---------------	--

Vehicle Information

Incident Vehicle Registration #

FBK9961K

Make

TPVD

Model

TBC

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

View Messages

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 28 June 2019 2:49 PM
To: Sg Motor
Cc: Sg Motor; CS A Team; Admin A
Subject: RE: Accident involving FBK 9961K and SHC 5516K
Attachments: TRAFFIC POL INV RESULT - AGAINST FBK 9961K.pdf

WITHOUT PREJUDICE

Dear Linda,

We refer to the subject.

Traffic Police Investigation Result (TPIR) revealed that your client, rider of FBK 9961K has committed an offence of inconsiderate driving. Copy of the TPIR attached.

In view of this, we regret to inform you that we are unable to look into your claim.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Sg Motor [mailto:sgmotor2000@yahoo.com.sg]
Sent: Tuesday, 25 June 2019 1:16 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>; CS A Team <cs-a@lkkauto.com>
Subject: Re: Accident involving FBK 9961K and SHC 5516K

Dear Joy

May I know the status for this case. Please revert.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd
Blk 4001 #01-21
Ang Mo Kio Industrial Park 1



RE: THIRD PARTY CHARGED FOR INCONSIDERATE DRIVING

Type

🔗 Question

Message

Dear Stacey, Thank you for sharing the Police Investigation Result. We will proceed to deny liability and will submit our report accordingly. Joy LKK

Reply



THIRD PARTY CHARGED FOR INCONSIDERATE DRIVING

Type

🔔 Question

Message

DOC SHARED

Reply



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408665
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/10441/2019
Date : 17 May, 2019

TOH KAY WAH
APT BLK 671A CHOA CHU KANG CRESCENT
#13-373
SINGAPORE 681671

Dear Sir/Madam

**ACCIDENT INVOLVING SHC5516K/FBK9961K ON 21 FEBRUARY 2019 AT 0849 HRS, ALONG
JURONG PIER ROAD BY JALAN AHMAD IBRAHIM L/P 63S1**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the rider of FBK9961K has committed an offence of Inconsiderate driving (accident) under Section 65(b) Of The Road Traffic Act Chapter 276. Action has been initiated against the rider for the said offence.

3. If you have any queries, please contact the Investigation Officer, Syed Muhammad Albar at telephone number 6547 6090 or via email at Syed_Muhammad_FARID_ALBAR@spf.gov.sg.

Yours faithfully

SHAHUL HAMEED
FOR HEAD, TRAFFIC INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19003473/Djb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY NG

Date : 10-07-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5516K	Veh. Inspected	FBK 9961K
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01EPU	Excess (\$)	0.00
Assign From		Assign Date	25/02/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA SNIPER T150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MH3UG0740G0013672	Colour	RED/ BLACK
Odometer	104216	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/90 R17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70 R17	MAXXIS	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/02/2019	Inspection Date	26/02/2019
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 9961K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR (CONSISTENT)	BENT / CUT	155.00	155.00
1	CLUTCH LEVER (CONSISTENT)	BROKEN	98.00	98.00
1	FRONT TOP COVER (CONSISTENT)	CUT	125.00	125.00
1	HEAD LAMP (CONSISTENT)	NOT NECESSARY	280.00	-
1	SET BALANCER (CONSISTENT)	CUT / DISLODGE	130.00	130.00
1	HANDLE BAR GRIP (CONSISTENT)	NOT NECESSARY	110.00	-
1	SET MIRROR (CONSISTENT)	N/S DAMAGED / O/S NOT NECESSARY	135.00	67.50
1	BRAKE LEVER (CONSISTENT)	NOT NECESSARY	75.00	-
1	FRONT PANEL (CONSISTENT)	CUT	135.00	135.00
1	INNER SHIELD (CONSISTENT)	MTG BROKEN	165.00	165.00
1	FRONT MUDGUARD (CONSISTENT)	CUT	150.00	150.00
1	HANDLE BAR BRACKET (CONSISTENT)	NOT NECESSARY	90.00	-
1	FOOTREST BRACKET (CONSISTENT)	BENT	125.00	125.00
1	FRONT FOOTREST LH (CONSISTENT)	BENT	75.00	75.00
1	GEAR PEDAL (CONSISTENT)	BENT	78.00	78.00
1	SET FORK TUBE (CONSISTENT)	DISTORTED / BENT	480.00	480.00
1	EXHAUST GUARD (CONSISTENT)	CUT	195.00	195.00
1	REAR MUDGUARD (CONSISTENT)	CRACKED / BROKEN	185.00	185.00
1	FRONT LH SIDE FAIRING (CONSISTENT)	TO REPAIR SEE LABOUR	185.00	-
1	FRONT LH SIGNAL (CONSISTENT)	BROKEN	60.00	60.00
1	REAR LH SIGNAL (CONSISTENT)	BROKEN	60.00	60.00
1	REAR LH FAIRING (CONSISTENT)	TO REPAIR SEE LABOUR	185.00	-
	LESS 10% DISCOUNT		-327.60	-228.35
			2,948.40	2,055.15
SPECIAL NETT ITEMS				
1	REAR BOX (SN) (CONSISTENT)	CUT	350.00	180.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	15.00	15.00

Report Ref No. CC4/ASM19003473/Djb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX BRACKET (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	135.00	-
1	IU UNIT (SN) (CONSISTENT)	CUT	170.00	120.00
			670.00	315.00
	LABOUR			
	TOWING FEE.		40.00	30.00
	LABOUR TO REMOVE & REPLACE PARTS ,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT LH SIDE FAIRING,REAR LH FAIRING AND REAR BOX BRACKET .		300.00	200.00
	REMOVE & REPLACE FRONT FORK TUBE & TOP UP FORK OIL.		120.00	80.00
	REMOVE & REPRESS REAR & FRONT RIM .		150.00	50.00
	SUPPLY BODY DECAL STICKER.		120.00	80.00
			730.00	440.00
GRAND TOTAL			4,348.40	2,810.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CC4/ASM19003473/Djb3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

[Home](#)
[SERVICE REQUESTS](#)
[MESSAGES](#)
[CLAIMS](#)

Service Request Details

Claim	59W01EPU
Reference	EC4/ASM19003473/D/b3a2 
Loss Date	21 February 2019
Report Date	21 Feb 2019 11:12:00 PM
Request Date	22 February 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

 Next Step: [Wait for Approve Invoice](#)
[Add Document](#)

Vehicle Information	
Incident Vehicle Registration #	FBK9961K
Make	TPVD
Model	TBC
Service Address	
	...

Primary Contact/Insured	
Primary Contact/Insured	TRANS-CAB SERVICES PTE LTD No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler	
Claim Handler	NG Stacy 6568B04351 stacy.ng@axa.com.sg

Additional Instructions

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notifs](#)

 Document Type:
[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LUK PHOTO-3.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
LUKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
LUKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
EMAIL REJECTION.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 June 2019
RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 June 2019
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 June 2019
TRAFFIC POL INV RESULT - AGAINST FBK 99A1R.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 June 2019
EMAIL TRAM AVA INSURANCE.msg	Letters and Correspondence	Government Authorities / Police / Association / Regulator	VISHNU BATHAM Shekhar	28 May 2019
SERVICE.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	22 February 2019
SHCS516K INSD GIA.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	22 February 2019
PRE EMAIL RECEIVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	22 February 2019