



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKU103X

Chua Kay Liang

23 Holland Hill
#01-05
Singapore 278739

Vehicle & Document Information

WIP No 31032
Reg No/Reg Date SKU103X / 17/06/2015
Date In/Mileage / 0
Chassis No WDD2050402R067843
Engine No 27491030386812
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 755 Tenorite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
WCV19669	CRDVCH	22/02/2019/ 14:03	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :D18MTPV01009985 // 19-02-2019 DRIVE IN:20-02-2019 // TP CAR NO:YM7640S (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :					
A BPILAB	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00 ✓
A BPILAB	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00 ✓
A BPILAB	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				1440.00 960
A BPIRES	RESPRAY REAR BUMPER & REAR BOOT LID				1500.00 1200
M RH/R TAIL LAMP	LKK Auto Consultants hence notify	1.00	693.13	00.00	693.13 ✓
M REAR BUMPER	the Repairer of the following:	1.00	3463.49	00.00	3463.49 ✓
M LH/R BUMPER GARNISH	• To resurvey before/after spray painting	1.00	93.01	00.00	93.01 ✓
M RH/R BUMPER GARNISH	• To display damaged part(s) during resurvey	1.00	93.01	00.00	93.01 ✓
M REAR BOTTOM PANEL	• Parts prices are subject to confirmation	1.00	215.55	00.00	215.55 ✓
M RH/R BASIC MOUNTING FOR BUMPER	• Third party survey is on a "Without Prejudice" basis	1.00	53.79	00.00	53.79 ✓
M RH/R PARKING SENSOR	• No illegal modification(s) is allowed	2.00	177.22	00.00	354.44 ✓
M RH/R PARKING SENSOR SEAL	• Supplementary item(s) must be resurveyed and	2.00	6.42	00.00	12.84 ✓
M RH/R BOTTOM BRACKET	is subject to final approval from Insurance Company	1.00	31.03	00.00	31.03 ✓
M RH/R BUMPER SIDE BRACKET		1.00	51.46	00.00	51.46 ✓
M REAR CROSS MEMBER	Acknowledged by Repairer	1.00	646.76	00.00	646.76 ✓
M REAR BOOT LID GARNISH	Signature:	1.00	131.28	00.00	131.28 ✓
M C180 EMBLEM	Date:	1.00	84.56	00.00	84.56 ✓
M STAR EMBLEM		1.00	48.25	00.00	48.25 ✓
M GROMMET		1.00	48.25	00.00	48.25 ✓
		3.00	1.88	00.00	5.64 ✓

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 918-1112 Fax: 6872 1272
www.cyclecarriage.com.sg

Confirmed & accepted by

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 918-112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Tanfu 93495749
7/3/19 WP
Rems before paint
105 days

Nett 9,418.24
7% GST on 9418.24 659.28
Total Payable 10,077.52

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

surellikants

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany