

Transcab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9973C**AAD1902-175***Not Attached
C/Eng &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9973C

VF1ABL15AUC273487

RENAULT

LATITUDE

21.2.2019

EQ

30/9/2013

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>By cm</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>By 10.1</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>By 11</i> 113.47	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>By</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	<i>By</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>By</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>By 11</i> 135.97	✓
8	1 BUMPER RETAINER LH REAR	\$	<i>By 11</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>cm</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>By</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>By 11</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>By</i> 225.95	✓
13	1 BOOT REAR	\$	<i>By</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>By</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>By 16m</i> 323.05	<i>50% @ 161.53</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>cm</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>By</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>By</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>By</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>By</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>By</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>By</i> 367.84	✓
23	1 BOOT HINGE RH	\$	<i>By 11</i> 367.84	✓
24	1 BOOT INNER TRIM	\$	<i>Return</i> 586.45	✓
25	1 BOOT SWITCH	\$	<i>By</i> 168.13	X
26	1 BOOT LOCK	\$	<i>By</i> 202.67	✓
27	1 BOOT LOCK CATCH	\$	<i>By</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>By</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>By</i> 221.81	X

Trans-cab Auto Services Pte Ltd**AAD1902-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9973C

30	1 FENDER PANEL REAR RH	CH	\$	Per	3,299.13	X
31	1 WHEELARCH REAR RH	CH	\$	Sh	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	CH	\$	Return Sh	671.45	X
33	1 WHEEL HOUSING PANEL REAR RH		\$	R	4,682.09	X
34	1 TAILLAMP LH		\$	CM	552.55	✓
35	1 TAILLAMP PANEL LH		\$	R	986.70	—
36	1 TAILLAMP RH		\$	Sh	552.55	X
37	1 TAILLAMP PANEL RH		\$	R	986.70	X
38	1 OUTER PANEL REAR (End Panel)		\$	R	1,471.77	—
39	1 OUTER PANEL REAR (End Panel)TRIM		\$	CM	404.56	—
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)		\$	R	2,189.88	} X
41	1 SPARE WHEEL PANEL TRIM		\$	Sh	612.21	
42	1 EXHAUST REAR		\$	R	7,489.05	
43	1 EXHAUST CAP REAR		\$	R	230.49	
44	1 WINDSCREEN REAR L70Y		\$	Sh	1,463.28	
45	1 WINDSCREEN GARNISH INNER LH		\$	Sh	263.74	} X
46	1 WINDSCREEN GARNISH INNER RH		\$	Sh	263.74	

TOTAL	\$	38,027.74
10%	\$	3,802.77
	\$	34,224.97

Special Nett

1	1SET PARKING AID	\$	Shat	700.00	Boosa
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	Boosa
13	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	Boosa
14	1 REAR BOOT ADVERTISEMENT STICKER	\$	na	300.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9973C

16 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
17 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	nb	28.00	✓
19 1 FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
20 1 TAILLAMP CLIP RH	\$	nn	5.00	X
21 1 TAILLAMP CLIP LH	\$	nn	5.00	✓
22 2 REAR WINDSCREEN SELANT	\$	nn	80.00	405n
23 1 WINDSCREEN MOULDING	\$	mc	100.00	✓
24 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	305n
25 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sk	385.00	X
26 1 SPARE TYRE	\$	nn	330.00	X

TOTAL \$ 2,580.02**TOTAL PARTS \$ 36,804.99****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	12001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-175**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9973C

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100%
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120%
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 51,144.99****(LUMP SUM)****Repair Days**~~20 DAYS~~

10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: