

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/13/2019 12:49 PM

Full Report
 Registration: SFX66M
 Printed: 15/04/2019 3:29 PM

Material Cost - Paint	Price SGD
New Part Painting	72.76
New Part Painting - Plastic K1R	57.56
Repair Painting	24.54
Surface-/Blend Paint	19.68
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	212.14

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	71101SDET10ZZ	/ BR	200.00 /
0317	L/F OUT BUMPER BRKT	71198SDET01	/ BR	11.00 /
0319	L/F UPP BUMPER BRKT	71190SDAA10	/ BR	29.00 /
0335	INN FIREWALL INSULAT	71170SDET00	/ BR	65.00 /
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	/ MEC	10.00 /
0410	GRILLE	71121SDJT01ZA	/ BR	60.00 /
0431	GRILLE BADGE	75700S9AG00	/ BR	18.00 /
0471	BONNET	60100SAGH00ZZ	/ DD	450.00 /
0492	BONNET LOCK	74120SDAA12	/ BT	65.00 /
0561	L/F HEADLAMP CPL	33151SDAQ11	/ BR	730.00 /
0562	R/F HEADLAMP CPL	33101SDAQ11	/ BR	600.00 /
4464	CONDENSER CPL	80110SDEQ02	/ DD	350.00 /
1000	INSULATOR CLIPS	VALUE	/ MEC	22.00 /
f: OEM Parts				0.00
n: Non-OEM Parts				2,610.00
u: Used parts				261.00
Savings				
Subtotal				2,871.00
Addition(+10.00%)				
Total				2,871.00

Extras

Code	Description	Price SGD
0335	[S]: INN FIREWALL IN SULAT: SUPP	0.00*
1004	FRONT NO PLATE / BR	35.00*
1005	AIR CON GAS / MEC	100.00*
1006	AIR CON COOLANT / MEC	20.00*
4464	[S]: CONDENSER CPL: OEM	0.00*
Total Extras		155.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/13/2019 12:49 PM

Full Report
 Registration: SFX66M
 Printed: 15/04/2019 3:29 PM

Code	Description	Price SGD	
Final Calculation			
		SGD	SGD
Parts		2,610.00	
	Addition(+10.00%)	261.00	
Total Parts			2,871.00
Labour Time Base 10 WU/h			
	Total 98.0 WU X 45.00 SGD/h	441.00	
Total of Labour			441.00
Total Of Extras			155.00
Paint Work Time Base 10 WU/h			
	Labour Cost 98.0 WU X 45.00 SGD/h	441.00	
	Material Cost	212.14	
Total Paint Including Material			653.14
Repair Cost Excludes GST			4,120.14
	GST (+7.0%)		288.41
Repair Cost Included GST			4,408.55

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD 0219 - 6896
Assessment number: OD 0219 - 6896
Version: 1810
Date calculated: 04/17/2019 10:26 AM

Full Report
Registration: SFX66M
Printed: 17/04/2019 10:26 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	OD 0219 - 6896	Date of Incident:	2019-02-22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	ACCORD (CM/CL)
Sub Model:	BASE MODEL
Model Sheet Number:	35 54 01
Registration:	SFX66M
VIN number:	MRHCM56505P400634
Odometer:	219598

Model Specs

FROM MODEL 2006	AIR CONDITIONING	FOG LAMPS	2.4 LTR 125KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/17/2019 10:26 AM

Full Report
 Registration: SFX66M
 Printed: 17/04/2019 10:26 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
8101D5	R + R FRONT BUMPER		4.0	18.00
8101A2)	RENEW FRONT BUMPER (REMOVED)		3.0	13.50
019106	R + R L/F FOGLAMP		3.0	13.50
019107	R + R R/F FOGLAMP		3.0	13.50
712102)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		8.0	36.00
813110)	RENEW RADIATOR GRILLE (REMOVED)		2.0	9.00
812100)	R + R BONNET		4.0	18.00
812100)	RENEW BONNET (REMOVED)		3.0	13.50
812120)	R + R BONNET LOCK		3.0	13.50
7201B0	R + R L/WING INDICATOR LAMP		1.0	4.50
8121B1)	R + R L/FRONT SCREEN FRAME AIR GRILLE		2.0	9.00
8121B1)	R + R R/FRONT SCREEN FRAME AIR GRILLE		2.0	9.00
710100	R + R BATTERY		2.0	9.00
616100)	R + R AIR CONDITIONING CONDENSER		1.0	4.50

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/17/2019 10:26 AM

Full Report
 Registration: SFX66M
 Printed: 17/04/2019 10:26 AM

Code	Description	WU	Price SGD
620020	REFILL + VENT AIR CONDITIONING	7.0	31.50
0741	L/F WING REPAIR	10.0*	45.00
0742	R/F WING REPAIR	20.0*	90.00
1009	FRONT PANEL CPL REPAIR	20.0*	90.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		9.80	98.0
Total of Labour			441.00

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
	BONNET NEW PART PAINTING	23.0	
	FRONT BUMPER NEW PART PAINT K1R	12.0	
	L/F WING REPAIR PAINTING <50%	11.0	
	R/F WING REPAIR PAINTING <50%	11.0	
	FRONT PANEL CPL SURFACE PAINT	7.0	

Paint Material Per Part

Code	Description	Price SGD
0333	FRT BUMPER SUPPORT SURFACE PAINT	3.74
0471	BONNET NEW PART PAINTING	72.76
0283	FRONT BUMPER NEW PART PAINT K1R	57.56
0741	L/F WING REPAIR PAINTING <50%	12.27
0742	R/F WING REPAIR PAINTING <50%	12.27
1009	FRONT PANEL CPL SURFACE PAINT	15.94

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		68.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	98.0	441.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/17/2019 10:26 AM

Full Report
 Registration: SFX66M
 Printed: 17/04/2019 10:26 AM

Material Cost - Paint	Price SGD
New Part Painting	72.76
New Part Painting - Plastic K1R	57.56
Repair Painting	24.54
Surface-/Blend Paint	19.68
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	212.14

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER	71101SDET10ZZ			200.00
0317	L/F OUT BUMPER BRKT	71198SDET01			11.00
0319	L/F UPP BUMPER BRKT	71190SDAA10			29.00
0335	INN FIREWALL INSULAT	71170SDET00			65.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS			10.00
0410	GRILLE	71121SDJT01ZA			60.00
0431	GRILLE BADGE	75700S9AG00			18.00
0471	BONNET	60100SAGH00ZZ			450.00
0492	BONNET LOCK	74120SDAA12			65.00
0561	L/F HEADLAMP CPL	33151SDAQ11			730.00
0562	R/F HEADLAMP CPL	33101SDAQ11			600.00
4464	CONDENSER CPL	80110SDEQ02			350.00
1000	INSULATOR CLIPS	VALUE			22.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				2,610.00
u: Used parts	Addition(+10.00%)				261.00
	Total				2,871.00

Extras

Code	Description	Price SGD
0335	[S]: INN FIREWALL IN SULAT: SUPP	0.00*
1004	FRONT NO PLATE	35.00*
1005	AIR CON GAS	100.00*
1006	AIR CON COOLANT	20.00*
4464	[S]: CONDENSER CPL: OEM	0.00*
	Total Extras	155.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/17/2019 10:26 AM

Full Report
 Registration: SFX66M
 Printed: 17/04/2019 10:26 AM

Code	Description	Price SGD
Final Calculation		
		SGD
		SGD
Parts		2,610.00
Addition(+10.00%)		261.00
Total Parts		2,871.00
Labour Time Base 10 WU/h		
Total 98.0 WU X 45.00 SGD/h		441.00
Total of Labour		441.00
Total Of Extras		155.00
Paint Work Time Base 10 WU/h		
Labour Cost 98.0 WU X 45.00 SGD/h		441.00
Material Cost		212.14
Total Paint Including Material		653.14
Repair Cost Excludes GST		4,120.14
GST (+7.0%)		288.41
Repair Cost Included GST		4,408.55

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729872
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PROGRESSIVE CAR CARE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY / PEI WEN / LEONG KEAT

00 6896

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9829

Arrange By _____ Driver _____



Wiper blade: NWB (Nippon Wiper blade), Silpor (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201902-10219
DATE : 26/02/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SFX66M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StdLoc	QTY	U/PRICE	AMOUNT
01	H71101-SDE-T10ZZT CM5 03 06	BUMPER FR	U1 L3-G14	1	200.00	200.00

26/02

SUB-TOTAL : 200.00
ADD GST 7.00 % 14.00

E. & O.E TOTAL AMOUNT SGD : 214.00

[P] 26/02/2019 5:51:46PM Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).
[E] 26/02/2019 5:51:25PM

JAE Auto Pte. Ltd.
Sales Executive : EDMUND



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date




日美汽車私人有限公司
JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Silpor (Made in Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD
 BLOCK 3022A #01-45/46
 UBI ROAD 1
 BUTTON 92712711
 SINGAPORE 408716
 TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
 ATTN : WENDY / PEI WEN / LEONG KEAT

006896

TAX INVOICE : AR201902-09780
 DATE : 26/02/2019
 CUSTOMER ID : PRO005
 VEH REG. NO. : SFX66M
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 1
 CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 H71198-SDA-T01T CM5 03	SPACER FR LH(A01)	U1 L2-F8-A	1	11.00	11.00 ✓
2 H71190-SDA-A00T CM5 03 06	BRACKET,L.FR BUMPER	U1 L2-G18-C	1	29.00	29.00 ✓

SUB-TOTAL : 40.00
 ADD GST 7.00 % 2.80

E. & O.E TOTAL AMOUNT SGD : 42.80

[P] 27/02/2019 10:01:07AM

[E] 26/02/2019 11:43:28AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : EDMUND



This is computer generated document.
 No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Arrange By _____ Driver LOW

WINDGREEN GLASS
Dept Direct: 6417 9791 / 6743 9029

TOYOTA
GEORGE PARKS
Dept Direct: 6203 9210

LEON LEE
DAIATSU
Dept Direct: 6203 9611

MAZDA
KIA
HYUNDAI
Dept Direct: 6417 9725

ISUZU
SUZUKI
NISSAN
Dept Direct: 6417 9700

Dept Direct: 6417 9753

Wiper blade: NWB (Nippon Wipor blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY / PEI WEN / LEONG KEAT

00 6896

TAX INVOICE : AR201902-09753
DATE : 26/02/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SFX66M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
✓	H60100-SDA-A00ZZ/SDB-A 90ZZ CM5 03 06	BONNET	PA PL1-G1-11A	1	450.00	450.00 ✓ -
✓	H74148-SDA-A00	BONNET SEAL RH R/G	PA PL1-C1-08J	1	15.00	15.00 ✓ -
3/	H91501-S1K-003	INSULATOR CLIP	PA PL1-L1-05R	11	2.00	22.00 ✓ -
4/	H74120-SDA-A12 CM5	BONNET LOCK	PA PL1-L1-07M	1	65.00	65.00 ✓ -
5/	H71121-SDF-T70 ROC CM5 03	GRILLE	PA PL1-A1-120	1	60.00	60.00 ✓ -
6/	H75700-S9A-G00T BE1 CL7 FD1	"H" EMBLEM	PA PL1-L1-04K	1	18.00	18.00 ✓ -
7/	H91503-SZ3-003	CLIP	PA PL1-J1-01A	10	1.00	10.00 ✓ -

CONTINUE NEXT PAGE

[P] 26/02/2019 11:41:17AM

[E] 26/02/2019 11:22:40AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9701 / 6745 9929

Audi
 Dept Direct: 6308 9616
 TOYOTA
 LEXUS
 DATSUN
 Dept Direct: 6305 9611
 Dept Direct: 6417 9702

MITSUBISHI
 Subaru
 MAZDA
 HONDA
 KIA
 HYUNDAI
 SUZUKI
 NISSAN
 Dept Direct: 6417 9704
 Dept Direct: 6417 9725
 Dept Direct: 6417 9706
 Dept Direct: 6417 9702

Wiper blade: NWB (Nippon Wiper blade), Silpor (Made in Korea),
Ferch (Made in Germany)
Spark plug: Nippon Danso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY / PEI WEN / LEONG KEAT

006896

TAX INVOICE : AR201902-09753
DATE : 26/02/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SFX66M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
9.	H71198-SDA-T01T	SPACER FR LH(A01)	PA	1	11.00	11.00
	CM5 03		PL1-L1-07J			R
9.	H33101-SFY-003	HEAD LAMP RH (D2S)	PA	1	600.00	600.00
	CM6 03		PL1-H1-01A			

SUB-TOTAL : 1,251.00
ADD GST 7.00 % 87.57

E. & O E TOTAL AMOUNT SGD : 1,338.57

[P] 26/02/2019 11:41:17AM

[E] 26/02/2019 11:22:40AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive: EDMUND



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9329

Arrange By

Driver

ASAP



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

00 6896

TAX INVOICE : AR201903-04389
DATE : 09/03/2019
CUSTOMER ID : PRO005
VEH REG. NO. : SFX66M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	St:Loc	QTY	U/PRICE	AMOUNT
1	H33151-SFY-003/023 CM6 03	HEAD LAMP LH (D2S)	PA PL1-H1-06A	1	730.00	730.00 ✓
2	H71170-SDE-T00F CM5 03	ABSORBER BUMPER	PA PL1-N1-070	1	65.00	65.00 ✓

SUB-TOTAL : 795.00
ADD GST 7.00 % 55.65

E. & O.E TOTAL AMOUNT SGD : 850.65

[P] 09/03/2019 9:52:12AM

[E] 09/03/2019 9:49:17AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: EDMUND



This is computer generated document.
No signature is required.

Goods Received in Good Order

[Handwritten Signature]

Signature / Co Stamp / Date

ORIGINAL



特 立 机 器 贸 易

MEGA POWER ENGINEERING & TRADING

Automobile Air Conditioning System Is Our Business

Head Office: 39 Genting Road Singapore 349485 Tel: 6842 3389 Fax: 6842 3373
Email: maga1980@singnet.com.sg Business Reg No 40869100W

TAX INVOICE

GST Reg# : M8-8002998-3
Invoice No. : INV 10114966
Invoice Date : 27-Feb-2019
Terms : 30 DAYS
PO No :
Vehicle No : SFX66 076896
Chassis No :
Staff : MS NEO

Bill To: PRO002
PROGRESSIVE CAR CARE PTE LTD
BLK 3022A UBI ROAD 1
#01-45/46
SINGAPORE 408716
Attn : Account Dept

Ship To: KG1
PROGRESSIVE CAR CARE PTE LTD
BLK 3022A UBI ROAD 1
#01-45/46
Attn : WENDY
Tel: 82585595

Remarks:
MUST KEY IN ORDER PERSON'S
NAME & VEHICLE NO.

S/NC	DESCRIPTION	MOQ	BIN	WH	QTY	PRICE	SP	TOTAL (SGD)
PO Number :		DO Number :						
1 CD	HONDA ACCORD CM5 2.0 CONDENSER W/DESI			KB	1	350.00		350.00 ✓

Rate : 1 SGD : 1.000000 SGD
Note : Goods sold are not returnable.
All Brand New compressor sold are without warranty.
Late payment is subject to 2% interest per month.

SUB-TOTAL 350.00 SGD
DISC 0.00% (-) SGD
GST 7% 24.50 SGD
AMOUNT 374.50 SGD

This is a computer-generated document.
No signature is required.
Printed on: 27/02/2019 9:49:14

CUSTOMER COPY

Customer Signature & Stamp



Blk 5025, Ang Mo Kio Ind Park 2 #01-55/57 S(568528) Tel: 6462 3389 Fax: 6461 1167
No 13 Kalo Bukit Rd 4 #01-27 Bantley Biz Centre S(417607) Tel: 6385 3389 Fax: 6385 3320

No 5 Soon Lee St #01-28 Pioneer Point S(627607) Tel: 6252 3389 Fax: 6275 3389
No 21 Teh Guan Rd East #01-33 Teh Guan Centre S(608509) Tel: 67603309 Fax: 6316 2454



Claim	S9M01EWY
Reference	CS/ASM19003479/Eq43s2 
Loss Date	February 22, 2019
Report Date	Feb 23, 2019 12:00:00 AM
Request Date	February 25, 2019
Due Date	February 25, 2020
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated survey and authorize

Actions

Next Step Finish the work

Complete Work More ▾

Vehicle Information

Incident Vehicle Registration #	SFX66M
Make	HONDA
Model	ACCORD 2.4

...

Primary Contact/Insured

HEE THIAM SOON
 NO.181 #08-19, TANJONG RHU ROAD, 436922, Singapore
 92379660
 TSHEE@STARHUB.COM

Claim Handler

TAN Jas
 656804844
 jas.tan@axa.com.sg

Additional Instructions **PROGRESSIVE OD XS \$400 + UNNAMED \$500-\$900**

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	
 SFX66 resurvey photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 17, 2019

Claim	S9M01EWY
Reference	CS/ASM19003479/Exp3x2
Loss Date	February 22, 2019
Report Date	Feb 23, 2019 12:00:00 AM
Request Date	February 25, 2019
Due Date	February 25, 2020
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated survey and authorize

Actions

Next Step: **Finish the work**

Vehicle Information

Incident Vehicle Registration #	SFX66M
Make	HONDA
Model	ACCORD 2.4
Service Address	...

Primary Contact/Insured

HEE THIAM SOON
 NO.181 #08-19, TANJONG RHU ROAD, 436922, Singapore
 92379660
 TSHEE@STARHUB.COM

Claim Handler

TAN Jas
 6568804844
 jas.tan@axa.com.sg

Additional Instructions: PROGRESSIVE OD XS \$400 + UNNAMED \$500-\$900

Messages Invoices History Documents Assessment Metrics Notes

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
TAN Jas	2/25/19 2:28 PM	3220.14	3220.14	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

Vehicle & Driver Details

Vehicle Registration#	SFX66M	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	11/05/2005
Mileage	219599	Age of Vehicle	13

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2005	2005	
Make	HONDA	HONDA	
Model	ACCORD 2.4	ACCORD 2.4 A	
Type			
Type of Paint			
Chassis No	ACR507044334	MRHCM56S05P400634	
Engine No	2AZC172939	K24A45P00726	
Engine Capacity		2354 cc	
Sum Insured	0	0	

Driver Details	
CATEGORY	PNOL INFORMATION
Driver Name	MOLLY TAN LEE JOO
Date of Birth	October 26, 1963
Age	55
Occupation	Unknown
Education Qualification	Other
Driving Experience	11
Driver License #	
License Type	

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	02/25/2019	Fair	
Total Loss	Yes No	Yes	No
Towing Charges	0	Yes	No
Voluntary Excess	0	Yes	No
Compulsory Excess	900	Yes	No
Young/Inexperienced/Unlicensed Driver Excess	0	Yes	No
Other Excess		Yes	No
Pre-accident condition		Good	

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	215/60R16	Rear Tyre Size	215/60R16
Front left side	MICHELIN 7mm	Rear left side	MICHELIN 7mm
Front right side	MICHELIN 7mm	Rear right side	MICHELIN 7mm

SERVICE REQUESTS **MESSAGES** **CLAIMS**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ BITTSK	DISC COUNTY%	SALV AGEN%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			FRONT NUMBER PLATE (NPA)			Repair	0				0	Reviewing	
	2	1			FRONT BUMPER [10%](WCP)			Broken	220				220	Reviewing	
	3	1			L/F OUT BUMPER BRKT [10%](WCP)			Broken	12.1				12.1	Reviewing	
	4	1			R/F OUT BUMPER BRKT			Serviceable	0				0	Reviewing	
	5	1			L/F UPP BUMPER BRKT [10%](WCP)			Bent	31.9				31.9	Reviewing	
	6	1			R/F UPP BUMPER BRKT			Serviceable	0				0	Reviewing	
	7	1			FRT BUMPER SUPPORT			Serviceable	0				0	Reviewing	
	8	1			FRT NUMBER CLAMP KIT [10%](WCP)			Necessary	11				11	Reviewing	
	9	1			GRILLE [10%](WCP)			Broken	66				66	Reviewing	
	10	1			RAD GRILLE COVER			Serviceable	0				0	Reviewing	
	11	1			L/GRILLE TRIM			Serviceable	0				0	Reviewing	

Add Approve Deny Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		5	
	2	FRONT NO PLATE	Reviewing	35	BROKEN	
	3	AIR CON GAS	Reviewing	100	NECESSARY	
	4	AIR CON COOLANT	Reviewing	20	NECESSARY	

- SERVICE REQUESTS
- MESSAGES
- CLAIMS

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount	\$3,220.14	Claim Amount	\$3,220.14
CATEGORY	ESTIMATE	REVISED AMOUNT	
Spare Parts	\$2,871.00	\$2,871.00	
Labour	\$1,094.14	\$1,094.14	
Miscellaneous	\$155.00	\$155.00	
Excess	-\$900.00	-\$900.00	

Submit for Review