



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 4661 9688 Fax: (65) 4661 9699 Email: info@hiahong.com.sg

Estimate Repair List

28 January 2019

HHTPClaims19-09

NTUC Income Cooperative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn: Motor Claims Department

ACCIDENT INVOLVING SKP 5137 S & GBE 3504 T ON 26/01/2019 ALONG BUKIT BATOK ROAD TOWARDS JURONG AT ABOUT 0830 HOURS

Insured : WAN WOO MEI
Vehicle Registration No : SKP 5137 S
Vehicle Make : NISSAN
Vehicle Model : SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Vehicle Chassis No : MNTBBAB1720020219
Policy No : 5073401372-03
Date of Accident : 26/1/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper BUC / NETT		\$ 453.60 /
2	2	Rear Bumper Retainer (LH/RH) 1 NMX NETT	\$ 48.50	\$ 97.00 X
3	1	Rear Bumper Foam (Center) 1 NMX NETT		\$ 58.60 X
4	2	Rear Bumper Foam (LH/RH) 1 LRA-RH NETT	\$ 58.60	\$ 117.20 58.60
5	2	Rear Bumper Stay (LH/RH) 1 DD-RH NETT	\$ 66.50	\$ 133.00 66.50
6	1	Rear End Panel DD / NETT		\$ 430.50 /
7	1	Rear End Panel Top Garnish DEF / NETT		\$ 125.30 /
8	2	Rear Taillamp Panel (LH/RH) 1 NMX NETT	\$ 263.20	\$ 526.40 X
9	2	Rear Taillamp (LH/RH) 1 SCR NETT	\$ 285.30	\$ 570.60 285.30
10	1	Rear Boot BUC / NETT		\$ 761.90 /
11	1	Rear Boot Lock Sketched / NETT		\$ 85.60 /
12	2	Rear Boot Hinge (LH/RH) 1 NMX NETT	\$ 58.40	\$ 116.80 X
13	1	Rear Boot Weather Strip DEF / NETT		\$ 76.80 /
14	1	Rear Boot Chrome (Lower) NEC / NETT		\$ 582.40 97.1
15	1	Rear Boot Chrome (Upper) NEC / NETT		\$ 182.20 /
16	1	Rear Emblem NEC / NETT		\$ 65.00 /
17	1	Rear Logo (SYLPHY) NEC / NETT		\$ 85.00 /
18	2	Rear Boot Lamp (LH/RH) 1 NMX NETT	\$ 147.60	\$ 295.20 X
19	1	Rear Boot Logo (XTRONIC CVT) NEC / NETT		\$ 105.00 /
				\$ 4,868.10
			Less 10%	\$ (486.81)
			(A)	\$ 4,381.29
20	10	Rear Bumper Clip S/NETT	\$ 3.50	\$ APC 35.00
			Less 5%	\$ (1.75)
			(B)	\$ 33.25

3151.30

10%

3136.17



HUA HONG PRIVATE LIMITED

250 Sungai Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

ACCIDENT INVOLVING SKP 5137 S & GBE 3504 T ON 26/01/2019 ALONG BUKIT BATOK ROAD TOWARDS JURONG AT ABOUT 0630 HOURS

Estimate Repair List for vehicle SKP 5137 S - Nissan Sylphy

		(A+B)	Balance B/F	\$	4,414.54
21	1	Reverse Sensor	? X	NETT	\$ 200.00 X
22	1	Rear Number Plate	DEF ✓	NETT	\$ 35.00 ✓
To dismantle, cut & weld rear panel, rear RH tail lamp panel, dismantle & change rear boot, rear LH/RH tail lamp, rear LH/RH boot lamp, knocking & pull straight rear tyre floor panel, rear RH fender and all area affected by accident					\$ 1,000.00 - 800 ✓
To perform wire checking					\$ 20.00 ✓
To dismantle & refit rear bumper sensor					\$ 60.00 ? X
To spray rear bumper, rear boot, rear end panel, rear tyre floor panel and rear LH/RH fender					\$ 1,000.00 800 ✓
					\$ 6,720.54
7% GST					\$ 471.07
Total					\$ 7,200.61

P- 2748 87

A1 - 65

L - 1520

4333 87

L/S - 3467 99

= 3450



Authorised by Claims Dept
Mrs Tan @ 9639 9195

28/2/19

Hwee Jia - CLK

25/2/19

L/S Solys.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: