

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Store

wrt print - 2/4/19 11.00 am

4 days

P/P

bpc spy

GST REG. NO : M2 - 0020081 - X

E S T I M A T EChange to
1 April morning
car will
25 FEB 2019 key drop
on 31/3/2019
SundayEstimate No. : b1 50247
Date Estimated : 25/02/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Daphnie Lin Rui Tong
27 Jalan Chengam

Singapore 578310

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG1689B	BJ24139	26/11/2018	630i GT	0

DESCRIPTIONVALUE

Replace rear bumper and remove attachment etc include knock on accident

850 1,275.00

Spray painting rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

X 531.00

Sundries.

? 150.00

Total Labour 1: **3,171.00**DESCRIPTIONQTYPRICVALUE

LH TAILPIPE TRIM CHROME X

1 180.90 180.90

REAR SILENCER WITH EXHAUST FLAP X

1 2,558.85 2,558.85

REAR BUMPER CARRIER ?

1 934.50 934.50

Abrasion gua XEC

1 5.50 5.50

Abrasion gua NEC

1 5.50 5.50

REAR BUMPER BOTTOM REINFORCEMENT ?

1 84.75 84.75

REAR BUMPER CENTRE GUIDE ?

1 73.80 73.80

REAR BUMPER TRIM PANEL PAINTED (M) X OR

1 452.80 452.80

REAR BUMPER PANEL PRIMED (M) ?

1 1,811.20 1,811.20

DECOUPING RING PDC TORQUE CONVERTER XEC

4 5.05 20.20

ULTRASONIC SENSOR MINERALWEISS(WA96) ?

2 368.80 737.60

Total Parts : **6,865.60**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 50247	Page No. : 2 of 5
Date Estimated	: 25/02/2019	
Prepared By	: Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG1689B	BJ24139	26/11/2018	630i GT	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No.	Claim No.
Date&Time	Excess S\$
Surveyor's Name	Sign
Surveyor's Tel	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Manager's Email	
Pls. of Working Days Recommend	

Labour 1	:	3,171.00
Parts	:	6,865.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	702.56
Grand Total	:	10,739.16

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **