

23052010

ASS. REC. BY:

REF: CS/FCS/19003489/T1td3 | ⁿ² Special Instruction

Wey/OV

ASSIGNMENT (Office)

From (Person): CWS Serene Ter of FCE Date/Time: 12:56pm @ 25/2/2019

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OI RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKC 500C Insured: SHC 29892

at Workshop n/s: Performance Tel: 6319 0174

of 303 Alexandra Road

Policy No: _____ Claim No: D19001186 MFST

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 1/2/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS CD

H.O.D. Endorsement: _____

Date/Time: 2:08pm @ 25/2/19 Person Contacted: Caroline Vehicle-IN/OUT: (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SKC 500C - X
	SHC 29892 - CS/FCS 13018554 / 11g6/c3 D.O.A. 6/10/13
14/3 @ 10:25am	revised preli via email.
	Part by part \$10,725.35 (Red: 2379.80 : 18%)

Taufik

REF:

FCI

5.0.1.1.1.1.1

Name: _____ Date: _____

Estimated Cost: _____

On: W5 / R5 / O5 / LVA / HW / HW

Make of Vehicle: _____

Model: _____

Year: _____

Engine: _____

Color: _____

Capacity: _____

Engine: _____

Color: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NH / R / STD AR / or

Tyre Size: F: _____ R: _____

Ex: BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: G mm _____ R/Bal: G mm

L/Bal: G mm _____ L/Bal: G mm

D.O.A. _____ D.O.I. 11/3/19

Survey held at: PML

Des. of Damages: Fit / Rear / O5 / N5 / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date of Market Value: _____

RAC: Accident Report Consistent? Yes or No

GA: PE Seca Consistent? Yes or No

Est. Repair: 7 days Res.: Yes or No

Time: _____ % 3 Val: Yes or No

CA / REM / REP. / 24 HRS WP'

Date: _____ Person Contacted: Kevin

Vehicle: IN / OUT

Vehicle: SKC500G Date: 2017 Jan.

Type: Car / Motorcycle / Bus / Van / Heavy / Light / Prime Mover / Truck / Trailer or

Make: BMW 218i CC: 1499

Colour: Black. No. Insured / Std / NI / NA

Cap. Rating: 22714 (1) Value: Insured / Std / NI / NA

Engine: W5A2F/2000 V885620

Color: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NH / R / STD AR / or

Tyre Size: F: 225/45R17 R: _____

Ex: BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: G mm _____ R/Bal: G mm


L/Bal: G mm _____ L/Bal: G mm

D.O.A. _____ D.O.I. 11/3/19

Survey held at: PML

Des. of Damages: Fit / Rear / O5 / N5 / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



Date/Time: 21/5 Action/Instruction: 910.725.35, 7 days email + Corolite

RECEIVED 23 MAY 2019

[Signature]
22/5/2019

Deliverable File Path: Preli. Report Final Report

Date/Time: 23/5 *[Signature]*

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee: 3x15 = 45

Transportation: 170 + 45

Other: 50

Total: 50 + 50 = 81

Date: 23/5/19

446

Add Fee: Site Insp. (\$) Interview (\$) Test report (\$) Workshop (\$)

Report Format: TP

Temp: 10725.35



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001186MFSH

Date: 14/3/2019

Our Ref: CS/FCI19003489/T1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKC 500C

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/3/2019 at the premises of M/s Performance have the following to report: -

Workshop Estimate Amount	: S\$ <u>12,920.15</u>
Revised Estimate Amount	: S\$ <u>8,594.85</u>
"Check" Items Amount	: S\$ <u>3,016.50</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-02-2019	Our Ref No. D19001186MFSH
Accident Date	14-02-2019	Claim Type. Third Party
Insured Vehicle	SHC2989Z	Third Party Vehicle. SKC500C
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR \$13,824.56)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 14 March 2019 10:25 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001186MFSH/1
Attachments: PRELI ADVISED SKC 500C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKC 500C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 25 February 2019 2:07 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001186MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 25 February 2019 12:56 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001186MFSH/1

Dear Sir/Mdm,

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 22 May 2019 11:54 AM
To: PBSP; SUR
Subject: RE: FINAL REPORT/ SKC500C

Dear Caroline,

Confirm Total Labour & Parts : \$10,725.35, 7days.

Please submit all relevant documents to first capital

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 14 May 2019 6:38 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT/ SKC500C

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,700.00

Total Parts : 4,025.35

Total Labour & Parts : 10,725.35

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

13105-15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Rongpong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (MOTORrad)
Fax. 64796601 (AfterSales)
64796624 (MOTORrad)

GST REG. NO : M2 - 0020081 - X

22 FEB 2019

ESTIMATE

Estimate No. : b1 50224 Date Estimated : 22/02/2019 Prepared By : Kevin Leong Wai Kit	Page No. : 1 of 5
--	--------------------------

- ESTIMATE REPAIR FOR - Ang Wei Shan (Hong Weishan) 66 Marine Parade Road #22-10 Singapore 449300	- ACCOUNT - 303 MS First Capital Insurance Limited 6 Raffles Quay #21-00 Singapore 048580
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC500C	V885620	03/01/2017	218iA/2	0

DESCRIPTION	VALUE
To replace rear bumper, rear boot, reinforcement & all attachments cause by accident. To repair on frt bumper panel	✓ 2550. 3,400.00
Painting on rear bumper, frt bumper & rear boot.	✓ 2664 2,961.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	✓ photo 451 531.00
To check electrical wiring systems for proper function.	250. ✓ 150 177.00 ¹⁰⁰
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	✓ 451 531.00
To carry out body cavity preservation. (Per panel) Boot	✓ 100. 118.00
Sundries.	✓ 150.00
Frnt Number plate	\$83.00 bt ✓
Total Labour 1:	7,868.00

DESCRIPTION	QTY	PRIC	VALUE
TAILPIPE TIP BLACK CHROME	1	118.65	mm ✓ 118.65
REAR SILENCER	1	908.05	bt ✓ 908.05
CLAMPING BUSH D=58MM	2	59.10	bt 59.10 3 118.20
BOOTLID	1	1,136.15	bt ✓ 1,136.15
SET MOUNTS PDC SENSOR REAR	1	58.60	new ✓ 58.60
SET MOUNTS PDC SENSOR REAR	1	58.60	✓ 58.60 mm
REAR BUMPER CARRIER	1	416.45	bt ✓ 416.45
REAR BUMPER CENTRE GUIDE	1	48.35	✓ 48.35 mm
LH SIDE GUIDE FOR BUMPER	1	49.05	? 49.05 mm
RH SIDE GUIDE FOR BUMPER	1	49.05	? 49.05 mm
REAR BUMPER TRIM STRIP (LINE SPORT)	1	90.50	Cca ✓ 90.50
REAR BUMPER PANEL PRIMED (BASIS)	1	1,018.95	side ✓ 1,018.95
RR FLAP TOWING EYE PRIMED	1	38.95	✓ 38.95 m



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : **b1 50224**
Date Estimated : **22/02/2019**
Prepared By : **Kevin Leong Wai Kit**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC500C	V885620	03/01/2017	218iA/2	0

DESCRIPTION	QTY	PRIC	VALUE
EMBLEM ADHERED REAR 218I	1	64.10	64.10
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
HEAT INSULATION REAR SILENCER REAR	1	59.75	59.75
TRUNK LID GASKET	1	125.45	125.45
LH REFLECTOR	1	36.80	36.80
RH REFLECTOR	1	36.80	36.80
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
ULTRASONIC SENSOR BLACK	2	236.85	473.70
(DG/SL) ADHESIVE SET K6	1	53.05	53.05

Total Parts : **5,052.15**

[Handwritten Signature]
14/3/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before entering painting
- To display damaged parts during resurvey
- Parts prices are subject to information
- Third party survey is on "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary work must be resurveyed and is subject to final approval from insurance Company

Ackno:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 11/3/19 0.1230 Excess \$S _____

Surveyor's Name Tan J M Sign [Signature]

Surveyor's Tel 97498744 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanjm@lkk.com.sg

No. of Working Days Recommend 6-7 days

1310515

Labour 1	:	7,868.00
Parts	:	5,052.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	904.41
Grand Total	:	13,824.56

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50224
Date Estimated : 22/02/2019
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Ang Wei Shan (Hong Weishan)
66 Marine Parade Road
#22-10

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 449300

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC500C	V885620	03/01/2017	218iA/2	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments include making good the front bumper and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, front bumper and boot lid	2665.00		2,665.00	
* To replace rear exhaust silencer include alignment of system and conducting checks for leak	451.00		451.00	
# To check electrical wiring systems and lightings at the front and rear section for proper function	250.00		250.00	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
# To supply front emboss number plate	83.00		83.00	(A) bt ✓
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR SILENCER	908.05	1.00		908.05
CLAMPING BUSH D=58MM	59.10	1.00		59.10
BOOTLID	1,136.15	1.00		1,136.15
SET MOUNTS PDC SENSOR REAR	58.60	1.00		58.60
# EXPANDING NUT *	1.00	2.00		2.00 (A) net ✓
REAR BUMPER CARRIER	416.45	1.00		416.45
REAR BUMPER TRIM STRIP (LINE SPORT)	90.50	1.00		90.50
REAR BUMPER PANEL PRIMED (LINES)	1,018.95	1.00		1,018.95
EMBLEM ADHERED REAR 218I	64.10	1.00		64.10
GROMMET	0.75	2.00		1.50
PLAQUE 74MM	71.25	1.00		71.25
TRUNK LID GASKET	125.45	1.00		125.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Page No. :

Estimate No. : b1 50224
Date Estimated : 22/02/2019
Prepared By : Kevin Leong Wai Kit

REPAIR FOR -
Ang Wei Shan (Hong Weishan)
66 Marine Parade Road
#22-10

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 449300

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC500C	V885620	03/01/2017	218iA/2	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To check electrical wiring systems and lightings at the front and rear section for proper function	250.00		250.00
# To supply front emboss number plate	83.00		83.00 BT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00 net

Total Labour :	333.00
Total Parts :	2.00
Total Labour & Parts :	335.00



FINAL REPORT

DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00	20.20
(DG/SL) ADHESIVE SET K6	53.05	1.00	53.05

SUPPLEMENTARY ITEMS

Total Labour :	6,700.00
Total Parts :	4,025.35
Total Labour & Parts :	10,725.35
Deduction for Excess :	0.00
Total Repair Costs less Excess:	10,725.35
GST @7%:	750.77
<u>Grand Total :</u>	<u>11,476.12</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003489/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-05-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2989Z	Veh. Inspected	SKC 500C
Policy No.		Coverage (\$)	0.00
Claim No.	D19001186MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	25/02/2019
2. Vehicle Particulars & Condition			
Make & Model	BMW 218I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA2F12000V885620	Colour	BLACK
Odometer	22714	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/02/2019	Inspection Date	11/03/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 500C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILPIPE TIP BLACK CHROME (SN)	NOT NECESSARY	118.65	-
1	REAR SILENCER (SN)	BENT	908.05	908.05
2	CLAMPING BUSH-D=58MM (SN)	BENT	118.20	59.10
1	BOOTLID (SN)	BENT	1,136.15	1,136.15
1	SET MOUNTS PDC SENSOR REAR (SN)	NECESSARY	58.60	58.60
1	SET MOUNTS PDC SENSOR REAR (SN)	NOT NECESSARY	58.60	-
1	REAR BUMPER CARRIER (SN)	BENT	416.45	416.45
1	REAR BUMPER CENTRE GUIDE (SN)	NOT NECESSARY	48.35	-
1	LH SIDE GUIDE FOR BUMPER (SN)	NOT NECESSARY	49.05	-
1	RH SIDE GUIDE FOR BUMPER (SN)	NOT NECESSARY	49.05	-
1	REAR BUMPER TRIM STRIP (LINE SPORT)(SN)	CRACKED	90.50	90.50
1	REAR BUMPER PANEL PRIMED (BASIS)(SN)	DEFORMED	1,018.95	1,018.95
1	RR FLAP TOWING EYE PRIMED (SN)	NOT NECESSARY	38.95	-
1	EMBLEM ADHERED REAR 218I (SN)	NECESSARY	64.10	64.10
2	GROMMET (SN)	NECESSARY	1.50	1.50
1	PLAQUE 74MM (SN)	NECESSARY	71.25	71.25
1	HEAT INSULATION REAR SILENCER REAR (SN)	NOT NECESSARY	59.75	-
1	TRUNK LID GASKET (SN)	NECESSARY	125.45	125.45
1	LH REFLECTOR (SN)	NOT NECESSARY	36.80	-
1	RH REFLECTOR (SN)	NOT NECESSARY	36.80	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	20.20	20.20
2	ULTRASONIC SENSOR BLACK (SN)	NOT NECESSARY	473.70	-
1	(DG/SL) ADHESIVE SET K6 (SN)	NECESSARY	53.05	53.05
1	FRONT EMBOSS NUMBER PLATE (ADDITIONAL)(SN)	BENT	83.00	83.00
2	EXPANDING NUT (ADDITIONAL)(SN)	NECESSARY	2.00	2.00
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
			5,287.15	4,258.35
LABOUR				
TO REPLACE REAR BUMPER, REAR BOOT, REINFORCEMENT & ALL ATTACHMENTS CAUSE BY ACCIDENT. TO REPAIR ON FRT BUMPER PANEL.			3,400.00	2,550.00

Report Ref No. CS/FCI19003489/T1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINTING ON REAR BUMPER, FRT BUMPER & REAR BOOT.		2,961.00	2,665.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.		531.00	451.00
	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION.		277.00	250.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		531.00	451.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) BOOT.		118.00	100.00
			7,818.00	6,467.00
	GRAND TOTAL		13,105.15	10,725.35
RECOMMENDED COST OF REPAIRS				10,725.35

Report Ref No. CS/FCI19003489/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.