

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
Reg No. 201629438M

India  
26/02/19 (Tue).  
LICK

10/02/2019

Owner: MKM CAR LEASING PTE LTD

## ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT6291P

|      |                                          |        |              |   |
|------|------------------------------------------|--------|--------------|---|
| 1pc  | rear LH door                             | Bz     | \$ 1,217.45  | ✓ |
| 2pcs | rear LH door hinge @\$141.45             | R      | \$ 282.90    | X |
| 1pc  | rear LH door frame sticker               | ru     | \$ 132.25    | ✓ |
| 1pc  | rear LH door glass motor & gear          |        | \$ 374.45    | ? |
| 1pc  | rear LH door glass pillar                |        | \$ 181.25    | ? |
| 1pc  | rear LH door inner lock                  |        | \$ 581.90    | ? |
| 1pc  | rear LH door inner rubber                | ru     | \$ 172.45    | X |
| 1pc  | rear LH door panel                       | ru     | \$ 621.25    | X |
| 1pc  | LH side skirt                            | CRM    | \$ 681.90    | ✓ |
| 1pc  | LH side air bag                          | Burn   | \$ 1,712.45  | ✓ |
| 1pc  | LH side air bag impact sensor            | ru     | \$ 381.90    | ✓ |
| 1pc  | rear LH fender                           | Bz     | \$ 971.50    | ✓ |
| 1pc  | rear LH fender air-duct                  | CRM    | \$ 178.85    | ✓ |
| 1pc  | rear LH fender inner shield              | CRM    | \$ 182.25    | ✓ |
| 8pcs | rear LH fender inner shield clip @\$5.00 | ru     | \$ 40.00     | ✓ |
| 1pc  | rear LH fender inner garnish             | Refurn | \$ 691.45    | ✓ |
| 1pc  | rear LH wheel house                      |        | \$ 561.60    | ? |
| 2pcs | rear sport rim @\$1218.10                | Refurn | \$ 2,436.20  | ✓ |
| 2pcs | rear adsorber @\$274.45                  |        | \$ 548.90    | ? |
| 2pcs | rear wheel bearing @\$561.60             | ru     | \$ 1,123.20  | ✓ |
| 2pcs | rear ABS sensor @\$381.85                |        | \$ 763.70    | ? |
| 1pc  | rear LH disc plate                       |        | \$ 531.35    | ? |
| 1pc  | rear LH brake caliper                    | ru     | \$ 371.85    | X |
| 1pc  | roof top trim                            | CRM    | \$ 1,715.45  | ✓ |
| 2pcs | rear taillamp @\$581.90                  | CRM    | \$ 1,163.80  | ✓ |
| 2pcs | rear taillamp lower bracket @\$172.10    |        | \$ 344.20    | ? |
| 1pc  | rear taillamp RH panel                   |        | \$ 377.45    | ? |
| 1pc  | rear tailgate                            | Bz     | \$ 1,518.45  | ✓ |
| 1pc  | rear tailgate "PRIUS" emblem             | ru     | \$ 61.10     | ✓ |
| 1pc  | rear tailgate "HYBRID" emblem            | ru     | \$ 63.90     | ✓ |
| 1pc  | rear tailgate inner lock                 | ru     | \$ 581.90    | X |
| 1pc  | rear tailgate inner rubber               | ru     | \$ 374.45    | X |
| 1pc  | rear tailgate inner garnish              |        | \$ 581.90    | ? |
| 1pc  | rear tailgate windscreen moulding        | ru     | \$ 175.45    | ✓ |
| 1pc  | rear bumper                              | Bz     | \$ 681.90    | ✓ |
| 2pcs | rear bumper side retainer @\$172.10      | CRM    | \$ 344.20    | ✓ |
| 2pcs | rear bumper side reflector @\$178.85     | 015?   | \$ 357.70    | ✓ |
|      | balance c/f                              |        | \$ 23,082.85 |   |

Not Authorized  
11 Lmp 8?  
Running After Paint  
12 days



# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/02/2019

Owner: MKM CAR LEASING PTE LTD

## ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT6291P

|      |                                      |    |                  |              |
|------|--------------------------------------|----|------------------|--------------|
|      | balance b/f                          |    |                  | \$ 23,082.85 |
| 1pc  | rear end panel                       | Pr | \$ 531.35        | X            |
| 1pc  | rear end panel inner garnish         | Pr | \$ 371.85        | X            |
| 1pc  | rear float panel garnish             | Pr | \$ 581.90        | X            |
| 1pc  | rear float panel LH side garnish     | Pr | \$ 381.25        | X            |
| 1pc  | air bag control unit                 |    | \$ 1,217.45      | ?            |
|      |                                      |    |                  | <hr/>        |
|      |                                      |    |                  | \$ 26,166.65 |
|      | less 25%                             |    |                  | \$ 6,541.66  |
|      |                                      |    |                  | <hr/>        |
|      |                                      |    |                  | \$ 19,624.99 |
| 1set | rear parking sensor                  |    | s.nett \$ 280.00 | ?            |
| 2pcs | rear tyre @\$160.00                  | Pr | s.nett \$ 320.00 | 608.00       |
|      | remove & refit rear cushios          |    | \$ 180.00        | 1200         |
|      | remove & refit rear undercarriage    |    | \$ 380.00        | 2800         |
|      | remove & refit petrol tank           |    | \$ 180.00        | 600          |
|      | remove & refix rear windscreen glass |    | \$ 150.00        | 1200         |
|      | remove & refit roof top tirm         |    | \$ 160.00        | 1000         |
|      | remove & refit air bag & reset       |    | \$ 320.00        | 2500         |
|      | reprogram ECU & Hybrid Battery       |    | \$ 380.00        | 2500         |
|      | towing                               |    | \$ 100.00        | ✓            |
|      | sealant                              |    | \$ 80.00         | 400.00       |
|      | tuffkote                             |    | \$ 120.00        | ✓            |
|      | wiring                               |    | \$ 120.00        | 800          |
|      | spray painting                       |    | \$ 1,600.00      | 12000        |
|      | labour charges                       |    | \$ 1,600.00      | 14000        |
|      | Total                                |    |                  | <hr/>        |
|      |                                      |    |                  | \$ 25,594.99 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

