

2/19/2019

ASS. REC. BY:

REF: CS/NOI 19003444/Eqd302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person):

Jenny Lee

of

NOI

Date/Time:

2/2/19

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 8992M

Insured:

SGL 2420L

at Workshop m/s

Progressive

Tel:

67415336

of

Blk 3022A Ubi Rd 1 #01-45/46

Policy No:

DHOM110094360909

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/2/19

CA / REV / REP. / REV 24 HRS

w/p

H.O.D. Endorsement:

Date/Time:

3:17pm 2/2/19

Person Contacted:

pei wee

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 8992M - NA / NOI 19003353 / K4
	SGL 2420L - NA / NOI 19003353 / K4
21/3/19 @ 1.36pm	confirmed with Ray from 1 leg 6470.20, 4 days.
	(Red 6402.90, 61%)
	no lump sum

D.O.A. 22/2/19

D.O.A. 22/2/19



MEMBER OF THE UOB GROUP

United Overseas Insurance Limited
3 Anson Road #28-01 Springleaf Tower
Singapore 079909
Tel (65) 6222 7733
Fax (65) 6327 3869 / 6327 3870
Email: ContactUs@uoi.com.sg
uoi.com.sg
Co. Reg. No. 197100152R

To :	Progressive Car Care Pte Ltd Attn. Lily Lim	Fax : 67417208
From :	Jenny Lew	Fax : 63273869
Date :	25.2.2019	Our ref: SGL2420L (DHOM110094360909) Yr ref : SKC8992M

FACSIMILE MESSAGE

WITHOUT PREJUDICE

REQUEST FOR PRE-REPAIR SURVEY – SKC8992M
ACCIDENT INVOLVING SGL2420L AND SKC8992M ON 22.2.2019

We refer to your email dated 25.2.2019.

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case you have proposed to appoint M/s LKK Auto Consultants Pte Ltd from our list, to conduct the pre-repair survey on without prejudice basis.

Please seek your client's instruction for the repair after the inspection has been completed.

We reserve all our rights in this matter.

Thank you.

Regards

Jenny Lew
Claims Dept

cc. LKK Auto Consultants Pte Ltd
Fax: 62564315
Attn : Shiau Chan

For your immediate attention.

/fy

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 21 March 2019 1:36 PM
To: 'Ray'
Subject: RE: FINALISE OF VEHICLE SKC 8992M (UOI-TP DOA: 22/02/2019) & SFX 66M (AXA-OD DOA: 22/02/2019)

Dear Ray,

WITHOUT PREJUDICE

Confirm final fig \$4,170.20 before GST and 4 repair days.

Kindly send the relevant documents to UOI Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>
Sent: Wednesday, 20 March 2019 5:34 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: FINALISE OF VEHICLE SKC 8992M (UOI-TP DOA: 22/02/2019) & SFX 66M (AXA-OD DOA: 22/02/2019)

Hi Shiau Chan,

As your per require, please refer to finalize

Parts	\$2770.20
Lab	\$1400.00
Total	\$4170.20

Regards,

Ray LIN

Damage Assessment

Progressive Automotive Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses (@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, March 20, 2019 5:12 PM

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2704B
Vehicle Details	
Vehicle No.:	SKC8992M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA250 (R18 BI)
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	27092030511475
Chassis No.:	WDC1569442J061445
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$33,853.00
Original Registration Date:	02 Apr 2015
First Registration Date:	02 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$34,395.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Apr 2025
PARF Rebate Amount:	\$25,796.00
Intended COE Rebate Details	
COE Expiry Date:	01 Apr 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,790.00
COE Rebate Amount:	\$46,859.00
Total Rebate Amount:	\$72,655.00

The information contained herein is correct as at 25 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/02/2019 09:42
Date Of Accident	22/02/2019 09:00
Exact Location Of Accident	EUNOS LINK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKC8992M
Insured/Policyholder	
Name Of Registered Owner	LIM XU WEN
NRIC No	S8502704B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98215352
Alternative Phone No	OTHERS-98215352
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	GLA250 (R18 BI)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100407059-03
Cover Note Number	
Driver	
Name of Driver	LIM XU WEN
NRIC No	S8502704B
Date Of Birth	12/01/1985
Occupation	INDOOR
Date Of Driving Pass	23/03/2005
Driving Experience	13 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98215352
Fax Number	
Contact Number	OTHERS-98215352
EMail Address	NOEMAIL

Address	90 PUNGGOL DRIVE #09-04 SINGAPORE
Postcode	828794
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL2420L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes.
- (c) my Personal Information may/can be disclosed by any of the Insurers' Insurer(s) to their third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Vehicle
 A - SKC 8992 M
 B - SGL 2420 L

Legend
 Vehicle: Motorcycle:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Traffic was heavy and I was stationary in my lane.

Suddenly, vehicle B hit the rear of my vehicle. I have in-car camera footage for front and back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Progressive Car Care Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s)
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

ATTN: UOI

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

4 days

P/P

Reg bel & Alr

Estimate No: EST1504601

Date: 22 Feb 2019

Policy No: 2100407059-03

Veh Reg No: SKC8992M

Make/Model: MERCEDES BEN
GLA250 (R18 BI)

Chassis No: WDC1569442J061445

Engine No: 27092030511475

Reg. Date: 02/04/2015

Your Ref No: TP 0219-5412

Claim Type: Third Party

Accident Date: 22/02/2019

TP Veh Reg No: SGL 2420 L

Estimate Repair Cost to Vehicle No :SKC8992M

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER / 00	1,151.00	1 PC	1,151.00	
2 REAR BUMPER LOWER CHROME / CR4 DE	838.00	1 PC	838.00	
3 REAR BUMPER LOWER / CUT	445.00	1 PC	445.00	
4 REAR BUMPER INNER FRAME ?	53.00	1 PC	53.00	x hn
5 REAR BUMPER SIDE HOLDER - LH / BR	60.00	1 PC	60.00	
6 REAR BUMPER SIDE HOLDER - RH / BR	60.00	1 PC	60.00	
7 REAR BUMPER CLIPS / NEC	7.00	10 PC	70.00	39
8 REAR BUMPER REINFORCEMENT ?	600.00	1 PC	600.00	x an
9 REAR BUMPER TOP CHROME / CRA	161.00	1 PC	161.00	CRA
10 REAR BUMPER SENSOR ?	183.00	2 PC	1,098.00	x an
11 REAR BUMPER SENSOR WIRE X	99.00	1 PC	99.00	x an
12 REAR BUMPER TOWING COVER - RH X	60.00	1 PC	60.00	DE
13 REAR BOOT / 00	1,941.00	1 PC	1,941.00	1767 / XR
14 REAR BOOT GLASS MOULDING / NEC	0.00	1 SET	0.00	x R
15 REAR BOOT MER LOGO / NEC	50.00	1 PC	50.00	
16 REAR BOOT GLA 250 WORDING / NEC	87.00	1 PC	87.00	
17 REAR BOOT OUTER CHROME X	146.00	1 PC	146.00	x an
18 REAR EXHAUST PIPE X	1,291.00	1 PC	1,291.00	x an
19 REAR EXHAUST PIPE TOP PLATE / 00	136.00	1 PC	136.00	
20 REAR PANEL X R	925.00	1 PC	925.00	x R
21 REAR PANEL TOP GARNISH X AN	88.00	1 PC	88.00	x
			9,359.00	
		Less 10%	935.90	8,423.10
Labour				
22 TO KNOCK OUT DENTS ON REAR PANEL, REAR BOOT, CUT/WELD & REPLACE ACCIDENT PARTS	700.00	1 JOB	700.00	500
23 TO RESPRAY PAINT ON ACCIDENT PORTIONS - SP	800.00	1 JOB	800.00	650
24 TO CHECK WIRING	50.00	1 JOB	50.00	
25 TO REMOVE, REFIX END PANEL GARNISH TO FACILITATE REPAIRS	80.00	1 JOB	80.00	3050
26 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.00	1 JOB	100.00	30
27 TO REMOVE, REPAIR REAR EXHAUST PIPE	100.00	1 JOB	100.00	80
28 TO RESET CHECK LIGHT	200.00	1 JOB	200.00	? x
29 TO TUFF-KOTE	120.00	1 JOB	120.00	40
			2,150.00	2,150.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : LIM XU WEN
90 PUNGGOL DRIVE #09-04
SINGAPORE 828794

ATTN: UOI

Your Ref No: TP 0219-5412
Claim Type: Third Party
Accident Date: 22/02/2019
TP Veh Reg No: SGL 2420 L

Estimate No: EST1504601
Date: 22 Feb 2019
Policy No: 2100407059-03
Veh Reg No: SKC8992M
Make/Model: MERCEDES BEN
GLA250 (R18 BI)
Chassis No: WDC1569442J061445
Engine No: 27092030511475
Reg. Date: 02/04/2015

Estimate Repair Cost to Vehicle No :SKC8992M

Description	U/Price	Quantity	Price SS	Amount SS
			Total	S\$ 10,573.10
			Add GST @ 7%	740.12
			Total Amount Payable	S\$ 11,313.22

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED THIRTEEN AND CENTS TWENTY TWO ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

Steve (LKJ) w/L prp/ia 25/2/19 5:45 pm
8322 8813 4 chys
P/P
Ry bef & Alr
Spring

PAP. 2770.20

W/B 1400.00

4170.20

M/S: LIM XU WEN
90 PUNGGOL DRIVE #09-04
SINGAPORE 828794

Estimate No: EST1504601
Date: 22 Feb 2019
Policy No: 2100407059-03
Veh Reg No: SKC8992M
Make/Model: MERCEDES BEN
GLA250 (R18 BI)
Chassis No: WDC1569442J061445
Engine No: 27092030511475
Reg. Date: 02/04/2015

ATTN: UOI

Your Ref No: TP 0219-5412
Claim Type: Third Party
Accident Date: 22/02/2019
TP Veh Reg No: SGL 2420 L

Estimate Repair Cost to Vehicle No :SKC8992M

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER / 00	1,151.00	1 PC	1,151.00 ✓	
2 REAR BUMPER LOWER CHROME / CR4	838.00	1 PC	838.00 ✓	
3 REAR BUMPER LOWER / CUT	445.00	1 PC	445.00 ✓	
4 REAR BUMPER INNER FRAME / X	53.00	1 PC	53.00 ✓	
✓5 REAR BUMPER SIDE HOLDER - LH / CR	60.00	1 PC	60.00 ✓	
✓6 REAR BUMPER SIDE HOLDER - RH / BR	60.00	1 PC	60.00 ✓	
7 REAR BUMPER CLIPS / NEC	7.00	10 PC	70.00 ✓	
8 REAR BUMPER REINFORCEMENT / X	600.00	1 PC	600.00 ✓	
9 REAR BUMPER TOP CHROME / CRA	161.00	1 PC	161.00 ✓	
10 REAR BUMPER SENSOR / CR	182.00	2 PC	1,098.00	366 ✓
11 REAR BUMPER SENSOR WIRE / X	99.00	1 PC	99.00 ✓	
✓12 REAR BUMPER TOWING COVER - RH / CR4	60.00	1 PC	60.00 ✓	
13 REAR BOOT / R	1,941.00	1 PC	1,941.00 ✓	
14 REAR BOOT GLASS MOULDING / NEC	0.00	1 SET	0.00 ✓	
15 REAR BOOT MER LOGO / NEC	50.00	1 PC	50.00 ✓	
16 REAR BOOT GLA 250 WORDING / NEC	87.00	1 PC	87.00 ✓	
17 REAR BOOT OUTER CHROME / NN	146.00	1 PC	146.00 ✓	
18 REAR EXHAUST PIPE / NAI	1,291.00	1 PC	1,291.00 ✓	
19 REAR EXHAUST PIPE TOP PLATE / 00	136.00	1 PC	136.00 ✓	
20 REAR PANEL / X R	925.00	1 PC	925.00 ✓	
21 REAR PANEL TOP GARNISH / X NN	88.00	1 PC	88.00 ✓	
			9,359.00 2078	
	Less 10%		935.90	8,423.10
Labour				
22 TO KNOCK OUT DENTS ON REAR PANEL, REAR BOOT, CUT/WELD & REPLACE ACCIDENT PARTS	700.00	1 JOB	700.00 500 ✓	
23 TO RESPRAY PAINT ON ACCIDENT PORTIONS - SP	800.00	1 JOB	800.00 650 ✓	
24 TO CHECK WIRING	50.00	1 JOB	50.00 ✓	
25 TO REMOVE, REFIX END PANEL GARNISH TO FACILITATE REPAIRS	80.00	1 JOB	80.00 30 50 ✓	
26 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.00	1 JOB	100.00 30 ✓	
27 TO REMOVE, REPAIR REAR EXHAUST PIPE	100.00	1 JOB	100.00 80 ✓	
28 TO RESET CHECK LIGHT	200.00	1 JOB	200.00 ? ✓	
29 TO TUFF-KOTE	120.00	1 JOB	120.00 40 ✓	
			2,150.00	2,150.00
				1400



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI19003494/Eqd3e2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 26-03-2019	
			Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGL 2420L	Veh. Inspected	SKC 8992M	
Policy No.	DHOM110094360909	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	25/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLA250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDC1569442J061445	Colour	GREY	
Odometer	58305	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/80 R18	CONTINENTAL	7 mm	
L/H Front Tyre	235/80 R18	CONTINENTAL	7 mm	
R/H Rear Tyre	235/80 R18	CONTINENTAL	7 mm	
L/H Rear Tyre	235/80 R18	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/02/2019	Inspection Date	25/02/2019	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 8992M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,151.00	1,151.00
1	REAR BUMPER LOWER CHROME	DEFORMED	838.00	838.00
1	REAR BUMPER LOWER	CUT	445.00	445.00
1	REAR BUMPER INNER FRAME	NOT NECESSARY	53.00	-
1	REAR BUMPER SIDE HOLDER - LH	BROKEN	60.00	60.00
1	REAR BUMPER SIDE HOLDER - RH	BROKEN	60.00	60.00
10	REAR BUMPER CLIPS @\$7.00	NECESSARY	70.00	30.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	600.00	-
1	REAR BUMPER TOP CHROME	CRACKED	161.00	161.00
6	REAR BUMPER SENSOR @\$183.00	NOT NECESSARY	1,098.00	-
1	REAR BUMPER SENSOR WIRE	NOT NECESSARY	99.00	-
1	REAR BUMPER TOWING COVER - RH	DEFORMED	60.00	60.00
1	REAR BOOT	TO REPAIR SEE LABOUR	1,941.00	-
1	SET REAR BOOT GLASS MOULDING (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT MER LOGO	NECESSARY	50.00	50.00
1	REAR BOOT GLA 250 WORDING	NECESSARY	87.00	87.00
1	REAR BOOT OUTER CHROME	NOT NECESSARY	146.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	1,291.00	-
1	REAR EXHAUST PIPE TOP PLATE	DENTED	136.00	136.00
1	REAR PANEL	TO REPAIR SEE LABOUR	925.00	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	88.00	-
	LESS 10% DISCOUNT		-935.90	-307.80
			8,423.10	2,770.20
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS ON REAR PANEL, REAR BOOT, CUT/WELD & REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT, SET REAR BOOT GLASS MOULDING AND REAR PANEL.		700.00	500.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS - SP.		800.00	650.00
	TO CHECK WIRING.		50.00	50.00
	TO REMOVE, REFIX END PANEL GARNISH TO FACILITATE REPAIRS.		80.00	50.00
	TO REMOVE, REPLACE REAR BUMPER SENSOR.		100.00	30.00

Report Ref No. CS/UOI19003494/Eqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPAIR REAR EXHAUST PIPE.	NOT NECESSARY	100.00	80.00
	TO RESET CHECK LIGHT.		200.00	-
	TO TUFF-KOTE.		120.00	40.00
			2,150.00	1,400.00
GRAND TOTAL			10,573.10	4,170.20
RECOMMENDED COST OF REPAIRS				4,170.20

Report Ref No. CS/UOI19003494/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.