an Anthorn	Phale Man	SSIGNMENT (Office)		
Estimated (0 1100 /110	AIG	Lude/Time 25/2/1918	12.36pm
OD(11)	VS/TP RES/OD RES/EVA/E	Bill to:		1
To inspect	Chiefe No. SFV 19	- 411	Insured: \$16,4728	
at Workshop	m/s Demick	Motor	Tal 96223602	
of	3/K 9002, tonoin	48 st-03 # 01-73	2 Turping Ind. Par	In
Policy No:_	2100482856	Claim No:	162457679986	. 11
Sum Insured		Excess	10011011611130	
Make of Vel (Client's Reco		BACCOS.	D.O.A. 21/02/19	
CA / REV	/ REP. / REV 24 HRS			
Date/Time:	1.41pm@ 28/2/19 Person (Contacted: Jerumy	H.O.D. Endorsement:	
Date/Time	Action/Instruction (X)	stimate		
	SEVISAL- NBA/N	18617024477/1	DOA: 08/2	In
	SJ G 4725-CS/SM	16 10/0033-70/Und	3 AUA: 0/12/19	U.J
	Dismantle: 27 2/2019			

Surveyor REF: AIG	
	GNMENT
From: Date: 25/2/P) Estimated Cost: OD (TR) WS (TR PES / OD PES / EVA / INV / MV	Veh No: SFV1541 L Yr Regn: 2015 / Type(M.Ca) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	MANUAL MANUAL CONTROL
To Inspect Vehicle No: SFV 1541 L	
at Workshop m/s Devrick Notor Works	Diack
of BUR 9002 401-72 Tempires ST 93	10111
Insured:	Eng/No: 278/526444
Policy No.	C/No: JTD6620WX0J002312
Claims No.	Gen. Cond: Good (Fair) / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 195/65 R15 914
(Policy Condition)	R: 195/65 R15 91H
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO KYOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 21/02/2019 D.O.I. 25/2/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Derrick Motor works
CA / REV / REP. / 24 HRS	Des. of Damages Frt Rear O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
RECE	IVED 1-0 APR 2019
111/1/12/12/12	
	Tacin line
	5/4/19
	Days Of Repair:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 180
Add Eco	P
2) Add Fee	: Interview (\$) Photos
Panert Format : Dan	: Tech, Invs (\$) Others t0
Report Format: DAR	
Lump Sum / I.B.I: (\$:Weekend (\$)
8.00	TOTAL (90

*- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG472S AND SFV1541L ON 21/02/2...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, admin-a@lkkauto.com

Cc: Fong, Andy-SY Sent: 25/2/2019 12:36:01 PM

HI LKK.

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying Chin@aig.com | www.aig.sg

From: elainetoh@visionlawllc.com [mailto:elainetoh@visionlawllc.com]

Sent: Monday, February 25, 2019 11:53 AM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; elainetoh@visionlawlic.com

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG472S AND SFV1541L ON 21/02/2019

Our Ref: SFV 1541 L (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Messrs Derrick Motor Works

Blk 9002 Tampines St 93

#01-72, Tampines Ind Park A

Singapore 528836

Attention: Mr Jeromy - HP 9633 3593

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor

(Name & Signature)

Regards, Elaine Toh Vision Law LLC Tel: 65342811 (Ext. 122) Fax: 65356802

cc:

SFV 1541 L - By email only

From: Hor, Yinrul

Sent: Mon, 25 Feb 2019 02:46:47 +0000

To: elainetoh@visionlawllc.com

Ce: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh,

Aashweenjeetkaur

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG472S AND SFV1541L ON 21/02/2019

Without Prejudice

Your Reference

: SFV 1541 L (et)

Our Reference

: SLG472S

Dear Sir/Madam,

We refer to your email below. We disagree with the list of your nominated surveyors.

Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our in house surveyor for the pre-repair inspection. Kindly provide us with details of repairer's contact number and address.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto Shared Services – Malaysia | Global Business Services

Yinnii Hor@aig.com | www.aig.ag

From: elainetoh@visionlawllc.com [mailto:elainetoh@visionlawllc.com]

Sent: Monday, February 25, 2019 9:59 AM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; elainetoh@visionlawlic.com

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG472S AND SFV1541L ON 21/02/2019

Our Ref: SFV 1541 L (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we are instructed to object to all your surveyors stated in your said List for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyors for your consideration:

1. Dennis Yap - PAL's Appraiser Pte Ltd

Please reply within 2 working days.

Regards, Elaine Toh Vision Law LLC Tel: 65342811 (Ext. 122) Fax: 65356802

cc: S

SFV 1541 L - By email only

From: Hor, Yinrul

Sent: Mon, 25 Feb 2019 01:34:46 +0000

To: Elaine Toh

Ce: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh,

Aashweenjeetkaur

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG472S AND SFV1541L ON 21/02/2019

Without Prejudice

Your Reference

: SFV 1541 L (et)

Our Reference

: SLG472S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto Shared Services – Malaysia | Global Business Services

Yinna HonRaig.com | www.aig.ag

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Friday, February 22, 2019 4:30 PM

To: Mithoosingh, Aashweenjeetkaur

Cc: 'Llly.Tan@aig.com'; 'Andy-SY.Fong@aig.com'; 'Baljit.Kaur@aig.com'; 'Lee-Ying.Chin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShangYasa Lin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShangYasa Lin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShangYasa Lin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShangYasa Lin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'NoorMariesa.AbuKassim@aig.com

'ShengYang.Lim@aig.com'; 'Darshene.Supramaniam@aig.com'; 'Syazairdina.Azlan@aig.com'; 'yokeshi.chan@aig.com'

Subject: PRE REPAIR INSPECTION --- ACCIDENT INVOLVING SFV 1541 L (#2) AND SLG 472 S (#3) AND GBD 7806 B (#4) AND SHD 1462 C (#1) ON 21 FEBRUARY 2019 ALONG UPPER CHANGI ROAD EAST TOWARDS BEDOK AT ABOUT 1710 HOURS

Importance: High

Our Ref: SFV 1541 L (et)

WITHOUT PREJUDICE

Dear Sir/Madam

We are instructed by UE-TAY SZE YIN to notify you of a road traffic accident on 21 February 2019 at about 1710 hours along Upper Changi Road East towards Bedok involving our client's vehicle registration number SFV 1541 Land vehicle registration number SLG 472 S driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards, Elaine Toh Vision Law LLC Tel: 65342811 (Ext. 122) Fax: 65356802

SFV 1541 L - By email only

VISION LAW LLC Advocates & Solicitors

(Incorporated with limited liability) Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413 Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information, if you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	2140A
Vehicle No.:	SFV1541L
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2ZR1526444
Chassis No.:	JTDGG20WX0J002312
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$23,454.00
Original Registration Date:	24 Apr 2015
First Registration Date:	24 Apr 2015
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$19,836.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2025
PARF Rebate Amount: Intended COE Rebate Details	\$14,877.00
COE Expiry Date:	23 Apr 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,889.00
COE Rebate Amount:	\$43,669.00
Total Rebate Amount:	\$58,546.00

The information contained herein is correct as at 27 Mar 2019

OK

Aug dep 10,300/g/ 858/14/1

> MV 69,600|= PV 58,546|= NV 10,454|>

> > TG UM 574/19



Toyota Wish 1.8A X - N.A 13-May-2015 1,797 cc - MPV SOLD

1 Owner Only, Best Fuel Consumption, Most Ideal For Family, Rare Opportunity, Good Condition, Strictly Viewing By Appointment Only.

360 VR Cars

Posted: 06-Mar-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A Elegance - N.A 03-Mar-2015 1,798 cc - MPV SOLD

Borneo Motors Unit With 5 Years Warranty Fully Maintain By Borneo With Service Record. High Paper Value, 100% Accident Free, Flexible High Loan Available, Bank Loan Up To 80%. Original Tip Top Conditi...

Posted: 21-Jan-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Wish, Used Toyota



Toyota Wish 1.8A Elegance \$69,800 \$10,150 /yr 27-Feb-2015 1,798 cc 91,431 km MPV Available

Single Owner "Elegance" Model With Full Agent Service! 100% Accident-Free. Beautiful Silver Paintwork, Most Popular Japan MPV In The Market, Ultra Reliable And Fuel Saving, Immaculate Condition, Buy W...

Posted: 19-Mar-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home, Roadside assistance & claims support completely free.

Find out more!



Toyota Wish 1.8A Elegance - N.A 09-Feb-2015 1,798 cc - MPV SOLD

1 Owner Borneo Unit! Original Paint Work And Interior! Borneo Built In Audio Set With GPS And Bluetooth! Well Maintained! Down To Earth Yet Lowest Petrol Consumption Toyota 7 Seters MPV! Come View And...

Posted: 08-Feb-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A \$71,800 \$10,630 /yr 29-Jan-2015 1,798 cc 66,000 km MPV Available

Excellent Unit Almost New, Uniquely Agent Colour Unit, (High OMV), 1 Owner Only, Full Agent Service Since Day 1, Low Mileage, (Proved Of Pictures), Clean And Beautiful Interior, Fuel Economical Stylis...

Posted: 16-Mar-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota Wish, Wish, Wish, Used Toyota



Toyota Wish 1.8A - N.A 21-Jan-2015 1,798 cc - MPV SOLD

Cheapest In Market Low Mileage Most Popular Family Mpv! Ultra Reliable And Fuel Saving! Agent Unit, High Arf. Single Owner And Well Maintained Unit! Loan And Trade In Packages Available! Come View And...

AL Autocar Pte Ltd

Posted: 05-Mar-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



For old advertisements, view Expired ads

Toyota Wish 1.8A \$74,800 \$11,290 /yr 02-Jan-2015 1,798 cc - MPV Available

Agent Unit!Most Popular MPV In The Market, Excellent Fuel Consumption, Fully Maintained By Borneo Motor, Trade In Welcome, Price Negotiable, Call/Sms/Whatsapp Us Now Before It Is Gone!

Posted: 27-Mar-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

« Back (12) Next »

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota, Toyota Singapore, used Toyota, used Vehicles Singapore or even buy used Toyota Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

Home New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

PERMITTED IN

20 ▼ results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

- 4		\sim	n	- 1		ι Δ	$\mathbf{n} = \mathbf{n}$	/IEN I
•	O	9		_				

 Date Of Report
 22/02/2019 12:59

 Date Of Accident
 21/02/2019 17:10

Exact Location Of Accident UPPER CHANGI ROAD EAST TWDS BEDOK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFV1541L

Insured/Policyholder

Name Of Registered Owner UE-TAY SZE YIN NRIC No S7522140A

Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-96199806

 Alternative Phone No
 OTHERS-96199806

Vehicle Particulars

Manufacturer TOYOTA

Model WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AVIVA LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 10818411

Cover Note Number

Driver

Name of Driver UE-TAY SZE YIN

 NRIC No
 \$7522140A

 Date Of Birth
 09/08/1975

 Occupation
 INDOOR

 Date Of Driving Pass
 30/03/1999

Driving Experience 19 YEARS AND 10 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96199806

Fax Number

Contact Number OTHERS-96199806

EMail Address NOEMAIL

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHD1462C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBD7806B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN A SFV |541L. B. SLG 4728. C'SHD 1462C D GBO 7806B. RUS Upper Changi Rolfost tageds Bedolf DESCRIBE CIRCUMSTANCES OF THE ACCIDENT -dleft 1/20190221/7022 1/0: report DECLARATION I/We declare the foregoing particulars are true in every respect. Driver's Signature Reporting Centre Personnel's Signature Policyholder's Signature

(If driver is not the policyholder)

NRIC/FIN No.:

Date & Time:

Date & Time:

	INC		CO	V A	0
1001	99188	6 Frt Number Plate	81	1	7
1002	99188	7 Frt Number Plate Base .	01	1	+
1003	99188	9 Frt Number Plate Garnish	-	-	+
1004	99130	0 Frt Bumper	17.6	17	+
1005	99234	1 Frt Bumper Clips	NE	10	+
1006	99132	5 Frt Bumper Bracket	- IV s	40	-
1007	99146	2 Frt Bumper Side Retainer	1150	1.	+
1008	99143	Frt Bumper Reinforcement	NEG		_
1009	99131	8 Frt Bumper Beam	00	1	1
1010	99146	8 Frt Bumper Sponge	-		
1011	00142	7 Frt Bumper Protector	BR	V	
1017	00142	Fit Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	99130.	Frt Bumper Grille	QL	W	
1014	99130	Frt Bumper Moulding			
1015	99140	Frt Bumper Lower Spoiler			
1016	1991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	P.R	1.7	-
1018	1991353	Frt RH Bumper Fog Lamp Cover	60	1	-
1019	1995079	Frt LH Bumper Fog Lamp	Bio	V	-
1020	995080	Frt RH Bumper Fog Lamp	00	-	-
1021	991793	Frt Grille	DA	N	-
1022	991328	Frt Grille Emblem	W	V	_
1023	991799	Frt Grille Chrome Moulding	-		
1024	991222	Frt Apron Panel	1		
1025	992013	Frt Support Panel	-		
1026	002025	E-t Support Panel	DD	R	
1027	992416	Frt Support Panel Top Garnish Cover			
1027	001277	Frt Brace Panel			
1020	005157	Frt Brace Panel	05		
1029	993133	Frt LH Headlamp Assy	BK	V	
1030	991821	Frt RH Headlamp Assy	BR	V	
1031	995088	Fr: LH Side Lamp			
1032	995089	Fri RH Side Lamp			
1033	990248	Bonnet	RT	0/	_
1034	991328	Bonnet Emblem	NEA	1	_
1035	990287	Bonnet Lock	MEN	٧.	_
1036	990285	Bonnet Insulator			-
1037	990273	Bonnet Hinge			-
1038	990261	Bonnet Damper		-	-
1039	990305	Bonnet Rubber		-	
1040	990252	Bonnet Cable	_	-	_
1041	990311	Bonnet Stand		-	
042	990119	Air Con Condenser		_	
043	990122	Air Con Fan Assy			
044	990134	Air Con Part Assy	-		
045	990114	Air Con Suction Pipe (Low Pressure)	-1		
046		Air Con Suction Hose			
047	100114	Air Con Discharge Pipe (High Pressure)			
045	000140	Air Con Discharge Hose			
	00000	Air Con Liquid Pipe		1	∇
()49	995066	Air Con Receiver Drier	MA	60	X
050	990111	Air Con Compressor Assy	XIVY	01	11
051	995294	Air Con Belt	11 }	1	+1
052	995074	Radiator	11	7	
053	992738	Radiator Cowling	V	-	-
0.54	992742	Radiator Fan Assy	10	10	2
055	992745	Radiator Fan Clutch	4+1	1	-
056	992758	Radiator Hose Top	-	1	_
057	992757	Radiator Hose Bottom		_	
058	992741	Radiator Expansion Tank			
-	990151	Air Duot			
-	000070	AL CI			
060	990070	Air Cleaner Assy .	_		-
061	990056	Air Cleaner Hose		-	-
)62	990089	Air Cleaner Resonator	-	-	-
)63 9	991712 F	rt Exhaust Manifold	-	+	-
064	91713 1	rt Exhaust Manifold Cover		- -	-
05 9	91054	rt Exhaust Manifold Sensor (Oxygen)			
	91714 6	ront Exhaust Pipe			_
67 5	90219 E	Authors		-	_
		Battery Cover			
	2014Z4 10	autery Cover		1	1
69 9	00222	aftery Bracket			٠

		0	Vehicle No: SFV	1541	1
	NAC		Item		MACQ
-	1071	99220			
-	1072	9940	1 Relay Box		
_	1073 1074		Wiper Washer Tank		
_	1075		Wiper Washer Tank Motor Alternator Assy	_	-
_	1076	99016	Alternator Belt	-	-
	1077		8 Power Steering Pump	-	-
	1078	99266	9 Power Steering Belt	+	-
	1079	99443	1 Power Steering Cooler Pipe	-	++
_	1080	99269	2 Power Steering Hose	-	\vdash
	1081	99001	0 ABS Pump Control Unit	1	+
-	1082	99042	7 Brake Master Pump Assy		\vdash
-	1083	99040	3 Brake Booster Pump Assy		\vdash
_	1084	99100	5 Engine Top Cover		
-	1085	99101	1 Engine Under Cover		
-	1086	-99094	6 Engine Mounting		
	088	99094	9 Engine Mounting Frt		
-	089	99093	0 Engine Mounting LH		
-	090	99093	2 Engine Mounting RH 1 Engine Mounting Rear	-	
-		99223	4 Gear Box Mounting	-	
1	092	99152	O Frt LH Chassis Member	-	-
1	093.	991520	Frt RH Chassis Member	_	
- 1	094	99072	Frt Vertical Cross Member	1	
_	095	991863	Frt Lower Cross Member		
_	096	995070	Frt LH Fender		
_	097	995077	Frt LH Fender Inner Panel		
-	098	995147	7: Frt LH Fender Lamp		
	099 100	995148	Frt LH Fender Protector		
_		991740	Frt LH Fender Inner Shield Frt LH Mudflap	-	
_	102	995170	Frt LH Wheel Rim		_
_	103	994025	Frt LH Rim Cover	1	-
1	104	995065	Frt LH Tyre		
	105	995071	Frt RH Fender		
	106	991739	Frt RH Fender Inner Panel		\neg
_	107	991744	Frt RH Fender Lamp		
	108	991752	Frt RH Fender Protector	5	
_	109	991740	Frt RH Fender Inner Shield	15.	
	110	991884	Frt RH Mudflap		
	112	992087	Frt RH Wheel Rim - Frt RH Rim Cover		
		995065	Frt RH Tyre	-	-
_	14	992093	Frt Windscreen Glass		-
11	15	992117,	Frt Windscreen Rubber	-	-
11	16	992108	Frt Windscreen Moulding		_
	17	992098	Frt Windscreen Sealant		
_			ERP Bracket		
			ERP Unit		
	20	992140	Frt Wiper Arm		
	21	005046	Frt Wiper Blade		
		001126	Wiper Panel Garnish		
_		000757	Firewall Panel Dashboard Assy		
	25	992282	Glove Box Cover	-	-
			Glove Box Compartment		
		994483	Steering Wheel Airbag		+
	28	994485	Steering Wheel Airbag Sensor		
	29 9	990749	Dashboard Airbag		+-i
113			Dashboard Airbag Sensor	+	-
11:	31 9	90029	Airbag Control Unit		\dashv
113	32 5	90864	Frt Driver Seat		
11:	33 9	91922	Frt RH Seat Belt Assy		
113	34 9	91899	Frt Passenger Seat		1
113	35 9	95182	Frt LH Seat Belt Assy.		
113	36 9	90247	Sticker ·		
	_				
	_				
			7		

No of Items:

ASTRESOF: TOUG

lin 574/19

MOTORCAR (Rear)

(1)Replace (/) (2)Repekt() (3)Chock ()
(4)Not Consistent (1C)

Velsicle	No:

Rear P		(12)Unconfirmed (15)Not Working			
NAC	INC	Item	CON	AC	Oty
1137	993626	Rear Number Plate	D.T	V	4.7
11'3'8	993627	Rear Number Plate Base	121	_	_
1139	993630	Rear Number Plate Garnish	SD.	V	_
1140	993632	Reaf Number Plate Lamp			
1141	992958	Rear Bumper	DD	./	_
1142	993085	Rear Bumper Upper	1		
1143	993017	Rear Bumper Lower	1.		
1144	993054	Rear Bumper Side	1		
1145	993103	Rear Bumper Tow Cover	1	-	-
1146	992341	Rear Bumper Clips	NEO	7	-
1147	992976	Rear Bumper Bracket	NE	~	-
1148	003060	Para Bumper Blacker	112.2	-	_
	993045	Rear Bumper Side Retainer Rear Bumper Reinforcement	NEC	V	-
1150	992970	Rear Bumper Beam	-	_	_
1151	993077	Rear Bumper Sponge	-	 _	_
1152	992999	Rear Bumper Damper	-	-	_
1153	993040	Rear Bumper Protector	-	-	-
1154	993036	Rear Bumper Pad	1	-	-
1155	993036	Rear Bumper Moulding	-	-	_
1156	993044	Pear Pumper P. G.	-	-	_
1157	002022	Rear Bumper Reflector	CAG	V	2
1158	904022	Rear Bumper Lower Spoiler Reverse Sensor	-	<u>_</u>	_
	993327	Reverse Sensor Rear End Panel	DL	V	-
		Rear End Panel Top Garnish	-	-	-
1161	993333	Rear End Panel Inner Trim	-	-	-
1162	990333	Boot Compartment Inner Trim	-	-	-
1163	993851	Rear LH Taillamp	-	\vdash	-
1164	993853	Rear LH Taillamp Garnish	-	+-	-
1165	993859	Rear LH Taillamp Panel	+-	-	-
1166	995116	Rear RH Taillamp	-	-	-
1167	993853	Rear RH Taillamp Garnish	-	1	-
1168	993859	Rear RH Taillamp Panel	-	-	-
1169	993554	Rear Apron Panel	-	-	-
1170	992895	Bootlid	1	-	-
1171	991328	Bootlid Emblem	-	+	\vdash
1172	990356	Bootlid Handle	-	-	\vdash
1173	995250	Bootlid Moulding	-	-	-
1174	990376	Bootlid Reflector	-	1	╌
1175	995222	Bootlid Lamp LH	-	\vdash	╌
1176	992899	Bootlid Lamp RH	-	-	-
1177	995243	Bootlid Lock	-	+	1
1178	990377	Bootlid Rubber	-	1	1
1179	990382	Bootlid Hinge	1	1	1
1180	993877	Bootlid Spoiler	1	†	1
1181		Tailgate	DD	1	1
1182		Tailgate Emblem	NG	17	2
1183	994643	Tailgate Outer Handle	1752	1	1
1184	994640	Tailgate Moulding	D/	V	1
1185	994545	Tailgate Garnish	BA	1	1
1186	994648	Tailgate Reflector :	1	1	1
1187	994549	Tailgate Lamp	BR	10	1
1188	994646	Tailgate Protector	200	1	
1189	994676	Tailgate Wiper Arm		1	1
1190	994677	Tailgate Wiper Blade		1	1
1191	994679	Tailgate Wiper Nozzle	1	\top	1
1192	994555	Tailgate Wiper Motor	1	1	1
1193		Tailgate Glass .	_	1	\vdash
1194	-	Tailgate Glass Rubber	1774	-	-
1195			NEC	4	-
		Tailgate Glass Moulding	-	-	+
1196		Tailgate Glass Sealant	Ng	4 V.	1
1197		Tailgate Lock	BT	V	-
1198		Tailgate Rubber	Curt	V	-
-					-
				1	_
1201	994613	Tailgate Inner Board		L	
1198 1199 1200 1201	994611 994594	Tailgate Rubber Tailgate Hinge Tailgate Damper Tailgate Inner Board	Curt		+

		- ~ /			
	1.5	Vehicle No:	154		_
NAC	INC	Item	CON	AC	Qt
		Spare Tyre Board			_
		Spare Tyre Panel	-		_
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
		Spare Tyre Covér			_
		Triangle Breakdown Sign			_
		CD Changer Assy	_	-	-
	990164			_	-
			to a	-/-	-
		Centre Exhaust Pipe Assy .	5/	V.	_
-		Centre Exhaust Mounting	DIS	V	_
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting	DIS	V	
		Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
		Rear RH Chassis Member			
		Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
		Rear LH Fender Inner Garnish		\vdash	\vdash
		Rear LH Fender Inner Shield		-	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim		1	
		Rear LH Rim Cover			
		Rear-LH Tyre		1	
		Rear RH Fender			
		Rear RH Fender Protector	_		
		Rear RH Fender Inner Panel			
		Rear RH Fender Inner Trim			
		Rear RH Fender Inner Garnish	D15	1/	
		Rear RH Fender Inner Shield			\vdash
		Rear RH Mudflap			
		Rear RH Wheel Rim			
		Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
		Rear Fender Extension Panel LH		-5	
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			14
1241		Rear Fender 1/4 Glass .			10
1242		Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Scalant			
1244	993949	Rear Windscreen Glass			
		Rear Windscreen Rubber			10
		Rear Windscreen Moulding		1	125
		Rear Windscreen Sealant			12
		Third Brake Light			13
		Rear Fender Air Grille			1
		Fuel Lid			1
		Fuel Neck			
		Fuel Tank ,			100
1253	992184	Fuel Tank Bracket		1	13
1254	992191	Fuel Tank Float			13
	990247				1
		1.1			10
7	1	atto	1		188
-/-	1		1		
-/	A	 	-	-	10
1	1/1	1/1	1	-	1
1.	1	h/0 0/9	-	-	1
	VY	17/22/1	+	+	-
	-	<u> </u>	-	+-	100
			1	1	800
			-	1-	-
				3	1

No of Items: Assessor: TGGW



No results.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj R	pt	Adj Submitted	Ins Auth'ed	1 5	Status		
Main	26 Feb 2019 Edit Reg	26 Feb 2019 00:00 25 Feb 2019			\$0.00 S\$0.00 Edit Estimates View Rpt		00		Pending for Survey Report Cancel Case		
	Main	R	eference		Claim Det	ails	Docum	ents		Show All	
CLAIM SI	JBFOLDER DI	ETAILS				[Create	d by adjuster]			
Insured:	QUEK LE	CHENG, NANTH	ANI (GUO LIQIN	, NANT	HANI), ID	: S8224971J					
Main Claimant:	UE-TAY S	ZE YIN									
Vehicle Re No.:	g. SFV154	1L		Date of		21/02/2019 17:00 - :59 [45 Months and 28 Days From LTA Reg Date (Man Yr)]					
Claim Type	E: TP / 762	TP / 7624576799SG				over 2100482	2100482856 (Comprehensive)				
Vehicle Re No. (Insured):	SLG472S	SLG472S			Policy No (Claiman						
					Excess:						
Repairer:	Messrs D	errick Motor Wo	rks (HQ) BLK 9002	TAMPIN	ES ST 93, #	01-72, TAMPINE	S IND PARK A,	528836 T	ampines - Te	el:	
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel	: 65-6419-3	000 [Handled	by Foo, Chit Y	an] Chit	yan.Foo@aig	.com	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled	by Lim Teow	Guan] [Fina	al Rpt o	due 06/03/	2019]	
Claimant's Solicitor:	VISION L	AW LLC - Tel: 65	342811								
ASSOCIA	TED MAIL RE	CEIVED						View All	Compos	e Case Ma	
AIG_SG	(26/02/2019)	TP GIA REPOR	**								
ALL ASS	OCIATED TAS	sks⊟				View All	Search Tasks	Create	New Task	Complet	

Merimen e-Claims Page 1 of 5

Claim Documents

*SFV1541L (7624576799SG)

[SLG472S]

TP

UE-TAY SZE YIN

Feb 21 2019 5:00PM

[QUEK LEE CHENG, NANTHANI (GUO LIQING, NANTHANI)]

Messrs Derrick Motor Works

Pho	otos/Images		3 per pa	ige 🔻	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	10/04/19 10:52	General View	0	Load JPG	V
2	10/04/19 10:52	General View	0	Load JPG	✓
3	10/04/19 10:53	General View	0	Load JPG	V
4	10/04/19 10:53	General View	0	Load JPG	V
5	10/04/19 10:53	General View	0	Load JPG	V
6	10/04/19 10:53	General View	0	Load JPG	✓
7	10/04/19 10:53	General View	0	Load JPG	✓
8	10/04/19 10:53	General View	0	Load JPG	V
9	10/04/19 10:53	General View	•	Load JPG	✓
10	10/04/19 10:53	General View	0	Load JPG	V
11	10/04/19 10:53	General View	0	Load JPG	✓
12	10/04/19 10:53	General View	0	Load JPG	~
13	10/04/19 10:53	General View	0	Load JPG	V
14	10/04/19 10:53	General View	0	Load JPG	~
15	10/04/19 10:53	General View	0	Load JPG	V
16	10/04/19 10:53	General View	0	Load JPG	✓
17	10/04/19 10:53	General View	Ð	Load JPG	V
18	10/04/19 10:53	General View	0	Load JPG	✓
19	10/04/19 10:53	General View	0	Load JPG	~
20	10/04/19 10:53	General View	0	Load JPG	V
21	10/04/19 10:53	General View	0	Load JPG	~
22	10/04/19 10:53	General View	0	Load JPG	~
23	10/04/19 10:53	General View	0	Load JPG	V
24	10/04/19 10:53	General View	0	Load JPG	✓
25	10/04/19 10:53	General View	0	Load JPG	V
26	10/04/19 10:53	General View	0	Load JPG	~
27	10/04/19 10:53	General View	0	Load JPG	V
28	10/04/19 10:53	General View	0	Load JPG	V
29	10/04/19 10:53	General View	0	Load JPG	V
30	10/04/19 10:53	General View	0	Load JPG	V
31	10/04/19 10:53	General View	O	Load JPG	~
32	10/04/19 10:53	General View	0	Load JPG	V
33	10/04/19 10:53	General View	0	Load JPG	V
34	10/04/19 10:53	General View	Ð	Load JPG	V
35	10/04/19 10:53	General View	0	Load JPG	V
36	10/04/19 10:53	General View	Ð	Load JPG	V
37	10/04/19 10:53	General View	0	Load JPG	V

Pho	tos/Images			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna 1994	_
38	10/04/19 10:53	General View	1 Load JPC	14
39	10/04/19 10:53	General View	1 Load JPC	_
40	10/04/19 10:53	General View	1 Load JPC	-
41	10/04/19 10:53	General View	1 Load JPC	_
42	10/04/19 10:53	General View	1 Load JPC	-
43	10/04/19 10:53	General View	1 Load JPC	3 V
44	10/04/19 10:53	General View	€ Load JPC	3 V
45	10/04/19 10:53	General View	1 Load JPC	5 2
46	10/04/19 10:53	General View	⑥ Load JPC	3 2
47	10/04/19 10:53	General View	Load JPC	3 2
48	10/04/19 10:53	General View	■ Load JPC	5 2
49	10/04/19 10:53	General View	1 Load JPC	3 🗷
50	10/04/19 10:53	General View	Load JPG	3 2
51	10/04/19 10:53	General View	Load JPG	3 2
52	10/04/19 10:53	General View	1 Load JPC	5 2
53	10/04/19 10:53	General View	1 Load JPC	3 V
54	10/04/19 10:53	General View	Load JPC	5 V
55	10/04/19 10:53	General View	■ Load JPC	3 2
56	10/04/19 10:53	General View	Load JPC	
57	10/04/19 10:53	General View	Load JPG	
58	10/04/19 10:53	General View	Load JPG	
59	10/04/19 10:53	General View	Load JPG	-
50	10/04/19 10:53	General View	■ Load JPG	-
51	10/04/19 10:53	General View	1 Load JPC	
52	10/04/19 10:53	General View	1 Load JPC	
53	10/04/19 10:53	General View	1 Load JPC	
54	10/04/19 10:53	General View	1 Load JPC	
		General View	1 Load JPC	
55	10/04/19 10:53		1 Load JPC	
56	10/04/19 10:53	General View		_
57	10/04/19 10:53	General View	1 Load JPC	_
58	10/04/19 10:53	General View	Load JPC	-
59	10/04/19 10:53	General View	Load JPC	_
70	10/04/19 10:53	General View	1 Load JPC	
71	10/04/19 10:53	General View	1 Load JPC	_
72	10/04/19 10:53	General View	1 Load JPC	_
73	10/04/19 10:53	General View	1 Load JPC	
74	10/04/19 10:53	General View	1 Load JPC	-
75	10/04/19 10:53	General View	1 Load JPC	
76	10/04/19 10:53	General View	1 Load JPC	_
77	10/04/19 10:53	General View	Load JP6	_
78	10/04/19 10:53	General View	1 Load JPC	_
79	10/04/19 10:53	General View	1 Load JPC	_
30	10/04/19 10:53	General View	Load JPC	
31	10/04/19 10:53	General View	1 Load JPC	_
32	10/04/19 10:53	General View	1 Load JPC	3 👿
33	10/04/19 10:53	Photographs of Damaged Parts	Load JPC	_
34	10/04/19 10:53	Photographs of Damaged Parts	Load JPC	3 🖸
35	10/04/19 10:53	Photographs of Damaged Parts	Load JPC	3 🖳
36	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	3 💆
87	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	3 🖳

Pho	tos/Images		3 per page	
No BB	Relabel/Reorder 10/04/19 10:53	LKK Auto Consultants Pte Ltd (HQ) Photographs of Damaged Parts	Thumbna Load JPC	_
39	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPC	-
0	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPC	
1	CV-0125 VIV-2 VIV-2 C-25		Load JPC	-
	10/04/19 10:53	Photographs of Damaged Parts		_
2	10/04/19 10:53	Photographs of Damaged Parts	Load JPC	_
3	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	_
4	10/04/19 10:53	Photographs of Damaged Parts	€ Load JPC	-
5	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	-
6	10/04/19 10:53	Photographs of Damaged Parts	6 Load JPG	-
7	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	_
8	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	_
9	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	S
00	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	
01	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	\
02	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	
03	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	
04	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	
05	10/04/19 10:53	Photographs of Damaged Parts	€ Load JPC	
06	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	
07	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	
08	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	
		Photographs of Damaged Parts	D Load JPC	
09	10/04/19 10:53	195 Jp 14 30:50 1975 197		-
10	10/04/19 10:53	Photographs of Damaged Parts		_
11	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPC	_
12	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	-
13	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	-
14	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	_
15	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	-
16	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	-
17	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	5 5
18	10/04/19 10:53	Photographs of Damaged Parts	■ Load 3PG	5 5
19	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	5
20	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPG	E
21	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	i 5
22	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	
23	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPG	
24	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPG	· •
25	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPC	1 -
26	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPC	-
27	10/04/19 10:53	Photographs of Damaged Parts	D Load JPG	-
28	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	-
		Photographs of Damaged Parts	1 Load JPC	-
29	10/04/19 10:53			_
30	10/04/19 10:53	Photographs of Damaged Parts	Load JPC	-
31	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	_
32	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	
33	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	_
34	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	-
35	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	-
36	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	_
137	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPC	5 B

No	tos/Images	LVV Auto Consultants Pts Ltd (UO)	3 per page V	4
No 138	Relabel/Reorder 10/04/19 10:53	LKK Auto Consultants Pte Ltd (HQ) Photographs of Damaged Parts	Thumbnai Load JPG	
139	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPG	V
40	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	
41	10/04/19 10:53	Photographs of Damaged Parts	■ Load JPG	V
42	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	V
43	10/04/19 10:53	Photographs of Damaged Parts	Load JPG	V
44	10/04/19 10:53	Photographs of Damaged Parts	1 Load JPG	Į.
45	10/04/19 10:53	Photo After Spray	1 Load JPG	-
46	10/04/19 10:53	Photo After Spray	1 Load JPG	5
47	10/04/19 10:53	Photo After Spray	1 Load JPG	5
48	10/04/19 10:53	Photo After Spray	Load JPG	-
49	100000 1 100000 1000 1000 1000 1000 10		1 Load JPG	-
50	10/04/19 10:53	Photo After Spray	1 Load JPG	5
	10/04/19 10:53	Photo After Spray	1 Load JPG	2
51	10/04/19 10:53	Photo After Spray		_
52	10/04/19 10:53	Photo After Spray		5
53	10/04/19 10:53	Photo After Spray	1 Load JPG	5
54	10/04/19 10:53	Photo After Spray	1 Load JPG	_
55	10/04/19 10:53	Photo After Spray	1 Load JPG	5
56	10/04/19 10:53	Photo After Spray	1 Load JPG	_
.57	10/04/19 10:53	Photo After Spray	1 Load JPG	_
58	10/04/19 10:53	Photo After Spray	1 Load JPG	-
59	10/04/19 10:53	Photo After Spray	1 Load JPG	+ -
60	10/04/19 10:53	Photo After Spray	1 Load JPG	5
161	10/04/19 10:53	Photo After Spray	Load JPG	-
162	10/04/19 10:53	Photo After Spray	Load JPG	-
163	10/04/19 10:53	Photo After Spray	1 Load JPG	-
164	10/04/19 10:54	Photo After Spray	■ Load JPG	-
165	10/04/19 10:54	Photo After Spray	1 Load JPG	6
166	10/04/19 10:54	Photo After Spray	1 Load JPG	_
167	10/04/19 10:54	Photo After Spray	1 Load JPG	-
168	10/04/19 10:54	Photo After Spray	1 Load JPG	6
169	10/04/19 10:54	Photo After Spray	1 Load JPG	6
170	10/04/19 10:54	Photo After Spray	1 Load JPG	6
171	10/04/19 10:54	Photo After Spray	1 Load JPG	[
72	10/04/19 10:54	Photo After Spray	1 Load JPG	5
73	10/04/19 10:54	Photo After Spray	Load JPG	6
74	10/04/19 10:54	Photo After Spray	1 Load JPG	6
75	10/04/19 10:54	Photo After Spray	■ Load JPG	6
76	10/04/19 10:54	Photo After Spray	Load JPG	6
77	10/04/19 10:54	Photo After Spray	Load JPG	E
178	10/04/19 10:54	Photo After Spray	Load JPG	6
79	10/04/19 10:54	Photo After Spray	1 Load JPG	6
80	10/04/19 10:54	Photo After Spray	■ Load JPG	6
81	10/04/19 10:54	Photo After Spray	1 Load JPG	6
82	10/04/19 10:54	Photo After Spray	1 Load JPG	6
83	10/04/19 10:54	Photo After Spray	■ Load JPG	1 -
184	10/04/19 10:54	Photo After Spray	■ Load JPG	-
185	10/04/19 10:54	Photo After Spray	■ Load JPG	_
	10/04/19 10:54	Photo After Spray	Load JPG	-

Pho	tos/Images		3 per pa	age 🔻	V
No Relabel/Reorder LKK Auto Consultants Pte Ltd (HQ)		Thumbnail			
Doc	Documentation		1 per pe	age 🔻	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	26/02/19 15:42	TP GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19003497/BCD3E2

Date:

22/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100482856

Claimant Vehicle No:

SFV1541L

Insured Vehicle No:

SLG472S

Date of Loss:

21/02/2019

Nature of Claim:

TP

Claim No: 7624576799SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SFV1541L

Make & Model:

TOYOTA WISH, 1.8 CVT (A)

Engine No:

2ZR1526444

Reg. Date:

24/04/2015 (Man. Year: 2015) Black

Chassis No: Odometer:

JTDGG20WX0J002312 92019 km

Colour: Engine Capacity:

1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

Yokohama 6 mm

Rear Left Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

Front Right Side: Yokohama 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

25/02/2019

Date Inspected:

25/02/2019 Inspected At:

Messrs Derrick Motor Works (HQ) BLK 9002 TAMPINES ST 93, #01-72,

TAMPINES IND PARK A

Singapore 528836

Estimated Period of Repair:

6.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Dage	-	224	00	Dorto
Reco	\mathbf{m}	ena	ea	raits

No.	Qty Part No	o. Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Bent	0.00 F	*-F
2	1	*FRT NUMBER PLATE BASE	Dented	0.00 F	*-F
3	1	*FRT BUMPER	Broken	0.00 F	*-F
4	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1	*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
6	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1	*FRT BUMPER SPONGE	Broken	0.00 F	*- F
8	1	*FRT BUMPER GRILLE	Dislodged	0.00 F	*-F
9	1	*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*- F
10	1	*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*-F
1.1	1	*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*- F
12	1	*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
13	1	*FRT GRILLE	Cut	0.00 F	*- F
14	1	*FRT SUPPORT PANEL	Repair	0.00 F	*-F
15	1	*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
16	1	*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
17	1	*BONNET	Bent	0.00 F	*- F
18	1	*BONNET EMBLEM	Necessary	0.00 F	*- F
19	1	*REAR NUMBER PLATE	Bent	0.00 F	*- F
20	1	*REAR NUMBER PLATE GARNISH	Dented	0.00 F	*-F
21	1	*REAR BUMPER	Dented	0.00 F	*-F
22	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
23	1	*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
24	2	*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
25	1	*REVERSE SENSOR	Dislodged	0.00 F	*- F
26	1	*TAILGATE	Dented	0.00 F	*- F
27	3	*TAILGATE EMBLEM	Necessary	0.00 F	*- F
28	1	*TAILGATE MOULDING	Dislodged	0.00 F	*- F
29	1	*TAILGATE GARNISH	Broken	0.00 F	*-F
30	1	*TAILGATE LAMP	Broken	0.00 F	*- F
31	1	*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
32	1	*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F
33	1	*TAILGATE LOCK	Bent	0.00 F	*-F
34	1	*TAILGATE RUBBER	Cut	0.00 F	*- F
35	1	*CENTRE EXHAUST PIPE ASSY	Bent	0.00 F	*-F
36	1	*CENTRE EXHAUST MOUNTING (RUBBER)	Distorted	0.00 F	*-F
37	1	*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F
38	1	*REAR RH FENDER INNER GARNISH	Distorted	0.00 F	*-F
	anchise part.		-		
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Polic∀holder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnelis Signature

Name:

NRIC/FIN No.

15 RIVIERA DRIVE Address

#07-17

Postcode 467205

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

YES

YES

1

NO

NO

YES

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name 10 UBI AVENUE 3

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN AND POLICE REPORT ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Vehicle Registration Number

Vehicle Make/Model/Colour

SLG472S

Details Of Properties

Vehicle Category

PRIVATE CAR

DETAILS OF OTHER VEHICLE PROPERTY 1

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name