

ASS. REC. BY:

REF:

CS/AIG19003501/TLS 302

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Har, Yinru

of

AIG

Date/Time: 25/2/19 @ 1:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

VCM 2085

Insured:

SMG 2312X

at Workshop m/s

A.S. phoun

Tel:

65150770

of

Blk 36, Joh Guen Rd East #01-35

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:10pm @ 25/2/19

Person Contacted:

Mr. Lee

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate Estimate not yet done. Repairer will call to arrange when estimate is done.

VCM 2085 - X

SMG 2312X - X


Tanji

ALG-

UCM 2085

2018 Dec

Make of Vehicle
Type of Vehicle
Year of Manufacture
Color
Engine
Transmission
Fuel System
Exhaust
Brake
Steering
Suspension
Tires
Wheels
Lights
Horn
Mirrors
Windows
Doors
Locks
Keys
Insurance
Registration
Title
VIN
Mileage
Condition
Remarks
Date
Time
Location
Inspector
Agent
Company
Signature
Stamp



Remarks: The vehicle had commenced its repair at the time of inspection.

Estimated Value: \$7000
Consistent? Yes or No
Consistent? Yes or No
Days: Rest: Yes or No
3 Val: Yes or No
G.A. / T.E.M. / F.H.P. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT
Mr. Kee

Action / Instruction: n/s will provide better work.

New bike \$9700 without insurance.

31/7 Confirm with Mr. Kee \$4872, 5 days.
(\$ 1,824.00 Red - 27%)

Make: Honda
Model: Vario 150
Color: Silver / Black
Engine: 149
Transmission: Automatic
Fuel System: Carburetor
Exhaust: Insured / STD / HI / HA
Brake: Insured / STD / HI / HA
Steering: Insured / STD / HI / HA
Suspension: Insured / STD / HI / HA
Tires: Insured / STD / HI / HA
Wheels: Insured / STD / HI / HA
Lights: Insured / STD / HI / HA
Horn: Insured / STD / HI / HA
Mirrors: Insured / STD / HI / HA
Windows: Insured / STD / HI / HA
Doors: Insured / STD / HI / HA
Locks: Insured / STD / HI / HA
Keys: Insured / STD / HI / HA
Insurance: Insured / STD / HI / HA
Registration: Insured / STD / HI / HA
Title: Insured / STD / HI / HA
VIN: Insured / STD / HI / HA
Mileage: Insured / STD / HI / HA
Condition: Insured / STD / HI / HA

PMKKF3770 KB002265

Copy Card: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt

Brake: Insured / Jammed / Leaked / Burnt

Model: STD / SRM / STD / SRM

Tyre Size: 90/80 R17
R: 120/70 R17

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PMA / SUMI /

TOYO / YOKO or

Front: 8 mm
R/Ral: 6 mm
L/Ral: 6 mm
D.O.A.: 12/3/19
Survey held at: AS Phoon Tsh Gaten
Des. of Damages: L / Rear / OBS / MS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 13 AUG 2019

Date/Time: 13/08/19
Typist: [Signature]
Date/Time: 13/08/19
Profit Report
Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Add Fee: []
Date/Time: []
Type/Size: []
Location: []
Work/Load: []

Survey Fee: 250
Transportation: 11
Total: 261

Report Form: \$4,872.00 P/P

– Pre-Repair Inspection Request – VCM2085 vs SMG2312X (OI) on D.O.A.: 22/01/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 25/2/2019 1:01:05 PM
Attachments:  tmp4236.tif  tmp4236.tif

Hi,

Please refer to the enclosed request from TAN CHIN HOE & CO.

Claim no : 9163368883SG003
Case Owner : KIAN MENG CHAN

If you have any queries/concerns, please let us know.
Kindly assist to assign **Mohamad Taufikh** as Single Joint Expert as requested.

Thanks & Regards,

Yin Rui, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: sheena@tanchinhoe.com.sg [mailto:sheena@tanchinhoe.com.sg]
Sent: Monday, February 25, 2019 11:34 AM
To: Mithoosingh, Aashweenjeetkaur; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Kaur, Baljit; Azlan, Syazairdina
Cc: 'kee kee'
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG2312X AND VCM2085 ON 22/01/2019 Our Ref: RT/43/2019/sn

Dear Sirs

- i. Our client's workshop agrees to Mohamad Taufikh from LKK Auto Consultants Pte Ltd to carry out the survey but reserve their position on whether to agree to Mohamad Taufikh being the SJE at the appropriate time.

Sheena Ng, Paralegal
TAN CHIN HOE & CO
24 Raffles Place
#24-01 Clifford Centre
Singapore 048621
Tel: 65382687
Fax: 65380287
Email: sheena@tanchinhoe.com.sg

This email is subject to legal privilege. If you are not the intended recipient, please delete this email and all its attachments from your computer immediately.

From: Hor, Yinnul
Sent: Monday, February 25, 2019 10:07 AM
To: info@tanchinhoe.com.sg
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Kaur, Baljit; Azlan, Syazairdina; Mithoosingh, Aashweenjeetkaur
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG2312X AND VCM2085 ON 22/01/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-03-04 10:07 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com

To: info@tanchinhoe.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, Baijit.Kaur@aig.com, Yinrul.Hor@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG2312X AND VCM2085 ON 22/01/2019

Date: Thu, 21 Feb 2019 01:53:19 +0000

Without Prejudice

Your Reference : RT/43/2019/sn (2)
Our Reference : 9163368883SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Chin, Ann

Sent: Wednesday, February 20, 2019 1:10 PM

To: PRDSG.WORKLIST

Cc: Azlan, Syazairdina; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; Md Ishak, Mohd Imran; Ho, Choon-Poh; Tan, Lily (AIG); Quek, Joyceline-CH; Zhou, Aiping; Hor, Yinrul

Subject: #9163368883SG004#002,002#

TAN CHIN HOE & CO
ADVOCATES & SOLICITORS
GST No. & UEN: 53131160X

24 Raffles Place
#24-01 Clifford Centre
Singapore 048621

Tel: 6538 2687
Facsimile: 6538 0287
Email: info@tanchincoe.com.sg

Your Ref:

Our Ref: RT/43/2019/sn (2)

20 February 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
Singapore 079120

Attn: Claims Department

Dear Sirs

PROPERTY DAMAGE CLAIM

FAX NO: 68357416

PDX Intercompany Exchange Pte Ltd



01080884581

FROM TAN CHIN HOE & COMPANY
PDX Box No. 8723

ACCIDENT INVOLVING VCM2085 AND SMG2312X ON 22 JANUARY 2019

1. We act for Ms Wong Pei Ling and are instructed to claim damages against your insured in connection with a road traffic accident on 22 January 2019 at Joo Koon Road involving our client's motorcycle no. VCM2085 and your insured's vehicle registration number SMG2312X.
2. We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's motorcycle was damaged and our client has been put to loss and expense.
3. We will revert with our client's quantification shortly.
4. In the meantime, our client's motorcycle is at the premises of A S Phoon Pte Ltd at Blk 36 Toh Guan Road East #01-35 Singapore 608580. Please contact Mr Kee at 65150770 for an appointment to survey the motorcycle within 2 days, failing which A S Phoon Pte Ltd will proceed to carry out the repairs.
5. Please let us have a copy of your insured driver's accident statement/traffic police report, if any.

Yours faithfully

Richard Tan

- cc:
1. client
 2. Lee Liang Ping
Block 445B Bukit Batok West Avenue 8
#12-443
Singapore 652445
 3. A S Phoon Pte Ltd
(Fax No. 65150779)



SINGAPORE POLICE FORCE



T/20190130/2193

Page 1

Police Station Of Origin:

Traffic Police

16 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Report No: T/20190130/2193

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:

22/01/2019 15:14

Vide Report No.:

Station Diary No:

Informant's Particulars

Name of Informant:

ADRIAN CHOE XIANG YANG

Address:

APT BLK 219 BUKIT BATOK STREET 21 #08-373
SINGAPORE 650219

ID Type / ID No.:

FIN NO / G7666837Q

Contact No.:

Home/Office:

Mobile: 0167066678

Nationality:

MALAYSIAN

Email:

Sex:

Male

Age:

31

Date of Birth:

29/10/1987

Type of Informant:

Rider

Race:

Chinese

Language:

Institution / School Name:

Occupation:

OTHERS

Driving Licence Information:

Class: 2B

Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury

Conveyed By Ambulance

Drink

Drive:

No

Date/Time of
Accident:

22/01/2019 08:45

Type of Location:
T-Junction

Location:

Along Road 1

JOO KOON ROAD

BEHIND JOOK KOON MRT

Weather:

Clear

Road Surface:

Dry

Road Speed Limit:

Traffic Flow:

Traffic Control:

Not Controlled

Traffic Volume:

Moderate

Type of Collision:

Anyone conveyed by
ambulance:
Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
VCM2085	Motorcycle					0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



Station Of Origin:
Police
150, Bras Basah Road SINGAPORE 408865
Tel: 65-4700000

Report No: T/20190130/2103

CONTINUATION OF REPORT

NAME	ADRIAN CHOE XIANG YANG	ID No	G/66681313
Related Vehicle	NIL	Contact No	915/0565/78
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: Nil
Date of Treatment	22/01/2019	Date Discharge	29/01/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE & LOCATION,

I WAS RIDING MY BIKE ALONG THE X JUNCTION AS I WAS GOING STRAIGHT ON THE LANE
I SUDDENLY A WHITE COLOURED CAR CAME TOWARDS FROM MY RIGHT AND COLLIDED ON
MY MOTORBIKE.

THE CAR HIT ME AND I FALL OFF FROM MY BIKE AND LANDED ON THE GROUND.

I SUSTAINED INJURIES AND WAS BROUGHT OVER TO THE HOSPITAL. I NEVER NOTE DOWN
THE PLATE NUMBER AND NEVER HAD ANY INTERACTION WITH THE DRIVER.

MY BIKE WAS TOWED TO TRAFFIC POLICE.

I WAS CONVEYED TO NTFGH AND GOT DISCHARGED ON THE 29/01/2019.

THATS ALL.



SINGAPORE
POLICE FORCE



T/20190130/2103

3 of 3

Report No. T/20190130/2103

Police Station Of Origin:

Traffic Police

100 Raffles Avenue 3 SINGAPORE 408865

Fax No. 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /

YOGENDRAN S/O RAJASAKARAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

Signature Of Informant:

Date/Time:

30/01/2019 15:14

Classification Of Case:

Authentication Stamp



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

ATKESC19

No. Pendaftaran : VCM2085
No. ID : 930422015992
Nama Pemunya Berdaftar : WONG PEI LING
Alamat : NO 52 JLN HANG KASTURI 7 TMN SKUDAI BARU
81300 SKUDAI JOHOR

No. Chasis/No. Enjin : PMKKF3770KB002265 / KF29E8043936
Buatan/Nama Model : HONDA / VARIO (ACB150CBTK)
Keupayaan Enjin : 149
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2018
Tarikh Pendaftaran : 15/12/2018
B.D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

7928403



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

VCM2085 HONDA VARIO 150 Fi REPAIR LIST (25FEB2019)

ITEM	DESCRIPTION	AMOUNT (SGD)
1	FRONT WHEEL ASSY	at \$340.00
2	FRONT WHEEL AXLE	bt \$22.00
3	BEARING X2	nc \$40.00
4	DUST COVER X2	x } \$16.00
5	FRONT BRAKE DISC	nx } \$125.00
6	FRONT BRAKE CALIPER	x } \$210.00
7	FRONT FORK ASSY R/H & L/H @\$220 photo	bt \$440.00
8	STEM STEERING	na \$185.00
9	CONE BEARING SET	nc \$65.00
10	FRONT FENDER	at \$68.00
11	STAY . FRONT FENDER	nx \$20.00
12	HEADLAMP ASSY	cut \$680.00
13	HEADLAMP BRACKET	at \$120.00
14	HORN COVER -SILVER	at \$75.00
15	HORN COVER TOP COVER -BK	at \$45.00
16	FRONT FAIRING RH (SILVER)	cut \$95.00
17	FRONT FAIRING COVER OUTER RH (MATT BLACK)	cu \$18.00
18	FRONT FAIRING COVER INNER RH (MATT BLACK)	cu \$16.00
19	SPOILER -FRONT	cu \$75.00
20	SPOILER -UNDER	at \$60.00
21	BUTTON X2	nc \$6.00
22	FRONT FAIRING LH (SILVER)	cu \$95.00
23	FRONT FAIRING COVER OUTER LH (MATT BLACK)	cu \$18.00
24	FRONT FAIRING COVER INNER LH (MATT BLACK)	cu \$16.00
25	BACK SHIELD UPPER (KEY)	cu \$125.00
26	BACK SHIELD LID (KEY)	mb \$8.00
27	COMPARTMENT COVER (SILVER)	cu \$50.00
28	BACK SHIELD LOWER	cu \$45.00
29	FOOTBOARD	cut \$100.00
30	EXHAUST ASSY	bt \$850.00
31	GASKET X1	na \$6.00
32	HEAT PROTECTION	cu \$28.00
33	CAP MUFFLER	cut \$32.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

VCM2085 HONDA VARIO 150 Fi (YELLOW) REPAIR LIST (25FEB2019)

ITEM	DESCRIPTION	AMOUNT (SGD)
34	RADIATOR	un X \$295.00
35	DADIATOR COVER	ant \$24.00
36	COOLANT	un X \$40.00
37	REAR FOOTREST RH	ant \$45.00
38	REAR FOOTREST BRACKET RH	dd \$45.00
39	REAR FAIRING RH	ant \$95.00
40	MAINSTAND	un. bt \$105.00
41	LOWER SPOILER RH & LH @\$75	LH-X, RH-un \$150.00 75
42	HANDLEBAR	bt \$75.00
43	HANDLEBAR UNDER BRACKET	un X \$35.00
44	BALANCER RH & LH	LH-X RH-un \$36.00 18
45	SIDE MIRRORS RH & LH @40	RH-un \$80.00 40
46	BRAKE LEVER	ant \$28.00
47	SCREW BRAKE LEVER	un. ant X \$12.00
48	HANDLEBAR COVER-FRONT	ant \$45.00
49	HANDLEBAR TOP COVER	ant \$22.00
50	STICKER SET	un \$160.00
51	REAR TOP BOX	ant \$280.00
52	TOP BOX BRACKRT	un X \$80.00
53	TRANSPORTATION TP - BIKESHOP	40 \$50.00
54	WORKMANSHIP	250 \$350.00
55	BODY CHASSIS REPAIR	200 \$450.00
56	TRANSPORTATION X2 @ \$50	80 \$100.00

TOTAL

\$6,696.00

Parts - 4780.
10% - 4302
Labour - 570
\$4872 *

Signature
15/3/19

Tanpin 97495749
-wp

12/3/19 @ 1830

5 days

Receiving new parts

tanpin@lilaauto.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2019 Edit Reg		25 Feb 2019 00:00 Edit Adj Rpt	S\$4,872.00 Edit Estimates	S\$4,872.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Lee Liang Ping , ID: S7906367C									
Main Claimant: WONG PEI LING									
Vehicle Reg. No.: VCM2085		Date of Loss: 22/01/2019 00:00 - :59 [1 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9163368883SG		Policy/Cover Note No.: (Comprehensive) Coverage: 11/12/2018 - 10/12/2019							
Vehicle Reg. No. (Insured): SMG2312X		Policy No. (Claimant):							
		Excess:							
Repairer: A.S. Phoon Pte Ltd (Toh Guan) Blk 36 Toh Guan Road, East Enterprise Hub #01-35, 608580 Jurong East - Tel: 6515 0770									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (26/02/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*VCM2085 (9163368883SG)
[SMG2312X]
TP
WONG PEI LING
Jan 22 2019 12:00AM
[Lee Liang Ping]
A.S. Phoon Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	31/07/19 14:00	General View				 Load JPG	☒
2	31/07/19 14:00	General View				 Load JPG	☒
3	31/07/19 14:00	General View				 Load JPG	☒
4	31/07/19 14:00	General View				 Load JPG	☒
5	31/07/19 14:00	General View				 Load JPG	☒
6	31/07/19 14:00	General View				 Load JPG	☒
7	31/07/19 14:00	General View				 Load JPG	☒
8	31/07/19 14:00	General View				 Load JPG	☒
9	31/07/19 14:00	General View				 Load JPG	☒
10	31/07/19 14:00	General View				 Load JPG	☒
11	31/07/19 14:00	General View				 Load JPG	☒
12	31/07/19 14:00	General View				 Load JPG	☒
13	31/07/19 14:00	General View				 Load JPG	☒
14	31/07/19 14:00	General View				 Load JPG	☒
15	31/07/19 14:00	General View				 Load JPG	☒
16	31/07/19 14:00	General View				 Load JPG	☒
17	31/07/19 14:00	General View				 Load JPG	☒
18	31/07/19 14:00	General View				 Load JPG	☒
19	31/07/19 14:00	General View				 Load JPG	☒
20	31/07/19 14:00	General View				 Load JPG	☒
21	31/07/19 14:00	General View				 Load JPG	☒
22	31/07/19 14:00	General View				 Load JPG	☒
23	31/07/19 14:00	General View				 Load JPG	☒
24	31/07/19 14:00	General View				 Load JPG	☒
25	31/07/19 14:00	General View				 Load JPG	☒
26	31/07/19 14:00	General View				 Load JPG	☒
27	31/07/19 14:00	General View				 Load JPG	☒
28	31/07/19 14:00	General View				 Load JPG	☒
29	31/07/19 14:00	General View				 Load JPG	☒
30	31/07/19 14:00	General View				 Load JPG	☒
31	31/07/19 14:00	General View				 Load JPG	☒
32	31/07/19 14:00	General View				 Load JPG	☒
33	31/07/19 14:00	General View				 Load JPG	☒
34	31/07/19 14:00	General View				 Load JPG	☒
35	31/07/19 14:00	General View				 Load JPG	☒
36	31/07/19 14:00	General View				 Load JPG	☒
37	31/07/19 14:00	General View				 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/07/19 14:00	General View	 Load JPG	☒
39	31/07/19 14:00	General View	 Load JPG	☒
40	31/07/19 14:00	General View	 Load JPG	☒
41	31/07/19 14:00	General View	 Load JPG	☒
42	31/07/19 14:00	General View	 Load JPG	☒
43	31/07/19 14:00	General View	 Load JPG	☒
44	31/07/19 14:00	General View	 Load JPG	☒
45	31/07/19 14:00	General View	 Load JPG	☒
46	31/07/19 14:00	General View	 Load JPG	☒
47	31/07/19 14:00	General View	 Load JPG	☒
48	31/07/19 14:00	General View	 Load JPG	☒
49	31/07/19 14:00	General View	 Load JPG	☒
50	31/07/19 14:00	General View	 Load JPG	☒
51	31/07/19 14:00	General View	 Load JPG	☒
52	31/07/19 14:00	General View	 Load JPG	☒
53	31/07/19 14:00	General View	 Load JPG	☒
54	31/07/19 14:00	General View	 Load JPG	☒
55	31/07/19 14:00	General View	 Load JPG	☒
56	31/07/19 14:00	General View	 Load JPG	☒
57	31/07/19 14:00	General View	 Load JPG	☒
58	31/07/19 14:00	General View	 Load JPG	☒
59	31/07/19 14:00	General View	 Load JPG	☒
60	31/07/19 14:00	General View	 Load JPG	☒
61	31/07/19 14:00	General View	 Load JPG	☒
62	31/07/19 14:00	General View	 Load JPG	☒
63	31/07/19 14:00	General View	 Load JPG	☒
64	31/07/19 14:00	General View	 Load JPG	☒
65	31/07/19 14:00	General View	 Load JPG	☒
66	31/07/19 14:00	General View	 Load JPG	☒
67	31/07/19 14:00	General View	 Load JPG	☒
68	31/07/19 14:00	General View	 Load JPG	☒
69	31/07/19 14:00	General View	 Load JPG	☒
70	31/07/19 14:00	General View	 Load JPG	☒
71	31/07/19 14:00	General View	 Load JPG	☒
72	31/07/19 14:00	General View	 Load JPG	☒
73	31/07/19 14:00	General View	 Load JPG	☒
74	31/07/19 14:00	General View	 Load JPG	☒
75	31/07/19 14:00	General View	 Load JPG	☒
76	31/07/19 14:00	General View	 Load JPG	☒
77	31/07/19 14:00	General View	 Load JPG	☒
78	31/07/19 14:00	General View	 Load JPG	☒
79	31/07/19 14:00	General View	 Load JPG	☒
80	31/07/19 14:00	General View	 Load JPG	☒
81	31/07/19 14:00	General View	 Load JPG	☒
82	31/07/19 14:00	General View	 Load JPG	☒
83	31/07/19 14:00	General View	 Load JPG	☒
84	31/07/19 14:00	General View	 Load JPG	☒
85	31/07/19 14:00	General View	 Load JPG	☒
86	31/07/19 14:00	General View	 Load JPG	☒
87	31/07/19 14:00	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	31/07/19 14:00	General View	 Load JPG	☒
89	31/07/19 14:00	General View	 Load JPG	☒
90	31/07/19 14:00	General View	 Load JPG	☒
91	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
92	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
93	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
94	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
95	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
96	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
97	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
98	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
99	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
100	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
101	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
102	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
103	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
104	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
105	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
106	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
107	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
108	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
109	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
110	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
111	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
112	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
113	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
114	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
115	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
116	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
117	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
118	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
119	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
120	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
121	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
122	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
123	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
124	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
125	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
126	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
127	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
128	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
129	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
130	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
131	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
132	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
133	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
134	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
135	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
136	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
137	31/07/19 14:01	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
139	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
140	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
141	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
142	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
143	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
144	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
145	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
146	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
147	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
148	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
149	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
150	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
151	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
152	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
153	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
154	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
155	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
156	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
157	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
158	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
159	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
160	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
161	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
162	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
163	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
164	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
165	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
166	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
167	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
168	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
169	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
170	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
171	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
172	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
173	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
174	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
175	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
176	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
177	31/07/19 14:01	Reinspection Photo	 Load JPG	☒
178	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
179	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
180	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
181	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
182	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
183	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
184	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
185	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
186	31/07/19 14:02	Reinspection Photo	 Load JPG	☒
187	31/07/19 14:02	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
188	31/07/19 14:02	Reinspection Photo		Load JPG ☒
189	31/07/19 14:02	Reinspection Photo		Load JPG ☒
190	31/07/19 14:02	Reinspection Photo		Load JPG ☒
191	31/07/19 14:02	Reinspection Photo		Load JPG ☒
192	31/07/19 14:02	Reinspection Photo		Load JPG ☒
193	31/07/19 14:02	Reinspection Photo		Load JPG ☒
194	31/07/19 14:02	Reinspection Photo		Load JPG ☒
195	31/07/19 14:02	Reinspection Photo		Load JPG ☒
196	31/07/19 14:02	Reinspection Photo		Load JPG ☒
197	31/07/19 14:02	Reinspection Photo		Load JPG ☒
198	31/07/19 14:02	Reinspection Photo		Load JPG ☒
199	31/07/19 14:02	Reinspection Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	31/07/19 14:03	POLICE REPORT.pdf		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	26/02/19 10:12	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003501/T1SD3E2

Date: 26/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : VCM2085

Insured Vehicle No : SMG2312X

Date of Loss: 22/01/2019

Nature of Claim: TP

Claim No: 9163368883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **VCM2085**

Make & Model: HONDA VARIO, 149cc

Engine No: KF29E8043936

Reg. Date: 15/12/2018 (Man. Year: 2018)

Chassis No: PMKKF3770KB002265

Colour: Black/Silver

Odometer: 0 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 R17

Rear Tyre Size:

120/70 R17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,746.00	4,302.00	1,444.00	25.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	570.00	380.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,696.00	4,872.00	1,824.00	27.24
+ GST 7.00/7.00% (S\$)	468.72	341.04	127.68	27.24
Nett Amount (S\$)	7,164.72	5,213.04	1,951.68	27.24

INSPECTION

Date of Assignment: 25/02/2019

Date Inspected: 12/03/2019 Inspected At:

A.S. Phoon Pte Ltd (Toh Guan)

Blk 36 Toh Guan Road, East Enterprise

Hub #01-35

Singapore 608580

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL ASSY	Cut	340.00 F	*340.00 FL
2	1		*FRONT WHEEL AXLE	Bent	22.00 F	*22.00 FL
3	2		*BEARING	Necessary	40.00 F	*40.00 FL
4	2		*DUST COVER	Not Necessary	16.00 F	*- FL
5	1		*FRONT BRAKE DISC	Not Necessary	125.00 F	*- FL
6	1		*FRONT BRAKE CALIPER	Not Necessary	210.00 F	*- FL
7	2		*FRONT FORK ASSY R/H & L/H	Bent	440.00 F	*440.00 FL
8	1		*STEM STEERING	Necessary	185.00 F	*185.00 FL
9	1		*SET CONE BEARING	Necessary	65.00 F	*65.00 FL
10	1		*FRONT FENDER	Cut	68.00 F	*68.00 FL
11	1		*STAY . FRONT FENDER	Not Necessary	20.00 F	*- FL
12	1		*HEADLAMP ASSY	Cut	680.00 F	*680.00 FL
13	1		*HEADLAMP BRACKET	Cut	120.00 F	*120.00 FL
14	1		*HORN COVER - SILVER	Cut	75.00 F	*75.00 FL
15	1		*HORN COVER TOP COVER - BK	Cut	45.00 F	*45.00 FL
16	1		*FRONT FAIRING RH (SILVER)	Cut	95.00 F	*95.00 FL
17	1		*FRONT FAIRING COVER OUTER RH (MATT BLACK)	Cracked	18.00 F	*18.00 FL
18	1		*FRONT FAIRING COVER INNER RH (MATT BLACK)	Cracked	16.00 F	*16.00 FL
19	1		*SPOILER - FRONT	Cracked	75.00 F	*75.00 FL
20	1		*SPOILER - UNDER	Cracked	60.00 F	*60.00 FL
21	2		*BUTTON	Necessary	6.00 F	*6.00 FL
22	1		*FRONT FAIRING LH (SILVER)	Cracked	95.00 F	*95.00 FL
23	1		*FRONT FAIRING COVER OUTER LH (MATT BLACK)	Cracked	18.00 F	*18.00 FL
24	1		*FRONT FAIRING COVER INNER LH (MATT BLACK)	Cracked	16.00 F	*16.00 FL
25	1		*BACK SHIELD UPPER (KEY)	Cracked	125.00 F	*125.00 FL
26	1		*BACK SHIELD LID (KEY)	Missing	8.00 F	*8.00 FL
27	1		*COMPARTMENT COVER (SILVER)	Cracked	50.00 F	*50.00 FL
28	1		*BACK SHIELD LOWER	Cracked	45.00 F	*45.00 FL
29	1		*FOOTBOARD	Cut	100.00 F	*100.00 FL
30	1		*EXHAUST ASSY	Bent	850.00 F	*850.00 FL
31	1		*GASKET	Necessary	6.00 F	*6.00 FL
32	1		*HEAT PROTECTION	Cracked	28.00 F	*28.00 FL
33	1		*CAP MUFFLER	Cut	32.00 F	*32.00 FL
34	1		*RADIATOR	Not Necessary	295.00 F	*- FL
35	1		*RADIATOR COVER	Cut	24.00 F	*24.00 FL
36	1		*COOLANT	Not Necessary	40.00 F	*- FL
37	1		*REAR FOOTREST RH	Cut	45.00 F	*45.00 FL
38	1		*REAR FOOTREST BRACKET RH	Dented	45.00 F	*45.00 FL
39	1		*REAR FAIRING RH	Cut	95.00 F	*95.00 FL
40	1		*MAINSTAND	Bent	105.00 F	*105.00 FL
41	1		*LOWER SPOILER RH & LH	N/S Not Necessary / O/S Cut	150.00 F	*75.00 FL
42	1		*HANDLEBAR	Bent	75.00 F	*75.00 FL
43	1		*HANDLEBAR UNDER BRACKET	Not Necessary	35.00 F	*- FL
44	1		*BALANCER RH & LH		36.00 F	*18.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				N/S Not Necessary / O/S Cut		
45	1		*SIDE MIRRORS RH & LH	O/S Cracked	80.00 F	*40.00 FL
46	1		*BRAKE LEVER	Cut	28.00 F	*28.00 FL
47	1		*SCREW BRAKE LEVER	Not Necessary	12.00 F	*- FL
48	1		*HANDLEBAR COVER-FRONT	Cut	45.00 F	*45.00 FL
49	1		*HANDLEBAR TOP COVER	Cut	22.00 F	*22.00 FL
50	1		*SET STICKER	Necessary	160.00 F	*160.00 FL
51	1		*REAR TOP BOX	Cut	280.00 F	*280.00 FL
52	1		*TOP BOX BRACKET	Not Necessary	80.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,746.00	4,780.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	478.00

Total Parts (\$\$)	5,746.00	4,302.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORTATION TP - BIKESHOP	New	50.00	40.00
2	WORKMANSHIP	New	350.00	250.00
3	BODY CHASSIS REPAIR	New	450.00	200.00
4	TRANSPORTATION	New	100.00	80.00
Gross Labour Cost (\$\$)			950.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >