



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33680

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 19/02/2019
CLAIM NO. : 11274
POLICY NO. : AVFMSB0000591803

FROM : RAYMOND

VEHICLE NO. : FBH1551D
MAKE/MODEL : YAM / YBR125

*not allowed
haha
2/5/8
4 day.
the 2nd. After rep
25/2/19*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00 ?
2	BUSH SWINGARM (METAL) P/N: 29093	REPLACE	2.00	\$5.00	10.00 ✓
3	BUSH SWINGARM (RUBBER) P/N: 29092	REPLACE	2.00	\$12.00	24.00 ✓
4	CLIP TUBE INNER FORK P/N: 35796	REPLACE	2.00	\$5.00	10.00 ?
5	COVER SIDE LH (BLACK) P/N: 45775	REPLACE	1.00	\$118.00	118.00 ✓
6	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00 ✓
7	COVER TANK SIDE LH (RED) P/N: 49207	REPLACE	1.00	\$119.00	119.00 ✓
8	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00 ✓
9	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$80.00	80.00 ✓
10	GUIDE AIR LH P/N: 48403	REPLACE	1.00	\$23.00	23.00 ?
11	HANDLE SEAT P/N: 42567	REPLACE	1.00	\$98.00	98.00 ✓
12	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	* Supply/Install	8.00	\$35.00	280.00 ✓
13	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00 ✓



112



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$19.00	19.00
15	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$98.00	98.00
16	OIL FORK (UNICORN) MR-10 P/N: 54320	REPLACE	1.00	\$10.00	10.00
17	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	\$32.00	32.00
18	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
19	SEAL OIL (18X24X4) SWINGARM BUSH P/N: 29094	REPLACE	2.00	\$8.00	16.00
20	SEAL OIL (30X41X10) FORK P/N: 13451	REPLACE	2.00	\$24.00	48.00
21	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$68.00	68.00
22	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	2.00	\$16.00	32.00
23	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	\$16.00	16.00
24	SWING ARM P/N: 25340	REPLACE	1.00	\$138.00	138.00
25	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.		1.00	\$35.00	35.00
26	TUBE INNER FORK P/N: 27114	REPLACE	2.00	\$98.00	196.00
27	VISOR P/N: 43130	REPLACE	1.00	\$30.00	30.00

SUB TOTAL

\$1,998.00

GST @ 7 %

\$139.86

GRAND TOTAL

\$2,137.86

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are known and agreed
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledge & Accepted By

Acknowledged by Repairer

Signature:

Date:

