



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33702

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 13/02/2019
CLAIM NO. : 11275
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

VEHICLE NO. : FBM4144A
MAKE/MODEL : YAM / YBR125

*Not Affected
2nd
P/P 3
25/2/19
Take photo After up*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$70.00	70.00 ?
2	CABLE SPEEDOMETER P/N: 50366	REPLACE	1.00	\$14.00	14.00 <i>70.00</i>
3	COVER TANK SIDE LH (BLACK) P/N: 54458	REPLACE	1.00	\$98.00	98.00 <i>50.00</i>
4	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$284.00	284.00 X <i>284.00</i>
5	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00 <i>50.00</i>
6	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	55.00 <i>70.00</i>
7	FORK FRONT ASSY LH P/N: 53203	REPLACE	1.00	\$140.00	140.00 ?
8	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$490.00	490.00 <i>100</i>
9	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	7.00	\$35.00	245.00 <i>200</i>
10	LAMP SIGNAL REAR RH P/N: 45419	REPLACE	1.00	\$63.00	63.00 <i>60.00</i>
11	LENS SIGNAL FRONT LH P/N: 54334	REPLACE	1.00	\$15.00	15.00 <i>50.00</i>
12	LENS SIGNAL FRONT RH P/N: 50591	REPLACE	1.00	\$15.00	15.00 <i>50.00</i>
13	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00 <i>50.00</i>



S/N	Description	Action	Qty	Unit Price	Amount
14	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00
15	MIRROR RH P/N: 26503	REPLACE	1.00	\$15.00	15.00
16	MUDGUARD FRONT (BLACK) P/N: 49723	REPLACE	1.00	\$98.00	98.00
17	PEDAL GEAR (SHORT) P/N: 45076	REPLACE	1.00	\$19.00	19.00
18	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$2,317.00	2,317.00
19	RIM SPORT FRONT P/N: 45153	REPLACE	1.00	\$275.00	275.00
20	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
21	STICKER (MCDONALD) SIDE COVER - NEW MODEL P/N: 44201	REPLACE	1.00	\$16.00	16.00
22	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$18.00	18.00
23	TRANSPORT CHARGES P/N: 07169		2.00	\$35.00	70.00

SUB TOTAL

\$4,745.00

GST @ 7 %

\$332.15

GRAND TOTAL

\$5,077.15

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

