

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5295S**AAD1902-185**

Not Noted
81648.93
Penalty Bepain

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5295S

JTDKB3FU303079127

TOYOTA

PRIUS

22.2.2019

III

17/1/2019

PART**LIST**

- 1 1 REAR BUMPER
- 2 1 REAR BUMPER RE-INFORCEMENT
- 3 1 REAR BUMPER TOWING COVER
- 4 1 REAR BUMPER UNDER COVER (BLACK)
- 5 1 REAR BUMPER SIDE RETAINER LH
- 6 1 REAR BUMPER SIDE RETAINER RH
- 7 1 REAR TAILGATE
- 8 1 REAR TAILGATE OUTER GARNISH
- 9 1 COVER, REAR COMBINATION LAMP, RH
- 10 1 COVER, REAR COMBINATION LAMP, RH
- 11 1 GARNISH, BACK DOOR SIDE, LH
- 12 1 GARNISH, BACK DOOR SIDE, RH
- 13 1 BOARD ASSY, BACK DOOR TRIM
- 14 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 15 1 REAR TAILGATE WEATHERSTRIP
- 16 1 REAR END PANEL
- 17 1 TAILLAMP LOWER RH
- 18 1 TAILLAMP UPPER RH
- 19 1 REAR BUMPER SIDE RH
- 20 1 REAR BUMPER SIDE LH

\$	<i>Am</i>	458.60	✓
\$	<i>R</i>	318.80	X
\$	<i>Sm</i>	14.70	X
\$	<i>Red Am</i>	552.60	✓
\$	<i>cm</i>	112.70	✓
\$	<i>Sm</i>	112.70	X
\$	<i>R</i>	1,547.27	} X
\$	<i>Sm</i>	905.10	
\$	<i>Sm</i>	54.70	
\$	<i>Sm</i>	54.70	
\$	<i>Sm</i>	93.60	
\$	<i>Sm</i>	93.60	
\$	<i>Sm</i>	254.40	
\$	<i>Sm</i>	51.20	
\$	<i>Sm</i>	365.20	
\$	<i>R</i>	602.10	
\$	<i>Sm</i>	548.40	} X
\$	<i>Sm</i>	557.90	
\$	<i>R</i>	232.00	
\$	<i>Am</i>	232.00	✓

\$	7,162.27
25% \$	1,790.57
\$	5,371.70

Specical Nett

1 1SET PARKING AID

\$ *Sm* 700.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5295S

2 1SET REAR BUMPER CLIP	\$	na	22.00	✓
3 2 REAR WINDSCREEN SELANT	\$	na	80.00	} X
4 1 WINDSCREEN MOULDING	\$	na	100.00	
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6 1 REAR TAILGATE TOYOTA LOGO	\$	na	47.00	
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	} X
10 1 REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	
11 1 REAR BUMPER PROTECTOR	\$	na	100.00	

TOTAL \$ 1,315.40**TOTAL PARTS \$ 6,687.10****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	3001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na	170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 52955

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ *nn* 170.00 X

To transfer of rear windscreen fittings and conduct
water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 X

TOTAL \$ 7,580.00

Over All Total \$ 19,638.81

(PART-BY-PART) Repair Days ~~10 DAYS~~
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: