

ASS. REC. BY:

REF

C8/CTI19003562/Ksd342

Special Instruction

Surveyor

Kenneth

## ASSIGNMENT (Office)

From (Person)

catherine thia

of

CTI

Date/Time:

26/2/19 @ 8:58am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 8805R

Insured:

YP 17294

at Workshop n/s

Ah Lim Motor

Tel:

64831244

of

No. 10, Amk Ind. park 2A #01-09

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/2/19

CA / REV / REP. / REV 24 HRS

Date/Time:

9:20am 26/2/19

Person Contacted:

Eileen

H.O.D. Endorsement:

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJK 8805R - 15/TP 10007201/11/11

YP 17294 - x

D.O.A: 12/4/2010

30/4 85951.48 Confirm

(\$7,298.64 Red - 55%)


REF: CTE

POLICY NAME

From: 26/02/19  
 Estimated Cost:  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJK 8805R  
 at Workshop: Ah Lim Motor  
 at: No. 10 AMK Ind. park 2A #01-09  
 Insured:  
 Policy No:  
 Claim No:  
 Sum Insured:  
 Excess:  
 (Client's Record)  
 Make of Veh: 1:30pm

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value.

IDAC Accident Report. Consistent? : Yes or No

GIA / PR Seen. Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lump Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJK 8805R 10 17  
 Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda (A) 1496  
 Colour: M. Red A/C Insured / Std / NI / NA  
 Sp Reading: 27499 I/Radio: Insured / Std / NI / NA  
 Eng/No:  
 Ch/No: RU1 1-228456  
 Gen Cond: ☒ Good / Fair / Poor / Burnt  
 Steering: ☒ In order / Jammed / Leaked / Burnt or  
 Brake: ☒ In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R:  
 BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: R/Bal: 7 mm  
 L/Bal: 7 mm  
 D.O.A: 20/2/19  
 Survey held at:  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

RECEIVED 6 MAY 2019

Date/Time: File Pass to:

1) 06/05/19  
Typ: 4

Date/Time: File Return to:

2)

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1) 10.00.00

1) Photo:

1) Other:

1) ...

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / L.B.1: 5,951.48 P/P

220

220

## Nivitha (LKK Auto)

---

**From:** Catherine Thia <catherine.thia@sg.cntaiping.com>  
**Sent:** Tuesday, 26 February 2019 8:58 AM  
**To:** assignments  
**Cc:** ahlimmc@singnet.com.sg  
**Subject:** FW: YOUR INSURED YP1729U DOA: 20/02/2019 & OUR CLIENT SJK8805R  
**Attachments:** 8805 - AXA.pdf; 8805-Estimate-0001.pdf

Dear LKK

Please assist to survey the vehicle

**Catherine Thia**  
Senior Executive  
Motor Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6193  
[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Eileen Chua [mailto:ahlimmc@singnet.com.sg]  
**Sent:** Monday, 25 February, 2019 5:49 PM  
**To:** Catherine Thia <catherine.thia@sg.cntaiping.com>  
**Subject:** Fw: YOUR INSURED YP1729U DOA: 20/02/2019 & OUR CLIENT SJK8805R

Hi Catherine,

I call you this morning,  
Our client is free to let the surveyor see the car tomorrow. Had you assign to LKK for survey. Please kindly advise soonest.

Best Regards,  
Eileen Chua  
Ah Lim Motor Company  
No. 10 Ang Mo Kio Ind. Park 2A  
#01-09 AMK Autopoint S(568047)  
Tel: 64831244 Fax: 64836170

**From:** Eileen Chua  
**Sent:** Monday, February 25, 2019 11:22 AM  
**To:** China - Catherine  
**Subject:** Fw: YOUR INSURED YP1729U DOA: 20/02/2019 & OUR CLIENT SJK8805R

Hi Catherine,

Please kindly arrange survey. And advise the liability.

Best Regards,  
Eileen Chua  
Ah Lim Motor Company  
No. 10 Ang Mo Kio Ind. Park 2A  
#01-09 AMK Autopoint S(568047)  
Tel: 64831244 Fax: 64836170

**From:** Eileen Chua  
**Sent:** Thursday, February 21, 2019 2:47 PM  
**To:** China - Claims Dept  
**Cc:** China - Lucas Lee ; China Taiping - Irene Tay  
**Subject:** YOUR INSURED YP1729U DOA: 20/02/2019 & OUR CLIENT SJK8805R

Hi Claim Team,

Please kindly arrange survey. And advise the liability.

Best Regards,  
Eileen Chua  
Ah Lim Motor Company  
No. 10 Ang Mo Kio Ind. Park 2A  
#01-09 AMK Autopoint S(568047)  
Tel: 64831244 Fax: 64836170

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5555H

**Vehicle Details**

Vehicle No.:	SJK8805R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	L15B4426459
Chassis No.:	RU11226456
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,758.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$12,462.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2027
PARF Rebate Amount:	\$9,346.00

**Intended COE Rebate Details**

COE Expiry Date:	11 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$34,320.00
<b>Total Rebate Amount:</b>	<b>\$43,666.00</b>

The information contained herein is correct as at 20 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/02/2019 16:18
Date Of Accident	20/02/2019 07:05
Exact Location Of Accident	ALONG CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJK8805R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOH YONG KIAT
NRIC No	S1375555H
Email Address	YONGKIAT.GOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96744286
Alternative Phone No	OTHERS-96744286
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA275225
Cover Note Number	12/10/2018 - 11/10/2019
<b>Driver</b>	
Name of Driver	GOH YONG KIAT
NRIC No	S1375555H
Date Of Birth	02/04/1959
Occupation	INDOOR
Date Of Driving Pass	18/12/1978
Driving Experience	40 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96744286
Fax Number	
Contact Number	OTHERS-96744286
Email Address	YONGKIAT.GOH@GMAIL.COM

# Sketch Plan Pg. 1

Date of accident: 20-02-2019 Time: 7:05 Am Location: CTE  
 My Vehicle A: SJK PROSR Vehicle B: YP1729U Vehicle C: —  
 SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While travelling along CTE, traffic slowed and came to a stop. I stopped the car and suddenly my car was hit from behind by lorry YP1729U

Veh B driver is Koh Yong Hao SP100524 I

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :

Email address :

& myself :

Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

20/2/2019  
3.30pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



AH LIM MOTOR COMPANY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1375555H



Name

GOH YONG KIAT

吴湧傑

Race

CHINESE

Date of Birth

02-04-1959

Sex

M

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S1375555H

Name

GOH YONG KIAT

Birth Date: 02 Apr 1959

Issue Date: 01 Nov 2003



Hp: 9674 4286

Email: yongkiat.goh@gmail.com

2510303



NRIC No: S1375555H



Blood Group: Date of issue

A+

25-10-1994

56 SPRINGSIDE AVENUE  
SINGAPORE 786983

NRIC No: S1375555H

Date: 01/09/2011

No: 6787878

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B Motorcycles not exceeding 200 cc

07 Jan 1985

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

18 Dec 1978



NP 428A

GOH XUANYI, KRISTAL (P)

My  
info No  
Ca: No  
Total: 2





redefining / insurance

AXA Insurance Pte Ltd  
☎ 1800 880 4888 (Within Singapore)  
(65) 6880 4888 (International)  
✉ (65) 6880 4740  
✉ customer.care@axa.com.sg  
🌐 www.axa.com.sg

## Certificate of Insurance

account number  
04061

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)  
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

### Policy details

Policyholder name	GOH YONG KIAT	Certificate number	GA275225 / 1
Cover	Comprehensive	Chassis number	RU11226456
Plan name	Peace	Engine number	L15B4426459
NCD applicable	50%		
Vehicle registration number	SJK8805R		
Period of Insurance	from 12/10/2018 to 11/10/2019 (both dates inclusive)		
Finance loan company	MAYBANK		

### Persons or classes of persons entitled to drive\*

- (a) The Policyholder
- (b) Any Named Driver as stated in the Policy:
  - 1. HUNG YUIK KHING
- (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 300.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

### Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

### Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GOH YONG KIAT  
56 SPRINGSIDE AVENUE

SINGAPORE 786983

ATTN:

Your Ref No: -  
Claim Type: Third Party -  
Accident Date: 20/02/2019  
TP Veh Reg No: YP1729U

Estimate No: MC1900150  
Date: 20 Feb 2019  
Policy No: GA275225  
Veh Reg No: SJK8805R  
Make/Model: HONDA VEZEL 1.5X  
CVT

## Estimate Repair Cost to Vehicle No :SJK8805R

Description	Quantity	List Price	Amount
		S\$	S\$
<b>SPARE PARTS</b>			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	✓
2 TAILGATE	1 PC	972.40	✓
3 TAILGATE ABSORBER X 2	2 PC	360.00	X
4 TAILGATE EMBLEM	1 PC	15.70	✓
5 TAILGATE LOGO (VEZEL) LH	1 PC	43.00	✓
6 TAILGATE WIPER BLADE	1 PC	48.60	X
7 TAILGATE WIPER ARM	1 PC	80.00	X
8 TAILGATE WIPER ARM CAP	1 PC	10.50	✓
9 TAILGATE MOTOR	1 PC	205.00	X
10 TAILGATE NUMBER PLATE OUTER GARNISH WITH CLIPS	1 PC	220.00	✓
11 TAILGATE NUMBER PLATE LAMP X 2	2 PC	77.00	X
12 TAILGATE REVERSE CAMERA	1 PC	597.30	X
13 TAILGATE OUTER HOLDER OPENING	1 PC	175.50	X
14 TAILGATE LAMP X 2	2 PC	529.20	✓
15 TAILGATE RUBBER (AT BODY)	1 PC	93.20	✓
16 TAILGATE INNER TRIMBOARD	1 PC	153.40	X
17 TAILGATE INNER SIDE HOLDER COVER RH	1 PC	25.00	✓
18 TAILGATE INNER LOCK	1 PC	157.10	✓
19 TAILGATE INNER LOCK COVER - CHECK PRICE	1 PC	0.00	X
20 TAILGATE BUZZLE SENSOR (AT END PANEL)	1 PC	85.00	X
21 TAILAMP X 2	2 PC	857.40	✓
22 TAILAMP CLIPS X 6	6 PC	27.00	✓
23 TAILAMP PANEL X 2	2 PC	270.00	X
24 REAR BUMPER UPPER CORNER X 2	2 PC	390.00	✓
25 REAR BUMPER UPPER CORNER CLIPS X 6	6 PC	23.40	✓
26 REAR BUMPER BLACK	1 PC	463.70	✓
27 REAR BUMPER SIDE RETAINERS X 2	2 PC	35.00	X
28 REAR BUMPER CLIPS X 12	12 PC	46.80	✓
29 REAR BUMPER LOWER REFLECTOR X 2	2 PC	282.20	X
30 END PANEL	1 PC	411.90	✓
31 END PANEL TOP GARNISH WITH CLIP	1 PC	92.30	✓
32 SPARE TYRE PANEL	1 PC	662.20	X
33 SPARE TYRE PANEL TOP INNER TRIM	1 PC	0.00	X
34 SPARE TYRE PANEL TOP TRIM	1 PC	206.20	X
35 SPARE TYRE PANEL TOOL BOX BIG	1 PC	126.90	X
36 SPARE TYRE PANEL LOWER OUTER COVER BIG	1 PC	190.00	X
37 REAR CHASSIS FRAME SIDE PANEL X 2	2 PC	320.00	X

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

M/S : GOH YONG KIAT  
 56 SPRINGSIDE AVENUE

SINGAPORE 786983

ATTN:

Estimate No: MC1900150

Date: 20 Feb 2019

Policy No: GA275225

Veh Reg No: SJK8805R

Make/Model: HONDA VEZEL 1.5X  
 CVT

Your Ref No: -

Claim Type: Third Party

Accident Date: 20/02/2019

TP Veh Reg No: YP1729U

## Estimate Repair Cost to Vehicle No :SJK8805R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
38 REAR EXHAUST BOX	1 PC	<i>nn</i> 528.00 <i>X</i>	
39 REAR EXHAUST BOX MOUNTING X 4	4 PC	<i>nn</i> 66.00 <i>X</i>	
40 REAR EXHAUST BOX TOP HEAT PLATE	1 PC	<i>nn</i> 55.00 <i>X</i>	
		9,021.90	
	Less 20%	1,804.38	7,217.52
<b>Special Nett</b>			
41 REAR NUMBER PLATE (BLACK)	1 PC	<i>nn</i> 35.00 <i>✓</i>	
42 REAR WINDSCREEN SEALANT	1 PC	<i>nn</i> 60.00 <i>40.00</i>	
43 REAR WINDSCREEN INNER SEAL	1 PC	<i>nn</i> 40.00 <i>30.00</i>	
44 REVERSE SENSOR X 2	2 PC	<i>Shot</i> 400.00 <i>200.00</i>	
		535.00	535.00
<b>LABOUR</b>			
45 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 <i>20.00</i>	
46 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	<i>nn</i> 80.00 <i>X</i>	
47 TO REMOVE & REINSTALL REAR WINDSCREEN	1 EA	150.00 <i>120.00</i>	
48 TO REMOVE & REINSTALL/REPLACE REAR REVERSE CAMERA	1 PC	80.00 <i>50.00</i>	
49 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	200.00 <i>60.00</i>	
50 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. REAR	1 PC	<i>nn</i> 400.00 <i>X</i>	
51 TO REMOVE AND REINSTALL FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	<i>nn</i> 150.00 <i>X</i>	
52 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	100.00 <i>50.00</i>	
53 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	80.00 <i>50.00</i>	
54 TO RESET ENGINE LIGHT, BUZZLE SENSOR, EDLC MODULE IDLING LIGHT, ABS LIGHT, AIRBAG LIGHT	1 PC	<i>nn</i> 380.00 <i>X</i>	
55 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	150.00 <i>60.00</i>	
56 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE, BOX, MOUNTING, HEAT PLATE	1 PC	<i>nn</i> 150.00 <i>X</i>	
57 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL L/R, REAR CHASSIS FRAME SIDE PANEL L/R. TO KNOCK & REPAIR REAR FENDER LH & RH, REAR CHASSIS FRAME X 2, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	2,000.00 <i>700.00</i>	

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : GOH YONG KIAT  
56 SPRINGSIDE AVENUE

SINGAPORE 786983

ATTN:

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 20/02/2019  
TP Veh Reg No: YP1729U

Estimate No: MC1900150  
Date: 20 Feb 2019  
Policy No: GA275225  
Veh Reg No: SJK8805R  
Make/Model: HONDA VEZEL 1.5X  
CVT

## Estimate Repair Cost to Vehicle No :SJK8805R

Description	Quantity	List Price	Amount
58 TO SPRAY TAILGATE, TAILGATE NO. PLATE OUTER GARNISH, REAR BUMPER UPPER CORNER X 2, END PANEL, SPRAY TYRE PANEL, TAILLAMP PANEL X 2, REAR FENDER X 2, REAR CHASSIS FRAME X 2 & CHASSIS FRAME SIDE PANEL X 2.,	1 PC	<u>S\$</u> 1,400.00	<u>S\$</u> 1,400.00
		5,360.00	5,360.00
		Total	S\$ 13,112.52
		Add GST @ 7%	917.88
		Total Amount Payable	S\$ 14,030.40

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND THIRTY AND CENTS FORTY ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

13250.12

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : GOH YONG KIAT  
56 SPRINGSIDE AVENUE  
  
SINGAPORE 786983

ATTN:

Estimate No: MC1900150  
Date: 04 Mar 2019  
Policy No: GA275225  
Veh Reg No: SJK8805R  
Make/Model: HONDA VEZEL 1.5X  
CVT

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 20/02/2019  
TP Veh Reg No: YP1729U

## Estimate Repair Cost to Vehicle No :SJK8805R

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR FENDER ARCH PROTECTOR LH	1 PC	172.00	✓
		172.00	
	Less 20%	34.40	137.60
Total			S\$ 137.60
GST Amount			S\$ 9.63
Total Amount Payable			S\$ 147.23

R/S By Kenneth  
4/3/19  
12.35pm

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 May 2019		06 May 2019 15:14 <a href="#">Edit Adj Rpt</a>	<b>S\$5,951.48</b> <a href="#">Edit Estimates</a>	<b>S\$5,951.48</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>GOH YONG KIAT</b> , ID: S1375555H								
Vehicle Reg. No.:	<b>SJK8805R</b>	Date of Loss:	20/02/2019 07:00 - :59 [16 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D200907C02</b>		Policy/Cover Note No.:	DMCVSN16179518022					
Vehicle Reg. No. (Insured):	<b>YP1729U</b>	Policy No. (Claimant):	GA275225						
		Excess:	S\$0.00						
Repairer:	<b>Ah Lim Motor Company (AMK)</b> 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 15/05/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									







## Claim Documents

\*SJK8805R (SNM19D200907C02)  
[YP1729U]  
TP  
GOH YONG KIAT  
Feb 20 2019 7:00AM  
[-]  
Ah Lim Motor Company

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)							Thumbnail	Print	
1	20/02/19 16:39	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)							Thumbnail	Print	
1	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
11	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
12	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
13	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
14	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
15	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
16	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
17	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
18	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
19	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
20	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
21	20/02/19 16:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	06/05/19 16:36	General View							Load JPG	<input checked="" type="checkbox"/>	
2	06/05/19 16:36	General View							Load JPG	<input checked="" type="checkbox"/>	
3	06/05/19 16:36	General View							Load JPG	<input checked="" type="checkbox"/>	
4	06/05/19 16:36	General View							Load JPG	<input checked="" type="checkbox"/>	
5	06/05/19 16:36	General View							Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				<input checked="" type="checkbox"/>
6	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/05/19 16:36	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	06/05/19 16:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/05/19 15:15	pri contact	 Load PDF	
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/02/19 16:36	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/19 11:10	Supplementary	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print	
1	20/02/19 16:39	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print	
1	20/02/19 16:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	20/02/19 16:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	20/02/19 16:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	20/02/19 16:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	20/02/19 16:37	Accident Photo	 Load JPG		



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				<input checked="" type="checkbox"/>
6	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	20/02/19 16:37	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/02/19 16:36	Sketch Plan	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19003562/KSD3E2

Date: 28/05/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN16179518022

Claimant Vehicle  
No : SJK8805RInsured Vehicle  
No : YP1729U

Date of Loss: 20/02/2019

Nature of Claim: TP

Claim  
No: SNM19D200907C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK8805R

Make &amp; Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4426459

Reg. Date: 12/10/2017 (Man. Year: 2017)

Chassis No: RU11226456

Colour: Metallic Red

Odometer: 27499 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,890.12	4,041.48	3,848.64	48.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	1,910.00	3,450.00	64.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,250.12</b>	<b>5,951.48</b>	<b>7,298.64</b>	<b>55.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>927.51</b>	<b>416.60</b>	<b>510.91</b>	<b>55.08</b>
<b>Nett Amount (S\$)</b>	<b>14,177.63</b>	<b>6,368.08</b>	<b>7,809.55</b>	<b>55.08</b>

### INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 26/02/2019 Inspected At:

Ah Lim Motor Company (AMK)  
10 Ang Mo Kio Industrial Park 2A, #01-09  
AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJK8805R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
2	1		*TAILGATE	Bent	972.40 FL	*972.40 FL
3	2		*TAILGATE ABSORBER	Serviceable	360.00 FL	*- FL
4	1		*TAILGATE EMBLEM	Necessary	15.70 FL	*15.70 FL
5	1		*TAILGATE LOGO (VEZEL) LH	Necessary	43.00 FL	*43.00 FL
6	1		*TAILGATE WIPER BLADE	Serviceable	48.60 FL	*- FL
7	1		*TAILGATE WIPER ARM	Serviceable	80.00 FL	*- FL
8	1		*TAILGATE WIPER ARM CAP	Dented	10.50 FL	*10.50 FL
9	1		*TAILGATE MOTOR	Serviceable	205.00 FL	*- FL
10	1		*TAILGATE NUMBER PLATE OUTER GARNISH WITH CLIPS	Buckled	220.00 FL	*220.00 FL
11	2		*TAILGATE NUMBER PLATE LAMP	Serviceable	77.00 FL	*- FL
12	1		*TAILGATE REVERSE CAMERA	Serviceable	597.30 FL	*- FL
13	1		*TAILGATE OUTER HOLDER OPENING	Serviceable	175.50 FL	*- FL
14	2		*TAILGATE LAMP	Cracked	529.20 FL	*529.20 FL
15	1		*TAILGATE RUBBER (AT BODY)	Distorted / Dented	93.20 FL	*93.20 FL
16	1		*TAILGATE INNER TRIMBOARD	Serviceable	153.40 FL	*- FL
17	1		*TAILGATE INNER SIDE HOLDER COVER RH	Dented	25.00 FL	*25.00 FL
18	1		*TAILGATE INNER LOCK	Dented	157.10 FL	*157.10 FL
19	1		*TAILGATE INNER LOCK COVER (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*TAILGATE BUZZLE SENSOR (AT END PANEL)	Serviceable	85.00 FL	*- FL
21	2		*TAILLAMP	Cut	857.40 FL	*857.40 FL
22	6		*TAILLAMP CLIPS	Necessary	27.00 FL	*27.00 FL
23	2		*TAILLAMP PANEL	Repair	270.00 FL	*- FL
24	2		*REAR BUMPER UPPER CORNER	Buckled / Cut	390.00 FL	*390.00 FL
25	6		*REAR BUMPER UPPER CORNER CLIPS	Necessary	23.40 FL	*23.40 FL
26	1		*REAR BUMPER BLACK	Bent	463.70 FL	*463.70 FL
27	2		*REAR BUMPER SIDE RETAINERS	Serviceable	35.00 FL	*- FL
28	12		*REAR BUMPER CLIPS	Necessary	46.80 FL	*46.80 FL
29	2		*REAR BUMPER LOWER REFLECTOR	Serviceable	282.20 FL	*- FL
30	1		*END PANEL	Bent	411.90 FL	*411.90 FL
31	1		*END PANEL TOP GARNISH WITH CLIP	Dented	92.30 FL	*92.30 FL
32	1		*SPARE TYRE PANEL	Repair	662.20 FL	*- FL
33	1		*SPARE TYRE PANEL TOP INNER TRIM (NPA)	Serviceable	0.00 FL	*- FL
34	1		*SPARE TYRE PANEL TOP TRIM	Serviceable	206.20 FL	*- FL
35	1		*SPARE TYRE PANEL TOOL BOX BIG	Serviceable	126.90 FL	*- FL
36	1		*SPARE TYRE PANEL LOWER OUTER COVER BIG	Serviceable	190.00 FL	*- FL
37	2		*REAR CHASSIS FRAME SIDE PANEL	Repair	320.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR EXHAUST BOX	Repair	528.00 FL	*- FL
39	4		*REAR EXHAUST BOX MOUNTING	Serviceable	66.00 FL	*- FL
40	1		*REAR EXHAUST BOX TOP HEAT PLATE	Repair	55.00 FL	*- FL
41	1		*REAR NUMBER PLATE (BLACK)	Dented	35.00 FS	*35.00 FS
42	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
43	1		*REAR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*30.00 FS
44	2		*REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
45	1		*REAR FENDER ARCH PROTECTOR LH	Mtg Cracked	172.00 FL	*172.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					9,728.90	4,975.60
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,838.78	934.12
Total Parts (\$\$)					7,890.12	4,041.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
3	TO REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REINSTALL / REPLACE REAR REVERSE CAMERA	New	80.00	50.00
5	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	200.00	60.00
6	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. REAR	New	400.00	0.00
7	TO REMOVE AND REINSTALL FUEL TANK, FIXTURE AND ATTACHMENTS	New	150.00	0.00
8	TO REMOVE AND REINSTALL / REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	100.00	50.00
9	TO REMOVE AND REINSTALL / REPLACE REAR BUMPER SENSORS	New	80.00	50.00
10	TO RESET ENGINE LIGHT, BUZZLE SENSOR, EDLC MODULE IDLING LIGHT, ABS LIGHT, AIRBAG LIGHT	New	380.00	0.00
11	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS	New	150.00	60.00
12	TO REALIGN, DISMANTLE AND REINSTALL / REPLACE EXHAUST PIPE, BOX, MOUNTING, HEAT PLATE	New	150.00	0.00
13	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL L/R, REAR CHASSIS FRAME SIDE PANEL L/R. TO KNOCK & REPAIR REAR FENDER LH & RH, REAR CHASSIS FRAME X 2, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	2,000.00	700.00
14	TO SPRAY TAILGATE, TAILGATE NO. PLATE OUTER GARNISH, REAR BUMPER UPPER CORNER X 2, END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL X 2, REAR FENDER X 2, REAR CHASSIS FRAME X 2 & CHASSIS FRAME SIDE PANEL X 2	New	1,400.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,360.00</b>	<b>1,910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

## Sketch Plan Pg. 2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

20/2/19  
3.30pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Address	56 SPRINGSIDE AVENUE
Postcode	786983
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GOH XUANYI KRISTAL GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP1729U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KOH YONG HAO
NRIC/Passport Number	S8100524I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	