

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8188D

DATE 25/2/2019 10:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Sponge			\$ 103.50
	Rear Bumper Under Cover			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear No. Plate			\$ 25.00
				\$ 25.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 2,088.36

Ka/uh 16/11/19

25/2/19

2 Days

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.