


INS. CASE OWNER: CC 4 KSM AXA1900 3568, RI LKK: 9352
 IDAC: 2/2

Surveyor: Rashid DOI: 26/2/2019 Date / Time: 26/2/19
 Registered in Merimen: 26/2/19

Pre-assign / CCU / FTE
 Insured Vehicle No.: XE 1134 Claim No.: SAMULFYN / 100885
 Name of Insured: VEOLA ES SINGAPORE P/L Policy No.: VFX / P1582555
 Insured Tel No.: 5000 HP: 2/2/19 Make / Model: VUUV0
 Excess Sec II :SS 5000 D.O.A: 2/2/19 Place of Accident: TUNAS SOUTH BR 1
 Is driver the owner? (YES / NO) Nature of Accident :
 If NO, Driver Name / Age: HAMBAN BIN DUTEN OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: (V/L: YES / NO) Insured Liability: % Final ? Yes / No



Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE: <u>26/2/19</u>	
	After call ltr to OE:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OE:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

13/3/2020 - Pte → Suci to em bsh
 17/3/2020 - File pass to MK to close.

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	SS	(days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>3/3/2020</u>	Confirm with: <u>Rashid</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% <u>100</u>	Agreed / Assessed) BOLA S/N No. : <u>15</u>	If NO or B 28. Ass. Lia :	
Repair Cost:	SS <u>13910.00</u>			
Loss of Rental (BOR):	SS <u>1412.40</u>	(<u>11</u> days) x \$ <u>120.00</u>		
Loss of Use (LOU):	SS -	(S x days)		
Loss of Income (LOI):	SS -	(S x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	SS <u>36.45</u>			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost	SS -			
Total:	SS <u>15358.45</u>	Global Sum SS: <u>14500.00</u> (as per <u>max</u>)		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS <u>14500.00</u>	Name 1: <u>EM - 1 AUTO Pte Ltd</u>		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT 17/3/2020

Param

REF: ASM(AXA)

f

50400

ASST. NATIONAL

Team: _____ Date: **26/2/19**

Estimated Cost: _____

OD: TP / RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SFD 699S**

at Work shop no: **EM-1 AUTO**

of: **BLK 8 #01-68 Sin Ming Ind. Est. Sec C**

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SFD 699S** Rego: **2016 Jun**

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: **TOYOTA WOH 1.8XA** CC: **1797**

Colour: **PURPLE** AC: **INSURED** / Std / NI / NA

Sp Reading: **78811** T/Radio: **INSURED** / Std / NI / NA

Eng/No: _____

C/No: **26E206030321**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Normal / Jammed / Leaked / Burnt or _____

Brake: Normal / Jammed / Leaked / Burnt or _____

Modif: Nil / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **78K**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: **12 ~~15~~ 20** days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Tyre Size: F: **195/65R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 22/02/19	D.O.I. 26/02/19

Survey held at: **EM-1 AUTO**

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or **O/S & FRNT N/S FRNT**

The UIC / Chassis frame / Body Structure affected due to collision.

US \$ 13000 (Red \$ 12874.33) 50%

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.F. (\$) _____

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3) _____

4) _____

5) _____

6) _____

7) _____

8) _____

9) _____

10) _____

11) _____

12) _____

13) _____

14) _____

15) _____

16) _____

17) _____

18) _____

19) _____

20) _____

21) _____

22) _____

23) _____

24) _____

25) _____

26) _____

27) _____

28) _____

29) _____

30) _____

31) _____

32) _____

33) _____

34) _____

35) _____

36) _____

37) _____

38) _____

39) _____

40) _____

41) _____

42) _____

43) _____

44) _____

45) _____

46) _____

47) _____

48) _____

49) _____

50) _____

51) _____

52) _____

53) _____

54) _____

55) _____

56) _____

57) _____

58) _____

59) _____

60) _____

61) _____

62) _____

63) _____

64) _____

65) _____

66) _____

67) _____

68) _____

69) _____

70) _____

71) _____

72) _____

73) _____

74) _____

75) _____

76) _____

77) _____

78) _____

79) _____

80) _____

81) _____

82) _____

83) _____

84) _____

85) _____

86) _____

87) _____

88) _____

89) _____

90) _____

91) _____

92) _____

93) _____

94) _____

95) _____

96) _____

97) _____

98) _____

99) _____

100) _____

- Add Fee:
- Site Insp (\$)
 - Interview (\$)
 - Tech Invs (\$)
 - Weekend (\$)

Survey Fee: _____

Transportation: _____

3) _____

4) _____

5) _____

6) _____

7) _____

8) _____

9) _____

10) _____

11) _____

12) _____

13) _____

14) _____

15) _____

16) _____

17) _____

18) _____

19) _____

20) _____

21) _____

22) _____

23) _____

24) _____

25) _____

26) _____

27) _____

28) _____

29) _____

30) _____

31) _____

32) _____

33) _____

34) _____

35) _____

36) _____

37) _____

38) _____

39) _____

40) _____

41) _____

42) _____

43) _____

44) _____

45) _____

46) _____

47) _____

48) _____

49) _____

50) _____

51) _____

52) _____

53) _____

54) _____

55) _____

56) _____

57) _____

58) _____

59) _____

60) _____

61) _____

62) _____

63) _____

64) _____

65) _____

66) _____

67) _____

68) _____

69) _____

70) _____

71) _____

72) _____

73) _____

74) _____

75) _____

76) _____

77) _____

78) _____

79) _____

80) _____

81) _____

82) _____

83) _____

84) _____

85) _____

86) _____

87) _____

88) _____

89) _____

90) _____

91) _____

92) _____

93) _____

94) _____

95) _____

96) _____

97) _____

98) _____

99) _____

100) _____

CC4/ASMI/9003568/R1pb3
 H3140 TUNE

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
 #01-68 SINGAPORE 575643
 Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)
 Email Address: em1autopteltd@gmail.com
 COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SFD 699S
 Vehicle Model : TOYOTA WISH
 Accident Date : 22.02.2018
 Original Reg Date : 12.02.2026

Date : 25.02.2019
 Chassis : ZGE206030321
 TP Ins. AXA

ESTIMATE

1	1 pc	Front Fender Inner Shield LH W cut		152.40	
2	1 set	Front Fender Inner Shield Clips W		30.00	
3	1 pc	Front Bumper SCA		657.80	
4/1	2 pcs	Front Bumper Side Retainers X LH/RC	72.10	144.20	X RH-SUC
5	1 set	Front Bumper Clips W		50.00	
6	1 pc	Front Bumper Reinforcement W BT		392.50	
7	1 pc	Front Bumper Sponge W CR		182.60	
8	1 pc	Front Bumper Fog Lamp Cover LH DE		92.50	
9	1 pc	Front Bumper Lower Side Grille LH DE		65.00	
10	1 pc	Headlamp HID LH CR		1,150.30	
11	1 set	Headlamps Clips W		20.00	
12	1 pc	Front Grille X SUC		363.50	X
13	1 set	Front Grille Clips X SUC		30.00	X
14	1 pc	Front Door RH PA		1,290.30	
15	1 pc	Front Door Outer Handle RH SCA		89.30	
16	1 pc	Front Door Outer Handle Joint RH SCA		56.00	
17	1 pc	Front Door Outer Moulding RH X SUC		125.60	X
18	2 pcs	Front Door Black Sticker RH W	92.50	185.00	
19	1 pc	Front Door Wind Mirror Assy RH MIS		1,009.10	
20	2 pcs	Front Door Hinges RH X SUC	79.10	158.20	X
21	1 pc	Front Door Checker RH X SUC		79.20	X
22	1 pc	Front Door Inner Lock RH X SUC		485.50	X
23	1 pc	Front Door Weatherstrip RH W		212.50	
24	1 pc	Front Door Regulator Motor RH X SUC		598.20	X
25	1 pc	Front Door Regulator Gear RH X SUC		271.00	X
26	1 pc	Front Door Channel RH X SUC		181.10	X
27	1 pc	Front Door Channel Seal RH X SUC		136.10	X
28	1 pc	Front Door Inner Trim RH X SUC		785.50	X
29	1 set	Front Door Inner Trim Clip X SUC		40.00	X
			C/F	9,033.40	

5707.46

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle NO : SFD 699S

B/F

9,033.40

1	1 pc	Front Door Speaker RH <i>X Svc</i>		221.10	X
2	1 pc	Front Absorber LH <i>? bt</i>		581.40	X
3	1 pc	Front Absorber Mounting LH <i>? X Svc</i>		191.80	X
4	1 pc	Front Lower Arm LH <i>? bt</i>		435.00	X
5	1 pc	Front Knuckle Arm LH <i>? bt</i>		392.70	X
6	1 pc	Front Wheel Bearing LH <i>? bt</i>		199.10	X
7	1 pc	Front Drive Shaft LH <i>X Svc</i>		1,214.40	X
8	1 pc	Front Steering Rack and Pinion <i>? bt</i>		1,565.50	X
9	1 pc	Anti Roll Bar Bush Link LH <i>X Svc</i>		131.10	X
10	1 pc	Rear Door RH <i>BT</i>		1,280.70	X
11	1 pc	Rear Door Outer Moulding RH <i>X Svc</i>		125.60	X
12	2 pcs	Rear Door Black Sticker RH <i>ne</i>	92.50	185.00	X
13	2 pcs	Rear Door Hinges RH <i>(Lower) TH</i>	79.10	158.20	X
14	1 pc	Rear Door Checker RH <i>? H</i>		79.20	X
15	1 pc	Rear Door Inner Lock RH <i>BT</i>		485.50	X
16	1 pc	Rear Door Weatherstrip RH <i>ne</i>		212.50	X
17	1 pc	Rear Door Regulator Motor RH <i>? X Svc</i>		598.20	X
18	1 pc	Rear Door Regulator Gear RH <i>? bt</i>		271.00	X
19	1 pc	Rear Door Channel RH <i>X Svc</i>		181.10	X
20	1 pc	Rear Door Channel Seal RH <i>X Svc</i>		136.10	X
21	1 pc	Rear Door Inner Trim RH <i>? CR</i>		785.50	X
22	1 set	Rear Door Inner Trim Clip <i>ne</i>		40.00	X
23	1 pc	Rear Door Speaker RH <i>? CR</i>		221.10	X
24	1 pc	Rear Windscreen Inner Seal <i>ne X AN</i>		60.00	X
25	2 pcs	Rear Windscreen Moulding <i>ne X AN</i>	112.60	225.20	X
26	1 pc	Rear Bumper Assy <i>ser</i>		826.70	X
27	2 pcs	Rear Bumper Side Retainers <i>RH/ ne</i>	58.10	116.20	X
28	1 set	Rear Bumper Clips <i>ne</i>		50.00	X
29	1 pc	Rear Fender RH <i>BT</i>		587.60	X

C/F

20,590.90

8335.70

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No :SFD 699S

B/F

20,590.90

1	1 pc	Rear Fender Quarter Glass w/Moulding RH net ✓	429.60
2	1 pc	Rear Fender Quarter Glass Inner Seal net ✓	60.00
3	1 pc	Rear Absorber RH X net ✓	211.90
4	1 pc	Rear Wheel Bearing RH net ✓	389.60
5	1 pc	Rear Axle Beam X net ✓	2,017.10

14618.70

25%

10964.02

23,699.10
Less 25% 5,924.78
17,774.33

126
✓
X
✓
X
575.60

Special Nett

1	1 pc	Front Sport Rim LH net ✓	350 550.00
2	1 pc	Front Sport Rim Tyre LH net ✓	700 350.00
5	1 pc	Rear Fender Glass Sealant net ✓	40 60.00
6	1 pc	Rear Sport Rim RH net ✓	350 550.00
7	1 pc	Rear Sport Rim Tyre RH X net ✓	700 X 350.00
8	1 pc	Side Skirt RH net ✓	760 850.00
9	1 set	Side Skirt Clip net ✓	50.00

30
1615
3760

Labour charge

Panel Beating	1400	1800.00
Spray painting	1600	2200.00
Check Wiring	30	50.00
Anti rust	100	180.00
Remove and install carpet and seat.	60	120.00
Remove and install rear fender glass.	80	120.00
Remove and install front & rear doors parts.	120	180.00
Remove and install front & rear undercarriage.	300	600.00
To perform computerize wheel alignment.	70	90.00

25,874.33
5,174.87

Lump sum 20,699.46

10964.02

1615.00

3760.00

16,339.02

20%

13,071.22

12 days

w/ship accept 4/3 - 13,000

ASUL
Hp 90010068
12 days
4/3
26/02/19 @ 1730
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Page 3 of 3

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SFD 699S
 Vehicle Model : TOYOTA WISH
 Accident Date : 22.02.2018
 Original Reg Date : 12.02.2026

Date : 25.02.2019
 Chassis : ZGE206030321
 TP Ins. AXA

ESTIMATE

1	1 pc	Front Fender Inner Shield LH 2 ?		152.40
2	1 set	Front Fender Inner Shield Clips 2 /		30.00
3	1 pc	Front Bumper 5 /		657.80
4/1	2 pcs	Front Bumper Side Retainers X LH / me	72.10	144.20
5	1 set	Front Bumper Clips me /		50.00
6	1 pc	Front Bumper Reinforcement ?		392.50
7	1 pc	Front Bumper Sponge ?		182.60
8	1 pc	Front Bumper Fog Lamp Cover LH DE /		92.50
9	1 pc	Front Bumper Lower Side Grille LH DE /		65.00
10	1 pc	Headlamp HID LH CR /		1,150.30
11	1 set	Headlamps Clips me /		20.00
12	1 pc	Front Grille X		363.50
13	1 set	Front Grille Clips X		30.00
14	1 pc	Front Door RH FA /		1,290.30
15	1 pc	Front Door Outer Handle RH 5 /		89.30
16	1 pc	Front Door Outer Handle Joint RH 50 /		56.00
17	1 pc	Front Door Outer Moulding RH X		125.60
18	2 pcs	Front Door Black Sticker RH me /	92.50	185.00
19	1 pc	Front Door Wind Mirror Assy RH MIS /		1,009.10
20	2 pcs	Front Door Hinges RH X	79.10	158.20
21	1 pc	Front Door Checker RH X		79.20
22	1 pc	Front Door Inner Lock RH X		485.50
23	1 pc	Front Door Weatherstrip RH me /		212.50
24	1 pc	Front Door Regulator Motor RH X		598.20
25	1 pc	Front Door Regulator Gear RH X		271.00
26	1 pc	Front Door Channel RH X		181.10
27	1 pc	Front Door Channel Seal RH X		136.10
28	1 pc	Front Door Inner Trim RH X		785.50
29	1 set	Front Door Inner Trim Clip X		40.00

C/F

9,033.40

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle NO : SFD 699S

B/F

9,033.40

1	1 pc	Front Door Speaker RH X		221.10
2	1 pc	Front Absorber LH ?		581.40
3	1 pc	Front Absorber Mounting LH ?		191.80
4	1 pc	Front Lower Arm LH ?		435.00
5	1 pc	Front Knuckle Arm LH ?		392.70
6	1 pc	Front Wheel Bearing LH ?		199.10
7	1 pc	Front Drive Shaft LH X		1,214.40
8	1 pc	Front Steering Rack and Pinion ?		1,565.50
9	1 pc	Anti Roll Bar Bush Link LH X		131.10
10	1 pc	Rear Door RH BH/		1,280.70
11	1 pc	Rear Door Outer Moulding RH X		125.60
12	2 pcs	Rear Door Black Sticker RH ne/	92.50	185.00
13	2 pcs	Rear Door Hinges RH (Lower) BH/	79.10	158.20
14	1 pc	Rear Door Checker RH ?		79.20
15	1 pc	Rear Door Inner Lock RH BH/		485.50
16	1 pc	Rear Door Weatherstrip RH ne/		212.50
17	1 pc	Rear Door Regulator Motor RH ?		598.20
18	1 pc	Rear Door Regulator Gear RH ?		271.00
19	1 pc	Rear Door Channel RH X		181.10
20	1 pc	Rear Door Channel Seal RH X		136.10
21	1 pc	Rear Door Inner Trim RH ?		785.50
22	1 set	Rear Door Inner Trim Clip ne/		40.00
23	1 pc	Rear Door Speaker RH ?		221.10
24	1 pc	Rear Windscreen Inner Seal ne X		60.00
25	2 pcs	Rear Windscreen Moulding ne X	112.60	225.20
26	1 pc	Rear Bumper Assy SER/		826.70
27	2 pcs	Rear Bumper Side Retainers RH/ne	58.10	116.20
28	1 set	Rear Bumper Clips ne/		50.00
29	1 pc	Rear Fender RH BH/		587.60

C/F

20,590.90

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No :SFD 699S

B/F

20,590.90

1	1 pc	Rear Fender Quarter Glass w/Moulding RH <i>ne /</i> <i>Cphoto</i>	429.60
2	1 pc	Rear Fender Quarter Galss Inner Seal <i>ne /</i>	60.00
3	1 pc	Rear Absorber RH <i>X</i>	211.90
4	1 pc	Rear Wheel Bearing RH <i>ne /</i>	389.60
5	1 pc	Rear Axle Beam <i>X</i>	2,017.10
			23,699.10
			Less 25% <u>5,924.78</u>
			17,774.33

Special Nett

1	1 pc	Front Sport Rim LH <i>500 /</i>	350 550.00
2	1 pc	Front Sport Rim Tyre LH	700 350.00 <i>@ net</i>
5	1 pc	Rear Fender Glass Sealant	40 60.00
6	1 pc	Rear Sport Rim RH	350 550.00
7	1 pc	Rear Sport Rim Tyre RH	700 350.00 <i>price?</i>
8	1 pc	Side Skirt RH	7600 850.00
9	1 set	Side Skirt Clip	ne / 50.00 <i>30</i>

Labour charge

Panel Beating	1400 1800.00
Spray painting	1600 2200.00
Check Wiring	30 50.00
Anti rust	100 180.00
Remove and install carpet and seat.	60 120.00
Remove and install rear fender glass.	80 120.00
Remove and install front & rear doors parts.	120 180.00
Remove and install front & rear undercarriage.	300 600.00
To perform computerize wheel alignment.	70 90.00

25,874.33

5,174.87

Lump sum 20,699.46

RASUL

Hp 90010068

12 days

4/5

26/02/19 @ 1730

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5040D
Vehicle Details	
Vehicle No.:	SFD699S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	2ZR1732809
Chassis No.:	ZGE206030321
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,085.00
Original Registration Date:	13 Jun 2016
First Registration Date:	13 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,085.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2026
PARF Rebate Amount:	\$14,313.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,156.00
COE Rebate Amount:	\$35,868.00
Total Rebate Amount:	\$50,181.00

The information contained herein is correct as at 25 Feb 2019

OK

78,000
50,181

27,819

km-1

Service Request Details

Claim

S9M01F4N

Reference

None 

Loss Date

February 22, 2019

Report Date

Feb 26, 2019 8:56:30 AM

Request Date

February 26, 2019

Due Date

February 26, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work	More 
---------------	--

Vehicle Information

Incident Vehicle Registration #

SFD6995

Make

TPVD

Model

TOYOTA

Primary Contact/Insured

VEOLIA ES SINGAPORE PTE LTD
17 TUAS AVENUE 12, 639037, Singapore
66810302
sookchan.ho@veolia.com

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

- Messages
 - Invoices
 - History
 - Documents
 - Assessment
 - Metrics
 - Notes
-

Please Add Content

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 26 February 2019 9:18 AM
To: assignments
Cc: Admin A
Subject: FW: ARRANGE SURVEY SFD 699S DOA 22.02.2019 YOUR REF : XE113Y
Attachments: 699-25022019160335.pdf

11.28am @ 26/2/19
vehicle in
Mr. Chen's
agreed Rapid survey.

SMARTCLAIM NEW CASE

Kindly arrange. TQ

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Monday, 25 February 2019 4:11 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: ARRANGE SURVEY SFD 699S DOA 22.02.2019 YOUR REF : XE113Y

WITHOUT PREJUDICE

Dear All,

Kindly arrange survey our client's vehicle at our workshop.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Your Vehicle: XE113S (3rd Party Vehicle)

Our Vehicle: SFD699S

Date: 25/2/19

M/s AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

By email
motor.survey@axa.com.sg
only

Dear Sir/Madam,

ACCIDENT INVOLVING SFD699S & XE113Y ON 22/2/19

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair survey of vehicle
SFD699S at my premises.

Yours faithfully

CWS

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Friday, 27 September 2019 9:49 AM
To: Chia Sin Muk
Cc: Admin A; Rasul (LKKAuto); Hsiao Tong (LKKAuto)
Subject: FW: LOD - SFD 699S, your ref. no. XE113Y, DOA : 22.02.2019
Attachments: SFD699S, AXA LOD-26092019103556.pdf

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/ASM19003568/R1pb3	Hsiao Tong

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Thursday, 26 September 2019 10:37 AM
To: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: LOD - SFD 699S, your ref. no. XE113Y, DOA : 22.02.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find attached LOD.

COR : \$ 13,910.00
TOW : \$ 80.00
LTA : \$ 7.45
GIA : \$ 29.00
LOR : \$ 1,530.10 (11 days x \$130 + GST)

Total : \$ 15,556.55
=====

Kindly arrange for settlement.

Thanks & Best Regards,

Karen, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately, you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

Hsiao Tong (LKKAuto)

From: Lim, Yong Hong <yonghong.lim@veolia.com>
Sent: Friday, 7 February 2020 4:08 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: FW: ACCIDENT INVOLVING XE 113Y(AXA) AND SFD 699S ALONG/AT TUAS SOUTH AVE 1 ON 22/02/2019
Attachments: 1162_001.pdf

Dear Ms Chew,

My sincere apologies for the late return,

Please find attached letter of authorization for your handling.

Thanks

Leonard

On Monday, 3 February 2020, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Dear Sirs/Mdm,

We refer to our email dated 21/09/2019.

We would like to follow up on the following documents: -

- Copy of the letter of authorization to confirm that the driver is allow to drive the vehicle.
- Driver's driving license or foreign driving license (if any)

Thank you.

"Wishing you a Happy and Prosperous New Year"



Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 21 September 2019 8:36 AM

To: DORA.THE@VEOLIA.COM

Subject: ACCIDENT INVOLVING XE 113Y(AXA) AND SFD 699S ALONG/AT TUAS SOUTH AVE 1 ON 22/02/2019

21 Sept 2019

M/s VEOLIA ES SINGAPORE PTE. LTD

Dear Sir/ Mdm

OUR REF : CC4/ASM19003568/R1pb3// S9M01F4N

YOUR REF : XE113Y

ACCIDENT INVOLVING XE 113Y(AXA) AND SFD 699S ALONG/AT TUAS SOUTH AVE 1 ON 22/02/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from EM-1 AUTO PTE LTD acting on behalf of the owner of SFD699S against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your driver favour as your driver changed lane and collided with third party. Under Motor Accident Guide, vehicles should keep in the proper lane and change lane only when it is safe. As such, we shall proceed to negotiate for an amicable settlement of the third party claim at best to avoid further litigation, which would escalate to even more cost.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy. We also wish to inform you that Section II of the Motor Insurance Policy is attached, and capped, with an excess of \$5,000.00 for third party claim settlements.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 7 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's work permit/ work pass
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Copy of the letter of authorization / Employment Letter
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or chewht@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

--
Lim Yong Hong Leonard
Assistant Manager (Contract Support)
PUBLIC CLEANSING DEPT

off: +65 63059185 / fax: +65 62685545
23 Pandan Avenue, Singapore 609389
www.veolia.com.sg



22 February 2019

To whom it may concern:

AUTHORIZATION LETTER

Dear Sir/Madam,

We, from Veolia ES Singapore Pte Ltd, the owner of vehicle number XE 113 Y certify that Mr. Hamzah Bin Puteh, S0108980 C is employed by us as a Driver and authorized to drive the said vehicle

Thank you.

With Regards,



.....
Vicky.Waran
Assistant Operation Manager
Veolia ES Singapore Pte Ltd



<TP - Mandate IA> - S9M01F4N [ACCIDENT INVOLVING XE 113Y(OI) & SFD 699S(TP) ON 22/02/2019]

Type

🗉 Question

Message

Liability: 100%. Insured driver changed lane and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$15,438.85(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 9-Mar-2020

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 09/03/2020

Survey Details:

Date of loss	22-Feb-19
Date of appointment	26-Feb-19
Date of survey	26-Feb-19
Location of survey	EM-1 AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SFD 699S
Make and Model	TOYOTA WISH 1.8X A
Date of registration	13/6/2016
Excess	
Market Value	\$78,000
Parf Rebate	\$50,181
Nett Loss	\$27,819

Repair details:

Initial Estimate	\$	20,699.46
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$	12,579.03
Check items (estimate)		NIL
Labour	\$	3,760.00
Total	\$	16,339.03
Lump Sum(if applicable)	\$	13,000.00

Number of days for repair		12
----------------------------------	--	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID changed lane and collided with third party.

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	13,910.00	
Loss of use		NIL	no. of days
Loss of rental (w/GST)	\$	1,412.40	(11days x \$120.00)
Loss of income		NIL	no. of days
LTA search fees	\$	36.45	
Others (Towing Fee)	\$	80.00	
Proposed Total	\$	15,438.85	



Re:<TP - Mandate IA> - S9M01F4N [ACCIDENT INVOLVING XE 113Y(OI) & SFD 699S(TP) ON 22/02/2019]

Type

 Question

Message

COR \$13,161.00 W/GST LOR \$1,412.40 LTA \$36.45 TOTAL \$14,609.85

Reply

Hsiao Tong (LKKAuto)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Thursday, 12 March 2020 5:18 PM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: Re: LOD - SFD 699S, your ref. no. XE113Y, DOA : 22.02.2019 //LKK REF: CC4/ASM19003568/R1pb3

WITHOUT PREJUDICE

Dear Hsiao Tong,

We confirmed acceptance of your Global offer S\$14,500.00 (all-in).
Kindly proceed to arrange payment/DV to **EM-1 AUTO PTE LTD.**

Thanks & Best Regards,

Karen, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Thu, 12 Mar 2020 at 08:35, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$14,500.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice

engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 27 September 2019 9:49 AM
To: Chia Sin Muk <em1autopteltd@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FW: LOD - SFD 699S, your ref. no. XE113Y, DOA : 22.02.2019

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/ASM19003568/R1pb3	Hsiao Tong

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chia Sin Muk <em1autopteltd@gmail.com>

Sent: Thursday, 26 September 2019 10:37 AM

To: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: LOD - SFD 699S, your ref. no. XE113Y, DOA : 22.02.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find attached LOD.

COR : \$ 13,910.00
TOW : \$ 80.00
LTA : \$ 7.45
GIA : \$ 29.00
LOR : \$ 1,530.10 (11 days x \$130 + GST)

Total : \$ 15,556.55
=====

Kindly arrange for settlement.

Thanks & Best Regards,

Karen, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY/ GST REG. NO: 201316380R

TAX INVOICE

M/S TAN PENG SENG

Invoice No : 20/00053/5404TPG

Date : 16-Mar-2020

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn : Ms Hsiao Tong

Date of Accident : 22-Feb-2019
Our Client's Vehicle Number : SFD 699S
Vehicle Make/ Model : TOYOTA WISH
Your Insurer : XE 113Y

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Global Sum (for property claim only)	13,551.40	948.60	14,500.00 SR

* Including loss of rental
& search fee


SGD (Fourteen Thousand Five Hundred only)

GRAND TOTAL

14,500.00

Subject to 7% GST

948.60



Authorised Signature and Company Stamp

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY/ GST REG. NO: 201316380R

M/S TAN PENG SENG

Lod : 19/PI00132/5404TP

Date : 25-Sep-2019

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn : Mr. Rasul

Date of Accident : 22-Feb-2019
Our Client's Vehicle Number : SFD 699S
Vehicle Make/ Model : TOYOTA WISH
Your Insurer : XE 113Y

Without Prejudice

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost(Recommend by LKK Rasul).	13,000.00	910.00	13,910.00 SR
Towing Fee	80.00		80.00 ES
LTA Fee	6.97	0.49	7.46 SR
GIA Fee	27.10	1.90	29.00 SR
Loss of Rental(11 days X \$130)	1,430.00	100.10	1,530.10 SR

SGD (Fifteen Thousand Five Hundred Fifty-Six And Cents
Fifty-Five only)

GRAND TOTAL


15,556.55

Subject to 7% GST

1,012.48



Authorised Signature and Company Stamp



MAXXIS RECOVERY

60 Punggol Walk #11-23
 Singapore 828780
 Co. Reg. No: 53239862M
 Email: maxxix_recovery@yahoo.com.sg
 H/P : + 65 9488 8856

No.: 9822

Date: 22/02/19

CASH SALES / WORK ORDER

Messrs: CASH

Vehicle No: SFD 6993 Model No: TOYOTA WISH

From: TUAS WEST DR

To: SIN MING

Time: (day/night) _____ Order by: _____

Cash \$: 80/- Remarks: _____

Issued by: [Signature] Received by: _____

Note: The recipient of service or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damage(s) to the car nor missing item(s) from the same.

- Accident / Overturn
- Crane Up / Winch Out
- Door Opening Service
- Jump Start
- King Dolly
- Low Body Kit
- Multi/Basement Carpark
- Transport Charge
- Tyre Replacement
- With Load / Cargo Box



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19003568/R1pa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN		Date : 20-03-2020	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 113Y	Veh. Inspected	SFD 699S
Policy No.	VFX/P1582555	Coverage (\$)	0.00
Claim No.	S9M01F4N	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	26/02/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH 1.8X A	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZGE206030321	Colour	PURPLE
Odometer	78811	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	TOYO	6 mm
L/H Front Tyre	195/65 R15	TOYO	6 mm
R/H Rear Tyre	195/65 R15	TOYO	6 mm
L/H Rear Tyre	195/65 R15	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/02/2019	Inspection Date	26/02/2019
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 699S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER INNER SHIELD LH (CONSISTENT)	CUT	152.40	152.40
1	SET FRONT FENDER INNER SHIELD CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT BUMPER (CONSISTENT)	SCRATCHED	657.80	657.80
2	FRONT BUMPER SIDE RETAINERS @ \$72.10 (CONSISTENT)	N/S NECESSARY / O/S SERVICEABLE	144.20	72.10
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	392.50	392.50
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	182.60	182.60
1	FRONT BUMPER FOG LAMP COVER LH (CONSISTENT)	DEFORMED	92.50	92.50
1	FRONT BUMPER LOWER SIDE GRILLE LH (CONSISTENT)	DEFORMED	65.00	65.00
1	HEADLAMP HID LH (CONSISTENT)	CRACKED	1,150.30	1,150.30
1	SET HEADLAMPS CLIPS (CONSISTENT)	NECESSARY	20.00	20.00
1	FRONT GRILLE (CONSISTENT)	SERVICEABLE	363.50	-
1	SET FRONT GRILLE CLIPS (CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT DOOR RH (CONSISTENT)	BENT	1,290.30	1,290.30
1	FRONT DOOR OUTER HANDLE RH (CONSISTENT)	SCRATCHED	89.30	89.30
1	FRONT DOOR OUTER HANDLE JOINT RH (CONSISTENT)	SCRATCHED	56.00	56.00
1	FRONT DOOR OUTER MOULDING RH (CONSISTENT)	SERVICEABLE	125.60	-
2	FRONT DOOR BLACK STICKER RH @ \$92.50 (CONSISTENT)	NECESSARY	185.00	185.00
1	FRONT DOOR WIND MIRROR ASSY RH (CONSISTENT)	MISSING	1,009.10	1,009.10
2	FRONT DOOR HINGES RH @ \$79.10 (CONSISTENT)	SERVICEABLE	158.20	-
1	FRONT DOOR CHECKER RH (CONSISTENT)	SERVICEABLE	79.20	-
1	FRONT DOOR INNER LOCK RH (CONSISTENT)	SERVICEABLE	485.50	-
1	FRONT DOOR WEATHERSTRIP RH (CONSISTENT)	NECESSARY	212.50	212.50
1	FRONT DOOR REGULATOR MOTOR RH (CONSISTENT)	SERVICEABLE	598.20	-
1	FRONT DOOR REGULATOR GEAR RH (CONSISTENT)	SERVICEABLE	271.00	-
1	FRONT DOOR CHANNEL RH (CONSISTENT)	SERVICEABLE	181.10	-
1	FRONT DOOR CHANNEL SEAL RH (CONSISTENT)	SERVICEABLE	136.10	-
1	FRONT DOOR INNER TRIM RH (CONSISTENT)	SERVICEABLE	785.50	-
1	SET FRONT DOOR INNER TRIM CLIP (CONSISTENT)	SERVICEABLE	40.00	-

Report Ref No. CC4/ASM19003568/R1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR SPEAKER RH (CONSISTENT)	SERVICEABLE	221.10	-
1	FRONT ABSORBER LH (CONSISTENT)	BENT	581.40	581.40
1	FRONT ABSORBER MOUNTING LH (CONSISTENT)	SERVICEABLE	191.80	-
1	FRONT LOWER ARM LH (CONSISTENT)	BENT	435.00	435.00
1	FRONT KNUCKLE ARM LH (CONSISTENT)	BENT	392.70	392.70
1	FRONT WHEEL BEARING LH (CONSISTENT)	BENT	199.10	199.10
1	FRONT DRIVE SHAFT LH (CONSISTENT)	SERVICEABLE	1,214.40	-
1	FRONT STEERING RACK AND PINION (CONSISTENT)	BENT	1,565.50	1,565.50
1	ANTI ROLL BAR BUSH LINK LH (CONSISTENT)	SERVICEABLE	131.10	-
1	REAR DOOR RH (CONSISTENT)	BENT	1,280.70	1,280.70
1	REAR DOOR OUTER MOULDING RH (CONSISTENT)	SERVICEABLE	125.60	-
2	REAR DOOR BLACK STICKER RH @ \$92.50 (CONSISTENT)	NECESSARY	185.00	185.00
2	REAR DOOR HINGES RH @ \$79.10 (CONSISTENT)	LOWER BENT	158.20	79.10
1	REAR DOOR CHECKER RH (CONSISTENT)	BENT	79.20	79.20
1	REAR DOOR INNER LOCK RH (CONSISTENT)	BENT	485.50	485.50
1	REAR DOOR WEATHERSTRIP RH (CONSISTENT)	NECESSARY	212.50	212.50
1	REAR DOOR REGULATOR MOTOR RH (CONSISTENT)	SERVICEABLE	598.20	-
1	REAR DOOR REGULATOR GEAR RH (CONSISTENT)	BENT	271.00	271.00
1	REAR DOOR CHANNEL RH (CONSISTENT)	SERVICEABLE	181.10	-
1	REAR DOOR CHANNEL SEAL RH (CONSISTENT)	SERVICEABLE	136.10	-
1	REAR DOOR INNER TRIM RH (CONSISTENT)	CRACKED	785.50	785.50
1	SET REAR DOOR INNER TRIM CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR DOOR SPEAKER RH (CONSISTENT)	CRACKED	221.10	221.10
1	REAR WINDSCREEN INNER SEAL (CONSISTENT)	NOT NECESSARY	60.00	-
2	REAR WINDSCREEN MOULDING @ \$112.60 (CONSISTENT)	NOT NECESSARY	225.20	-
1	REAR BUMPER ASSY (CONSISTENT)	SCRATCHED	826.70	826.70
2	REAR BUMPER SIDE RETAINERS @ \$58.10 (CONSISTENT)	O/S NECESSARY	116.20	58.10
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR FENDER RH (CONSISTENT)	BENT	587.60	587.60
1	REAR FENDER QUARTER GLASS W/MOULding RH (CONSISTENT)	NECESSARY	429.60	126.00

Report Ref No. CC4/ASM19003568/R1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER QUARTER GLASS INNER SEAL (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR ABSORBER RH (CONSISTENT)	SERVICEABLE	211.90	-
1	REAR WHEEL BEARING RH (CONSISTENT)	NECESSARY	389.60	389.60
1	REAR AXLE BEARING (CONSISTENT)	SERVICEABLE	2,017.10	-
	LESS 25% DISCOUNT		-5,924.77	-3,654.67
			17,774.33	10,964.03
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT SPORT RIM LH (SN) (CONSISTENT)	SCRATCHED	550.00	350.00
1	FRONT SPORT RIM TYRE LH (@ \$350.00 DISC 70%) (SN) (CONSISTENT)	CUT	350.00	245.00
1	REAR FENDER GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	REAR SPORT RIM RH (SN) (CONSISTENT)	NECESSARY	550.00	350.00
1	REAR SPORT RIM TYRE RH (SN) (CONSISTENT)	SERVICEABLE	350.00	-
1	SIDE SKIRT RH (SN) (CONSISTENT)	NECESSARY	850.00	600.00
1	SET SIDE SKIRT CLIP (SN) (CONSISTENT)	NECESSARY	50.00	30.00
			2,760.00	1,615.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,800.00	1,400.00
	SPRAY PAINTING.		2,200.00	1,600.00
	CHECK WIRING.		50.00	30.00
	ANTI RUST.		180.00	100.00
	REMOVE AND INSTALL CARPET AND SEAT.		120.00	60.00
	REMOVE AND INSTALL REAR FENDER GLASS.		120.00	80.00
	REMOVE AND INSTALL FRONT & REAR DOOR PARTS.		180.00	120.00
	REMOVE AND INSTALL FRONT & REAR UNDERCARRIAGE.		600.00	300.00
	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT.		90.00	70.00
			5,340.00	3,760.00
	GRAND TOTAL		25,874.33	16,339.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,000.00

Report Ref No. CC4/ASM19003568/R1pa3s2



Report Ref No. CC4/ASM19003568/R1pa3s2

A handwritten signature in black ink, consisting of the letters 'MRB' in a stylized, cursive font.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan' in a cursive style.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.