

HS190 Tunk

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SFD 699S
 Vehicle Model : TOYOTA WISH
 Accident Date : 22.02.2018
 Original Reg Date : 12.02.2026

Date : 25.02.2019
 Chassis : ZGE206030321
 TP Ins. AXA

ESTIMATE

1	1 pc	Front Fender Inner Shield LH 2 cut		152.40	/
2	1 set	Front Fender Inner Shield Clips 2 pc		30.00	/
3	1 pc	Front Bumper SCA		657.80	/
4/1	2 pcs	Front Bumper Side Retainers LH/RH	72.10	144.20	X RH-SUC
5	1 set	Front Bumper Clips 2 pc		50.00	/
6	1 pc	Front Bumper Reinforcement 1 pc		392.50	/
7	1 pc	Front Bumper Sponge 1 pc		182.60	/
8	1 pc	Front Bumper Fog Lamp Cover LH DE		92.50	/
9	1 pc	Front Bumper Lower Side Grille LH DE		65.00	/
10	1 pc	Headlamp HID LH CRS		1,150.30	/
11	1 set	Headlamps Clips 2 pc		20.00	/
12	1 pc	Front Grille X SUC		363.50	X
13	1 set	Front Grille Clips X SUC		30.00	X
14	1 pc	Front Door RH PA		1,290.30	/
15	1 pc	Front Door Outer Handle RH SCA		89.30	/
16	1 pc	Front Door Outer Handle Joint RH SUC		56.00	/
17	1 pc	Front Door Outer Moulding RH X SUC		125.60	X
18	2 pcs	Front Door Black Sticker RH 2 pc	92.50	185.00	/
19	1 pc	Front Door Wind Mirror Assy RH MIS		1,009.10	/
20	2 pcs	Front Door Hinges RH X SUC	79.10	158.20	X
21	1 pc	Front Door Checker RH X SUC		79.20	X
22	1 pc	Front Door Inner Lock RH X SUC		485.50	X
23	1 pc	Front Door Weatherstrip RH 2 pc		212.50	/
24	1 pc	Front Door Regulator Motor RH X SUC		598.20	X
25	1 pc	Front Door Regulator Gear RH X SUC		271.00	X
26	1 pc	Front Door Channel RH X SUC		181.10	/
27	1 pc	Front Door Channel Seal RH X SUC		136.10	X
28	1 pc	Front Door Inner Trim RH X SUC		785.50	/
29	1 set	Front Door Inner Trim Clip X SUC		40.00	X

C/F

9,033.40

5707.40

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle NO : SFD 699S

B/F

9,033.40

1	1 pc	Front Door Speaker RH <i>X suc</i>		221.10	X
2	1 pc	Front Absorber LH <i>? bt</i>		581.40	X
3	1 pc	Front Absorber Mounting LH <i>? X suc</i>		191.80	X
4	1 pc	Front Lower Arm LH <i>? bt</i>		435.00	X
5	1 pc	Front Knuckle Arm LH <i>? bt</i>		392.70	X
6	1 pc	Front Wheel Bearing LH <i>? bt</i>		199.10	X
7	1 pc	Front Drive Shaft LH <i>X suc</i>		1,214.40	X
8	1 pc	Front Steering Rack and Pinion <i>? bt</i>		1,565.50	X
9	1 pc	Anti Roll Bar Bush Link LH <i>X suc</i>		131.10	X
10	1 pc	Rear Door RH <i>BT</i>		1,280.70	X
11	1 pc	Rear Door Outer Moulding RH <i>X suc</i>		125.60	X
12	2 pcs	Rear Door Black Sticker RH <i>ne</i>	92.50	185.00	X
13	2 pcs	Rear Door Hinges RH (Lower) <i>BT</i>	79.10	158.20	X
14	1 pc	Rear Door Checker RH <i>? bt</i>		79.20	X
15	1 pc	Rear Door Inner Lock RH <i>BT</i>		485.50	X
16	1 pc	Rear Door Weatherstrip RH <i>ne</i>		212.50	X
17	1 pc	Rear Door Regulator Motor RH <i>? X suc</i>		598.20	X
18	1 pc	Rear Door Regulator Gear RH <i>? bt</i>		271.00	X
19	1 pc	Rear Door Channel RH <i>X</i>		181.10	X
20	1 pc	Rear Door Channel Seal RH <i>X</i>		136.10	X
21	1 pc	Rear Door Inner Trim RH <i>BT</i>		785.50	X
22	1 set	Rear Door Inner Trim Clip <i>ne</i>		40.00	X
23	1 pc	Rear Door Speaker RH <i>? BT crn</i>		221.10	X
24	1 pc	Rear Windscreen Inner Seal <i>ne X BT</i>		60.00	X
25	2 pcs	Rear Windscreen Moulding <i>ne X BT</i>	112.60	225.20	X
26	1 pc	Rear Bumper Assy <i>SER</i>		826.70	X
27	2 pcs	Rear Bumper Side Retainers <i>RH/ne</i>	58.10	116.20	X
28	1 set	Rear Bumper Clips <i>ne</i>		50.00	X
29	1 pc	Rear Fender RH <i>BT</i>		587.60	X

C/F

20,590.90

8335.70

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No :SFD 699S

B/F

20,590.90

1	1 pc	Rear Fender Quarter Glass w/Moulding RH RM ✓	429.60	126
2	1 pc	Rear Fender Quarter Glass Inner Seal RM ✓	60.00	✓
3	1 pc	Rear Absorber RH X SUN ✓	211.90	X
4	1 pc	Rear Wheel Bearing RH RM ✓	389.60	✓
5	1 pc	Rear Axle Beam X ✓	2,017.10	X

14618.70

23,699.10

Less 25%

5,924.78

17,774.33

25%

10964.02

575.60

Special Nett

1	1 pc	Front Sport Rim LH SUN ✓	350	550.00	✓
2	1 pc	Front Sport Rim Tyre LH	70	350.00	✓
5	1 pc	Rear Fender Glass Sealant	40	60.00	✓
6	1 pc	Rear Sport Rim RH	350	550.00	✓
7	1 pc	Rear Sport Rim Tyre RH X SUN ✓	70	350.00	X
8	1 pc	Side Skirt RH	70	350.00	✓
9	1 set	Side Skirt Clip	RM	50.00	✓

8265

7122?

30 / 1615

Labour charge

Panel Beating	1400	1800.00	✓
Spray painting	1600	2200.00	✓
Check Wiring	30	50.00	✓
Anti rust	100	180.00	✓
Remove and install carpet and seat.	60	120.00	✓
Remove and install rear fender glass.	80	120.00	✓
Remove and install front & rear doors parts.	120	180.00	✓
Remove and install front & rear undercarriage.	300	600.00	✓
To perform computerize wheel alignment.	70	90.00	✓

3760

25,874.33

5,174.87

Lump sum

20,699.46

10964.02

1615.00

3760.00

16,339.02

20%

13,071.22

12 days

w/ship accept 45. 13,000

RASUL
Hp 90010068

12 days

45

26/02/19 @ 1730

Requ after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Quotations are subject to confirmation.
- Final survey is on a "Without Prejudice" basis
- Final repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Approved by Repairer

Page 3 of 3