

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Feb-19

lmp

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6028 X

1 pc	Front bumper <i>X repair</i>	\$	531.00
1 pc	Front bumper emblem @ \$44.00 <i>X</i>	\$	44.00
1 pc	Front bumper n/s & o/s side retainer @ \$16.00 <i>X</i>	\$	32.00
1 pc	Front n/s fender @ \$384.00 <i>X repair</i>	\$	384.00
1 pc	n/s mirror assy @ \$590.00 <i>X repair</i>	\$	590.00
		\$	1,581.00
		Less 10%	\$ 158.10
			<u>\$ 1,422.90</u>

S/NETT

1 set	Front bumper clips <i>X</i>	\$	48.00
1 pc	Front n/s fender sticker <i>X</i>	\$	30.00

Sundry

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~50.00~~ *20*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

\$ ~~180.00~~ *X*

To putty and spray painting on front bumper, front n/s fender, n/s side mirror

\$ ~~750.00~~ *400*

To apply rustproofing on the repaired and replaced panels.

\$ ~~600.00~~ *410*

\$ ~~120.00~~ *X*

\$ 3,200.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalwilly
N 25/2/19 1020h
2 hrs
4/5
After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before refit/spray painting
- To display damaged parts during resurvey
- Parts prices are to be on a "no prejudice" basis
- Third party survey on a "no prejudice" basis
- No illegal modification is allowed
- Supplementary cost of repair is reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: