

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

CH/22

25-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8034 B

1 pc	o/s head lamp	X	\$	1,028.00
1 pc	Front bumper emblem	/	\$	44.00
1 pc	Front bumper	X repair	\$	531.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	1/1x o/s	\$	32.00
1 pc	Front o/s fender	/	\$	384.00
1 pc	Front o/s fender inner shield	X	\$	120.00
1 pc	Front o/s door	/	\$	791.00
1 pc	Front o/s door regulator	?	\$	290.00
2 pcs	Front o/s door hinges @ \$34.00	X	\$	68.00
1 pc	Front o/s rim	X	\$	246.00
1 pc	O/s wing mirror assy	X repair	\$	590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

S/NETT

1 set	Front o/s fender inner shield clips	X	\$	28.00
1 set	Front bumper clips	X	\$	48.00
1 pc	Front o/s fender sticker	X	\$	30.00
1 pc	Tyre	X	\$	200.00
1 pc	o/s door stickers	/	\$	100.00

Acknowledged by Repairer
Signature:
Date:

Kalin LKK

25/2/19 1050h

3 Pcs

After Repair photo

Sundry		\$	50.00
To check wheel alignment		\$	80.00 X
To dismantle / refit inner components of the front o/s door onto new shell door		\$	150.00 50
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$	400.00 X
To putty and spray painting on front bumper, front o/s fender, front o/s door, o/s wing mirror cover		\$	590.00
To apply rustproofing on the repaired and replaced panels.		\$	150.00 50
		\$	6,127.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.