



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327N
GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR ANG HAW SIANG BRANDON (HONG HAOXIANG) 706 UPPER CHANGI ROAD EAST #03-0 SINGAPORE 486836 Contact No Mobile: 98303215	Cust No/Name /MR ANG HAW SIANG BRANDON (HONG Reg No/Reg Date SLT6945L / 08/11/2017 Date In/Mileage / 0 Chassis No VF7KFBH2TGS504077 Engine No 10JBHC3052271 Make/Model CIT/DS5 1.6 BLUEHDI 120 EAT6 SO CHIC Colour/Trim 9GP GRIS HURRICANE / 3JF MISTRAL CLAUDIA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	25/02/2019/ 22:06		465 / Tay Jian Ye	14161

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER, REAR RH DOOR, REPAIR REAR RH FENDER, FRT RH DO				1800 2400.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, REAR FENDER RH, REAR RH DOOR, FRT RH DOOR				1680 2100.00
E PNT88000 TO TRANSFER REAR RH DOOR TRIM, GLASS, MECHANISM TO NEW PART				2. 550.00
E PNT88000 TO TRANSFER REAR PARKING SENSOR TO NEW PART				60. 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				20 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 300.00
M SUNDRY TO APPLY ANTI CORROSION				60. 80.00
M SUNDRY TO APPLY BODY SEALANT				✓ 40.00
M SUNDRY SUNDRIES				✓ 20.00
M REAR BUMPER	1.00	1129.00	0.00	de 1129.00
M BRACKET SET	1.00	111.00	0.00	3 111.00
M SET REINFORFORC	1.00	173.00	0.00	3 173.00
M LOW RR PAN FIX	1.00	121.00	0.00	nei 121.00
M REAR DOOR RH ASS	1.00	1241.00	0.00	ht 1241.00
M MOULDING RH	1.00	237.00	0.00	inf 237.00
M DECOR STRIP RH	1.00	156.00	0.00	ant 156.00
M TRIM RH	1.00	114.00	0.00	7 114.00
M MOULDING RH FRT	1.00	299.00	0.00	ant 299.00

SURVEYOR NAME: Tay Jian YeSURVEYOR SIGNATURE: [Signature]DATE: 15/3/19REMARKS: Resurvey before paint
sure (warranty) 06 days

Confirm & accepted by:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized Signatory and company stamp

No illegal modification(s) is allowed

Parts	3,581.00
Labour	5,480.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	140.00
Total (w/o GST)	9,201.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date: