

ASS. REC. BY:

REF: 08/FCI19003580/Eq/d3/n2

Special Instruction:

SURVEYOR:

ASSIGNMENT (Office)

CWS

From (Person):

Henry Kao

of

FCI

Date/Time: 5:52pm @ 26/2/19

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLH 1416T

Insured:

SHB 2626B

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

D19000909 MFSH

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

2/2/19

CA / REV / REP. / REV 24 HRS / DS'

H.O.D. Endorsement:

Date/Time:

10:54am @ 26/2/19

Person Contacted:

caroline

Vehicle IN/

OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 1416T-X

SHB 2626B - NS/INC 15022011/Hlg/bn2

D.O.A. 21/2/19

11/3/19 @ 11:52pm revised to Henry Kao by email.

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.


Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLH 1416T** Yr Regn: **25/10/16**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **BMW 116 D** C.C. **1496**
 Colour: **Blue** A/C Insured / Std / NI / NA
 Sp. Reading: **47068** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WBA 1V 72090V 724 779**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **205/55R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Firelli**
 Front: _____ Rear: _____
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. 3 mm L/Bal. 3 mm
 D.O.A: **2/2/19** D.O.I: **6/3/19**
 Survey held at **Performance Motors**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time : _____ Action / Instruction

MV - 83090

Steve

pls see my remarks

9/4/2019
 11/3

8/4/19 Finalize \$3052.90. 3 days (Red \$596, 15%)

RECEIVED 10 APR 2019

Date/Time, File Pass to:

☐ : Preli. Report

Days Of Repair: 3

4) 10/4 10/19

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to:

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

) S + R. \$

) Photos

) Other

)

TOTAL

Report Format: 7P

Lump Sum / I.B. 3052.90

130
50
19
199



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000909MFSH
Our Ref: CS/FCI19003580/Eqd3

Date: 11 March 2019

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 1416T.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/03/2019 at the premises of M/s PERFORMANCE MOTORS LIMITED, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,608.90 .
Revised Estimate Amount	: S\$ 2,972.90 .
"Check" Items Amount	: S\$ 80.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Steve
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-02-2019	Our Ref No. D19000909MFSH
Accident Date	02-02-2019	Claim Type. Third Party
Insured Vehicle	SHB2626B	Third Party Vehicle. SLH1416T
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 9 April 2019 1:45 PM
To: PBSP; Steve Chen (LKK Auto); SUR
Subject: RE: FINAL REPORT / SLH1416T

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$3,052.90 before GST and 3 repair days.

Kindly send the relevant documents to First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simerdarby.com.sg>
Sent: Wednesday, 3 April 2019 6:10 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SLH1416T

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00

Total Parts : 1,038.90

Total Labour & Parts : 3,052.90

Repair days: 3

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 11 March 2019 11:59 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000909MFSH/1
Attachments: CSFCI19003580Eqd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SLH 1416T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 February 2019 10:57 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000909MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 25 February 2019 5:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000909MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5073D
Vehicle Details	
Vehicle No.:	SLH1416T
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	35109602B37D15A
Chassis No.:	WBA1V72090V724779
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,904.00
Original Registration Date:	25 Oct 2016
First Registration Date:	25 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$10,466.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Oct 2026
PARF Rebate Amount:	\$7,849.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$39,294.00
Total Rebate Amount:	\$47,143.00

The information contained herein is correct as at 07 Mar 2019

OK

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048680
Tel (65) 6724 0011 Fax (65) 6724 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UTN: M45500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MCHM 19015992 Vehicle Registration No: SLH 1416T
Name (as shown in NRIC): Yang Wen Yi NRIC/FIN/Passport No: S2725073D
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 46 Canberra Drive #10-11 Singapore 748436
Contact (Tel): _____ Mobile No.: 91006937
Email Address: myyangwenyi@gmail.com
Date of Accident: 02/02/2019 Time of Accident: 06:58 am
Place of Accident: _____
Insurance Company: Mtuc Income Ins

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- 1) Actual Location should be - Changi Airport T2 Arrival Dr
Near Merging of Departure Dr.
- 2) Third Party actual vehicle plate number: SHB 2626B

Policyholder / Driver's Signature
Date: 13 Feb 2019

Reporting Centre Personnel's Signature
Name: Sharon
NRIC/FIN No.: _____
Date: 13/2/19



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63489773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 FEB 2019

Estimate No. : b1 50113
Date Estimated : 14/02/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Yang Wenyi
46 Canberra Drive
#10-11

Singapore 768436

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH1416T	V724779	25/10/2016	116d	0

DESCRIPTION

To replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

① 850/- 1,275.00

② 934/- 1,038.00

③ 150/- 177.00

④ 9 80.00

Total Labour 1: 2,570.00

DESCRIPTION

REAR BUMPER PANEL PRIMED

REAR PDC HOLDER SET

(DG/SL) ADHESIVE SET K6

QTY PRIC VALUE

1 961.25 961.25

1 24.60 24.60

1 53.05 53.05

Total Parts : 1,038.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1 : 2,570.00

Parts : 1,038.90

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 252.62

Grand Total : 3,861.52

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

3608.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50113
Date Estimated : 14/02/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Yang Wenyi
46 Canberra Drive
#10-11

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 768436

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLH1416T	V724779	25/10/2016	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	①
To spray paint rear bumper	934.00		934.00	②
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	③
Sundries	80.00		80.00	④

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
① REAR BUMPER PANEL PRIMED	961.25	1.00		961.25 ✓
② REAR PDC HOLDER SET	24.60	1.00		24.60 ✓
③ (DG/SL) ADHESIVE SET K6	53.05	1.00		53.05 ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,038.90
Total Labour & Parts :	3,052.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,052.90
GST @7%:	213.70
Grand Total :	3,266.60



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003580/Eqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2626B	Veh. Inspected	SLH 1416T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000909MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	26/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW 116 D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA1V72090V724779	Colour	BLUE	
Odometer	47068	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FIRELLI	7 mm	
L/H Front Tyre	205/55 R16	FIRELLI	7 mm	
R/H Rear Tyre	205/55 R16	FIRELLI	7 mm	
L/H Rear Tyre	205/55 R16	FIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2019	Inspection Date	06/03/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 1416T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	REAR BUMPER PANEL PRIMED (SN)	DENTED	961.25	961.25
1	REAR PDC HOLDER SET (SN)	NECESSARY	24.60	24.60
1	(DG/SL) ADHESIVE K6 (SN)	NECESSARY	53.05	53.05
			1,118.90	1,118.90
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER AND ATTACHMENTS.		1,275.00	850.00
	PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,490.00	1,934.00
	GRAND TOTAL		3,608.90	3,052.90

RECOMMENDED COST OF REPAIRS			3,052.90
------------------------------------	--	--	-----------------

Report Ref No. CS/FC19003580/Eqd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.