

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFK981P
Make & Model : TOYOTA, WISH 1.8 CVT, JTDGG20W90J004343
Year of : 2016
Manufacture

Estimation No. : E19020025
DOA : 22/02/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper	1.00	681.70 ^{499.50}	681.70 DD✓
2	Rear bumper retainer long (LH)	1.00	121.50 ^{95.80}	121.50
3	Rear bumper retainer long (RH)	1.00	121.50 ^{95.80}	121.50 } BRV
4	Rear bumper retainer short (LH)	1.00	89.90 ^{55.80}	89.90
5	Rear bumper retainer short (RH)	1.00	89.90 ^{55.80}	89.90 } BRV
6	Rear bumper bracket (LH)	1.00	179.00	179.00 } NNx
7	Rear bumper bracket (RH)	1.00	179.00 ^{68.50}	179.00 } BRV
8	Rear bumper reflector (LH)	1.00	199.20 ^{85.50}	199.20 } BRV
9	Rear bumper reflector (RH)	1.00	199.20 ^{85.50}	199.20 } BRV
10	Tailgate	1.00	1,239.70	✓ 1,239.70 DD✓
11	Tailgate hinge (LH)	1.00	98.70	-98.70 } NNx
12	Tailgate hinge (RH)	1.00	98.70	-98.70 } NNx
13	Tailgate damper (LH)	1.00	278.00	-278.00 } NNx
14	Tailgate damper (RH)	1.00	278.00	-278.00 } NNx
15	Tailgate rubber beading weatherstrip	1.00	0.00 ^{299.10}	100.00 TN✓
16	Tailgate emblem - Logo	1.00	98.90 ^{68.50}	98.90
17	Tailgate emblem - Elegance	1.00	98.90 ^{62.50}	98.90 } NECV
18	Tailgate emblem - Valve Matic	1.00	98.90 ^{35.70}	98.90 } NECV
19	Tailgate lamp (LH)	1.00	450.00 ^{387.50}	450.00 } BRV
20	Tailgate lamp (RH)	1.00	450.00 ^{387.50}	450.00 } CRA✓
21	License lamp chrome garnish	1.00	229.00	✓ 229.00 BRV
22	License lamp (LH)	1.00	180.00	-180.00 } ? NNx
23	License lamp (RH)	1.00	180.00	180.00 } ? NNx
24	Tailgate lock	1.00	252.20	✓ 252.20 } ? BTV
25	Tailgate lock switch	1.00	160.00	✓ 160.00 } CRA✓
26	Tailgate lock sensor	1.00	362.00 ^{107.90}	362.00 } CRA✓
27	Tailgate lock catch	1.00	0.00	0.00 } NNx

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFK981P
Make & Model : TOYOTA, WISH 1.8 CVT, JTDGG20W90J004343
Year of Manufacture : 2016

Estimation No. : E19020025
DOA : 22/02/2019

No	Description	Qty	U/P	Amt	
28	Tailgate inner trim board	1.00	780.00	780.00	? CRAV
29	Tailgate inner pull handle	1.00	0.00	0.00	} NNX
30	Tailgate inner side garnish (LH)	1.00	0.00	0.00	
31	Tailgate inner side garnish (RH)	1.00	0.00	0.00	
32	Tailgate inner top garnish	1.00	290.00	290.00	? NNX
33	Tailgate windscreen moulding top	1.00	130.00	130.00	NECV
34	Tailgate windscreen moulding lower	1.00	92.00	92.00	} NECV
35	Tailgate windscreen outer side moulding (LH)	1.00	150.00	150.00	
36	Tailgate windscreen outer side moulding (RH)	1.00	150.00	150.00	
37	Tailgate wiper motor	1.00	690.00	690.00	NNX
38	Tailgate top spoiler	1.00	0.00	0.00	} NNX
39	Third brake lamp	1.00	0.00	0.00	
40	Tail lamp (LH)	1.00	599.20	599.20	} ? CRAV
41	Tail lamp (RH)	1.00	599.20	599.20	
42	Tailgate lamp gasket (LH)	1.00	0.00	0.00	} NNX
43	Tailgate lamp gasket (RH)	1.00	0.00	0.00	
44	Tail lamp gasket (LH)	1.00	0.00	0.00	
45	Tail lamp gasket (RH)	1.00	0.00	0.00	
46	Tail lamp inner panel (LH)	1.00	442.00	442.00	NNX
47	End panel	1.00	869.70	869.70	? BTV
48	End panel top garnish	1.00	340.00	340.00	DLV
49	Rear floor panel top board	1.00	432.00	432.00	NNX
50	Rear fender (LH)	1.00	1,333.96	1,333.96	? NNX
51	Rear fender inner trim (RH)	1.00	462.90	462.90	? BRV

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFK981P
Make & Model : TOYOTA, WISH 1.8 CVT, JTDGG20W90J004343
Year of Manufacture : 2016

Estimation No. : E19020025
DOA : 22/02/2019

No	Description	Qty	U/P	Amt
			Amt	S\$
				13,774.86
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$
				13,774.86

Section: Special Nett Items

52	Reverse camera	1.00	550.00	550.00 N/A
53	Reverse sensor set	1.00	250.00	250.00 200
54	Rear bumper clip set	1.00	45.00	30.00 45.00
55	Tailgate inner trim board clip set	1.00	45.00	38.00 45.00
56	End panel top garnish clip set	1.00	30.00	30.00
57	Rear fender inner trim clip set (LH)	1.00	45.00	45.00
58	Rear windscreen tinted	1.00	250.00	250.00 N/A
59	Rear windscreen sealant	1.00	100.00	100.00 60.00
60	End panel sealant	1.00	50.00	50.00 ✓
61	Rear number plate & casing	1.00	45.00	45.00 N/A
			Amt	S\$ 1,410.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 1,410.00

Section: Labour Items

62	To R&R rear bumper reverse sensor	1.00	60.00	60.00 ✓
63	To check wiring and lighting system	1.00	60.00	60.00 40.00 ✓
64	To supply undercoating & putty on parts replacement	1.00	80.00	80.00 60.00 ✓
65	To perform anti-rust treatment on affected areas	1.00	80.00	80.00 60.00 ✓
66	To R&R rear windscreen	1.00	200.00	200.00 100.00 ✓
67	To R&R tailgate mechanism	1.00	200.00	200.00 100.00 ✓
68	To R&R rear seats, garnish & trims assy	1.00	250.00	250.00 120.00
69	To repair, replace & realign damage areas	1.00	1,600.00	1,600.00 800.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFK981P
Make & Model : TOYOTA, WISH 1.8 CVT, JTDGG20W90J004343
Year of Manufacture : 2016

Estimation No. : E19020025
DOA : 22/02/2019

No	Description	Qty	U/P	Amt
70	To spray painting on affected areas	1.00	1,200.00	1,200.00
71	To check water seepage after repair	1.00	150.00	150.00
72	To car wash and polishing vehicle after repair	1.00	150.00	150.00
				Amt S\$ 4,030.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,030.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

? photo
4/5 repair
Days of repair 5

TG Lim
1730 hrs

Resurvey 6/3/19
1230 hrs
TG Lim

List Items Subtotal S\$ 13,774.86
Special Nett Items Subtotal S\$ 1,410.00
Labour Items Subtotal S\$ 4,030.00
Total S\$ 19,214.86