



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0980 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : AXA Insurance Singapore Pte Ltd
ATTN : Motor Claim Department
TEL. NO. : 1800-8804-741
EMAIL : motor.survey@axa.com.sg

CC : Toll Logistic (Asia) Limited

DATE : 25.02.2019

VEHICLE NO. : GZ7285D
MODEL NO. : MITSUBISHI FB70ABOSRDEB
CHASSIS NO. : FB70ABA00457
ENGINE NO. : 4M40HB9015
LTA REG DATE : 17-Aug-06

CLAIM TYPE : TP Claim - XD 6261 T
D.O.A : 22.02.2019
CLAIM REF NO. : asm/AC19013/AS

Quotation for Accident Repair

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	Rear Deck assy - <i>dismantle photo</i>	1	\$ 7,326.31	\$ 7,326.31 <i>bt</i>
2	Rear Crossmember - <i>dismantle photo</i>	1	\$ 893.27	\$ 893.27 <i>?</i>
3	Front air duct Snorkel	1	\$ 540.24	\$ 540.24 <i>de</i>
4	Air intake Box	1	\$ 346.52	\$ 346.52 <i>X</i>
5	Connector	1	\$ 67.99	\$ 67.99 <i>x</i>
6	Water spare tank	1	\$ 177.68	\$ 177.68 <i>? photo</i>
SUB-TOTAL :				\$ 9,352.01
less 25% Bal				\$ 2,338.00
Nett item				\$ 7,014.01
1	rear number plate	1	\$ 25.00	\$ 25.00 <i>st</i>
2	Spark arrester	1	\$ 250.00	\$ 250.00 <i>?</i>
Total Nett				\$ 275.00
Total Parts				\$ 7,289.01

LABOUR CHARGES

1	To remove and replace rear deck assy, replace air duct, box and connector. Panel beat front rear end panel, door pillar and realignment etc.	350	\$ 1,750.00
2	To remove rear deck, perform hot work to knock and straighten chassis. Realignment etc.	1400	\$ 2,500.00 <i>? photo</i>
3	Spray painting	600	\$ 800.00
TOTAL LABOUR :			\$ 5,050.00

GRAND TOTAL : \$ 12,339.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Taylor 97495447
wp
2/1/19
lump sum
Resurvey after repair
8 days
Taylor @ lkkauto.com
sure lkkauto.com