

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 21/02/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKN902T		
MODEL	: TOYOTA MARK X 2.5A		GRX130600551
CHASSIS NO			Joy
<u>ACCIDENT DETAILS</u>		DATE	: 21-Feb-19
		TIME	: 17:50HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 1,050.00	\$ 1,050.00
2	BOOT LTD EMBLEM 'MARK' <i>?</i>	1	\$ 72.00	\$ 72.00
3	BOOT LTD EMBLEM 'X' <i>new</i>	1	\$ 52.00	\$ 52.00
4	BOOT LID EMBLEM '250G'	1	\$ 61.00	\$ 61.00
5	BOOT LID LOGO	1	\$ 80.00	\$ 80.00
6	BOOTLID DETECTOR <i>Replaced</i>	2	\$ 410.00	\$ 820.00
7	BOOTLID LOCK <i>Damaged</i>	1	\$ 400.00	\$ 400.00
8	BOOTLID HINGE <i>new</i>	2	\$ 194.00	\$ 388.00
9	BOOTLID DAMPER <i>new</i>	2	\$ 115.00	\$ 230.00
10	BOOTLID WEATHERSTRIP <i>let</i>	1	\$ 175.00	\$ 175.00
11	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 62.00	\$ 124.00
12	REAR NUMBER PLATE GARNISH WITH MOULDING <i>new</i>	1	\$ 388.50	\$ 388.50
13	REAR BUMPER <i>Dislodged</i>	1	\$ 755.50	\$ 755.50
14	REAR BUMPER TOW HOOK COVER <i>Replaced</i>	2	\$ 55.50	\$ 111.00
15	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 88.10	\$ 176.20
16	REAR BUMPER REFLECTOR <i>Cracked</i>	2	\$ 105.90	\$ 211.80
17	REAR BUMPER SCREW COVER GARNISH <i>new</i>	2	\$ 42.10	\$ 84.20
18	REAR BUMPER BRACKET <i>Dented</i>	2	\$ 108.00	\$ 216.00

19	REAR BUMPER EXHAUST CHROME <i>new</i>	2	\$ 360.00	\$ 720.00	+
20	TAILLAMP <i>cancel</i>	2	\$ 455.20	\$ 910.40 790	
21	TAILLAMP PANEL <i>Repr</i>	2	\$ 275.10	\$ 550.20	+
22	REAR FENDER <i>Repr</i>	2	\$ 825.00	\$ 1,650.00	+
23	REAR FENDER INNER TRIM <i>Not ne</i>	2	\$ 825.00	\$ 1,650.00	+
24	REAR END PANEL <i>Delet</i>	1	\$ 565.00	\$ 565.00	✓
25	REAR END PANEL TOP GARNISH <i>Delet</i>	1	\$ 195.00	\$ 195.00	✓
26	REAR FLOOR PANEL <i>Repr</i>	1	\$ 995.10	\$ 995.10	+
27	REAR FLOOR PANEL COVER BOARD <i>Delet</i>	1	\$ 398.00	\$ 398.00	✓
28	REAR TOOLS TRAY <i>Delet</i>	1	\$ 497.00	\$ 497.00	✓
29	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 82.00	\$ 82.00	+

6420.50
 4815.37
 TOTAL PRICE \$ 13,607.90
 LESS 25% \$ 3,401.98
 SUB TOTAL PRICE \$ 10,205.93

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY		TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	BOOTLID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	REAR NUMBER PLATE GARNISH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
5	TAILLAMP PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
6	REAR FENDER SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
7	REAR FENDER INNER TRIM CLIP <i>new</i>	1	\$ 20.00	\$ 20.00	+
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 60	
9	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00 10	
10	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	+
11	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00 200	
12	REVERSE CAMERA <i>new</i>	1	\$ 650.00	\$ 650.00	+

290
 TOTAL \$ 1,705.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	900	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	900	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 80.00	30	

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	60	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
9	REMOVE AND REFIX REVERSE CAMERA SETTING	\$ 120.00	50	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	

TOTAL

\$4,920.00

2100

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,910.93
TOTAL LABOUR COST : \$ 4,920.00
TOTAL REPAIR COST : \$ 16,830.93

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian King
1/5 25/02/19.
07 Days.

FAX

total: 7205.37
4/5: 5.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: