

INSURER

INS. CASE OWNER:

Lynn
Kate.

CC 3 ASM
AXA1900

3589, Kp6352

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

25/2/19

Date / Time :

26/2/19.

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMD 5777J

Name of Insured

CHUA CHAN HUA

Insured Tel No.

HP:

n/a

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No.:

SAMOLENT 101038

Policy No.:

P257942

Make / Model :

TOYOTA

Place of Accident :

TENASET AVE ROUND AB7.

If NO, Driver Name / Age :

Driver Tel No.:

(VL: YES / NO)

OIGIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SHE 563R



INSRS:
WSP:
Tel:
Liability:
RMKS:

Trans cab



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHE 563R

SMD 5777J

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

26/2/19.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : *15.*

If NO for B 28, Ass. Lia :

Repair Cost:

SS

4333.50

Loss of Rental (LOR):

SS

501.94

(6 days)

x

days

X \$ 96.99

Loss of Use (LOU):

SS

(5 - x days)

Loss of Income (LOI):

SS

(5 - x days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$750.00

Total:

SS

4922.89

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4922.89

Name 1:

Trans-cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT 17/6/19

ASS. REC. BY:

REF:

ALA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 563R

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M-White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

436203

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

VF1ABL15MIC 278138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/2/19

D.O.I.

25/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rm body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

9/5/19

11/2/19

B 4050L Confirmed Tamin

(A+2 X 96.99)

(Red \$ 27150.11/874)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fixes

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 563R**AAD1902-190***Not Authorised*
L/Ring 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

P-Drive
*(X) RS photos***SHF 563R**

VF1ABL15AUC278138

RENAULT

LATITUDE

21.2.2019

AXA

20/6/2014

PART**LIST**

1	DOOR PANEL FRT RH	\$	<i>2,844.66</i>	
1	DOOR HINGE UPPER RH	\$	<i>261.28</i>	<i>X</i>
1	DOOR HINGE LOWER RH	\$	<i>300.55</i>	
1	DOOR CHECK FRT RH	\$	<i>194.77</i>	
1	DOOR LOCK FRT RH	\$	<i>908.75</i>	
1	DOOR CATCH FRT RH	\$	<i>131.23</i>	
1	DOOR HANDLE OUTER FRT RH	\$	<i>477.76</i>	
1	DOOR HANDLE COVER FRT RH	\$	<i>13.22</i>	<i>X</i>
1	DOOR HANDLE MODULE FRT RH	\$	<i>133.60</i>	
1	DOOR REGULATOR FRT RH	\$	<i>505.19</i>	
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>796.46</i>	
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>120.97</i>	
1	DOOR PANEL REAR RH	\$	<i>2,844.66</i>	
1	DOOR GUIDE REAR RH	\$	<i>176.82</i>	<i>X</i>
1	DOOR HINGE UPPER RH	\$	<i>274.50</i>	
1	DOOR HINGE LOWER RH	\$	<i>300.55</i>	
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>203.06</i>	
1	DOOR LOCK REAR RH	\$	<i>908.75</i>	
1	DOOR HANDLE OUTER REAR RH	\$	<i>126.49</i>	
1	DOOR HANDLE CAP REAR RH	\$	<i>35.52</i>	
1	DOOR HANDLE SEAL REAR RH	\$	<i>7.89</i>	
1	DOOR HANDLE COVER REAR RH	\$	<i>13.22</i>	
1	DOOR HANDLE MODULE REAR RH	\$	<i>133.60</i>	
1	DOOR REGULATOR REAR RH	\$	<i>1,135.10</i>	
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>893.75</i>	
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>12.43</i>	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>6.31</i>	
1	DOOR FINISHER REAR RH	\$	<i>423.10</i>	
1	DOOR MOULDING REAR RH	\$	<i>176.82</i>	

Trans-cab Auto Services Pte Ltd

AAD1902-190

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 563R

1	DOOR MOULDING CLIP L70Y	\$	nn	5.92	}
1	DOOR MOULDING SCREW L70Y	\$	nn	6.91	
1	DOOR CASING REAR RH	\$	sn	1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	sn	30.39	
1	DOOR CASING CLIP	\$	nn	12.63	
1	DOOR CASING LIGHT L70Y	\$	sn	48.74	
1	DOOR FINISHER INNER REAR RH	\$	sn	323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33	
1	DOOR GRAB HANDLE REAR RH	\$	sn	210.96	
1	DOOR BLIND REAR RH	\$	sn	741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	sn	410.66	
1	DOOR SEAL REAR RH	\$	sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	sn	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	sn n	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	sn	115.64	
1	DOOR MIRROR ASSY RH	\$	sn	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	sn	466.51	}
1	ROCKER PANEL INNER RH	\$	n	1,024.79	
1	ROCKER PANEL CENTER RH	\$	n	990.25	

	\$	22,576.09
10%	\$	2,257.61
	\$	20,318.48

Specical Nett

1	FRONT DOOR STICKER 'TRANS-CAB'	\$	nn	80.00	born
1	FRONT DOOR STICKER 'CHASSIS'	\$	nn	50.00	155n
1	REAR DOOR STICKER '6555-3333'	\$	nn	80.00	born
1	DOOR CHECK BOLT	\$	nn	22.69	X
1	DOOR GUIDE SCREW	\$	nn	10.85	X
1	DOOR HINGE BOLT	\$	nn	10.85	X

Trans-cab Auto Services Pte Ltd

AAD1902-190

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 563R

1	DOOR HINGE NUT RH	\$	nn 14.60	} X
1	DOOR CHECK BOLT	\$	nn 22.69	
1	DOOR CHECK NUT	\$	nn 3.75	
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	

TOTAL	\$	311.63
--------------	-----------	---------------

TOTAL PARTS	\$	20,630.11
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	800
Putty and spray painting of the affected portion.	\$	4,200.00	600
To rust-proofing of the affected areas.	\$	170.00	60
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
TOTAL	\$	10,570.00	
Over All Total	\$	31,200.11	09
LUMP SUM (REPAIR DAY)			15 DAYS 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- * To repair the vehicle within the agreed time frame
- * To provide a written confirmation
- * This party hereby agrees to "without Prejudice" be
- * No legal action is allowed
- * Supplier's responsibility must be resolved

Authorised signature required:



<MANDATE IA> - S9M01EU7 [ACCIDENT INVOLVING SMD 5777J(OI) & SHF 563R(TP) ON 21/02/2019]

Type

🔗 Question

Message

Liability: 100%. Insured driver changed lane and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$5,420.95(all-in). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 18 May 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/05/2019

Survey Details:

Date of loss	21-Feb-19
Date of appointment	26-Feb-19
Date of survey	26-Feb-19
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHF 563R
Make and Model	RENAULT LATITUDE
Date of registration	20/6/2014
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 31,200.11
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,586.42
Check items (estimate)	NIL
Labour	\$ 1,460.00
Total	\$ 5,046.42
Lump Sum(if applicable)	\$ 4,050.00

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	4,333.50
Loss of use		NIL no. of days
Loss of rental	\$	780.00 (6days x \$130.00)
Loss of income	\$	300.00 (6days x \$50.00)
LTA search fees	\$	7.45
Others		NIL
Proposed Total	\$	5,420.95



Re:<MANDATE IA> - S9M01EU7 [ACCIDENT INVOLVING SMD 5777J(OI) & SHF 563R(TP) ON 21/02/2019]

Type

🔍 Question

Message

Proceed as proposed quantum. To submit relevant doc at completion. Thanks

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 5 June 2019 8:49 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; claims@transcab.com.sg
Subject: Your ref: AAD1902-190 (SHF 563R) *Our Ref: CC3/ASM19003589/Kpb3 [ACCIDENT INVOLVING SMD 5777J(AXA) AND SHF 563R ON 21/02/2019]
Attachments: EXPRESS SETTLEMENT FORM_SHF563R.pdf

Your ref: **AAD1902-190 (SHF 563R)**
Our Ref: CC3/ASM19003589/Kpb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SMD 5777J(AXA) AND SHF 563R ON 21/02/2019

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,333.50
2. Loss of Rental (6days x \$96.99)	\$ 581.94
3. LTA/ GIA Search Fee	\$ 7.45
Total	<u>\$ 4,922.89</u>

If our offer is acceptable by your client, please duly sign the document enclosed and return to us (LKK) for our necessary action.

***Meantime, kindly let us have the after repair/paint photos for SHF 563R (DOA: 21/02/2019).*

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

LKK

Our Ref : AAD1902-190

Your Ref : SMD5777J

Date : 10.April 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHF0563R AND SMD5777J ON 21/02/19 08:50 PM ALONG TEMASEK BOULEVARD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	4,333.50
2.	Loss of Rental for <u>7</u> days @ \$ <u>96.99</u> per day	\$	678.93
3.	Loss of Income for <u> </u> days @ \$ <u> </u> per day	\$	0.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	5,019.92

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Certificate of Insurance

Original final repair bill

Rental rate and mileage records

Authorization To Act

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMD 5777J (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHF 563R (TP veh)		
Date of Accident:	21/02/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	33,384.10
Final Repair Cost	:	\$	4,333.50
Loss of Token Sum	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	581.94 6 days
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	4,922.89

Is Third Party Workshop GIA Registered?		☒ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111				

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	:	\$ 4,922.89

NUR SHAQILAH BTE ABDOL
WAHAB

17/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC3/ASM19003589/Kpb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG		Date : 17-06-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMD 5777J	Veh. Inspected	SHF 563R
Policy No.	P2157942	Coverage (\$)	0.00
Claim No.	S9M01EU7	Excess (\$)	0.00
Assign From		Assign Date	25/02/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278138	Colour	METALLIC WHITE / RED
Odometer	436203	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	8 mm
L/H Front Tyre	215/60R16	GITI	8 mm
R/H Rear Tyre	215/60R16	GITI	8 mm
L/H Rear Tyre	215/60R16	GITI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/02/2019	Inspection Date	25/02/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 563R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL FRT RH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH (CONSISTENT)	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH (CONSISTENT)	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH (CONSISTENT)	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH (CONSISTENT)	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH (CONSISTENT)	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH (CONSISTENT)	SERVICEABLE	893.75	-

Report Ref No. CC3/ASM19003589/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR NUT REAR L70Y (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH (CONSISTENT)	SERVICEABLE	115.64	-
1	DOOR MIRROR ASSY RH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH (CONSISTENT)	BENT	990.25	990.25
	LESS 10% DISCOUNT		-2,257.61	-383.49
			20,318.48	3,451.42

Report Ref No. CC3/ASM19003589/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CHASSIS' (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			311.61	135.00
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION. REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR REGULATOR FRT RH, DOOR PANEL REAR RH, DOOR LOCK REAR RH, DOOR REGULATOR REAR RH, DOOR FINISHER BRACKET INNER REAR RH AND ROCKER PANEL INNER RH.		4,500.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHERM TO ENABLE REPAIR.		380.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00

Report Ref No. CC3/ASM19003589/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			10,570.00	1,460.00
GRAND TOTAL			31,200.09	5,046.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CC3/ASM19003589/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.