

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 563R**AAD1902-190***Not Authorised**1/10/18*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 563R

VF1ABL15AUC278138

RENAULT

LATITUDE

21.2.2019

AXA

20/6/2014

PART**LIST**

1	DOOR PANEL FRT RH	\$	<i>2</i> 2,844.66	—
1	DOOR HINGE UPPER RH	\$	<i>1</i> 261.28	} X
1	DOOR HINGE LOWER RH	\$	<i>1</i> 300.55	
1	DOOR CHECK FRT RH	\$	<i>1</i> 194.77	
1	DOOR LOCK FRT RH	\$	<i>1</i> 908.75	
1	DOOR CATCH FRT RH	\$	<i>1</i> 131.23	
1	DOOR HANDLE OUTER FRT RH	\$	<i>1</i> 477.76	}
1	DOOR HANDLE COVER FRT RH	\$	<i>1</i> 13.22	
1	DOOR HANDLE MODULE FRT RH	\$	<i>1</i> 133.60	
1	DOOR REGULATOR FRT RH	\$	<i>1</i> 505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>1</i> 796.46	} X
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>1</i> 120.97	
1	DOOR PANEL REAR RH	\$	<i>1</i> 2,844.66	
1	DOOR GUIDE REAR RH	\$	<i>1</i> 176.82	
1	DOOR HINGE UPPER RH	\$	<i>1</i> 274.50	
1	DOOR HINGE LOWER RH	\$	<i>1</i> 300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>1</i> 203.06	
1	DOOR LOCK REAR RH	\$	<i>1</i> 908.75	
1	DOOR HANDLE OUTER REAR RH	\$	<i>1</i> 126.49	
1	DOOR HANDLE CAP REAR RH	\$	<i>1</i> 35.52	
1	DOOR HANDLE SEAL REAR RH	\$	<i>1</i> 7.89	
1	DOOR HANDLE COVER REAR RH	\$	<i>1</i> 13.22	
1	DOOR HANDLE MODULE REAR RH	\$	<i>1</i> 133.60	
1	DOOR REGULATOR REAR RH	\$	<i>1</i> 1,135.10	
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>1</i> 893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>1</i> 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>1</i> 6.31	
1	DOOR FINISHER REAR RH	\$	<i>1</i> 423.10	
1	DOOR MOULDING REAR RH	\$	<i>1</i> 176.82	

Trans-cab Auto Services Pte Ltd

AAD1902-190

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 563R

1	DOOR MOULDING CLIP L70Y	\$	nn	5.92	} X
1	DOOR MOULDING SCREW L70Y	\$	nn	6.91	
1	DOOR CASING REAR RH	\$	sn	1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	sn	30.39	
1	DOOR CASING CLIP	\$	nn	12.63	
1	DOOR CASING LIGHT L70Y	\$	sn	48.74	
1	DOOR FINISHER INNER REAR RH	\$	sn	323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33	
1	DOOR GRAB HANDLE REAR RH	\$	sn	210.96	
1	DOOR BLIND REAR RH	\$	sn	741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	sn	410.66	
1	DOOR SEAL REAR RH	\$	sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	sn	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	sn n	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	sn	115.64	
1	DOOR MIRROR ASSY RH	\$	sn	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	sn	466.51	} ✓
1	ROCKER PANEL INNER RH	\$	n	1,024.79	
1	ROCKER PANEL CENTER RH	\$	n	990.25	

\$	22,576.09
10% \$	2,257.61
\$	20,318.48

Special Nett

1	FRONT DOOR STICKER 'TRANS-CAB'	\$	nn	80.00	born
1	FRONT DOOR STICKER 'CHASSIS'	\$	nn	50.00	1500
1	REAR DOOR STICKER '6555-3333'	\$	nn	80.00	born
1	DOOR CHECK BOLT	\$	nn	22.69	X
1	DOOR GUIDE SCREW	\$	nn	10.85	X
1	DOOR HINGE BOLT	\$	nn	10.85	X

Trans-cab Auto Services Pte Ltd

AAD1902-190

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 563R

1	DOOR HINGE NUT RH	\$	nn 14.60	} X
1	DOOR CHECK BOLT	\$	nn 22.69	
1	DOOR CHECK NUT	\$	nn 3.75	
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	

TOTAL \$ 311.63**TOTAL PARTS \$ 20,630.11****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	800 4,500.00	
Putty and spray painting of the affected portion.	\$	4,200.00	6601
To rust-proofing of the affected areas.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL \$ 10,570.00**Over All Total \$ 31,200.11****LUMP SUM (REPAIR DAY)****15 DAYS****4 days**

Acknowledged by Repairer

Signature:

Date:

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey the damaged part(s) during resurvey
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company