

Sheet1

S M SPRAY PAINTING

BLOCK 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KB Singapore 417800
Tel: 6384 1755/1766 Fax: 6384 1744

25th february 2019

Bk 25 Kaki Bukit Rd 4
08-30 SYNERGY @KB
Singapore 417800

TPLCR
Xiao Tony

WDD2052472F401401

Accident date: 23rd February 2019

Estimated repair cost for vehicle no: SLU3318L MERCEDES BENZ 350

S/n	Qty	Items/Nett	U/price	Amount
				\$2,651.00 X
1	1	Rear boot lid <i>Repis</i>		\$65.00 ✓
2	1	Rear boot lid emble logo <i>3me</i>		\$65.00 ✓
3	1	Rear boot lid 350 logo		\$288.00 X
4	1	rear boot Lid centre moulding <i>Not new</i>		\$957.00 785
5	1	Rear tail lamp-LH <i>smushed</i>	\$8.00	\$16.00 ✓
6	2	Rear tail lamp clips <i>new</i>		\$900.00 450
7	4	Rear bumper reverse sensor <i>2 pieces dngd</i>	\$225.00	\$958.00 688
8	1	Rear Bumper reinforcement <i>Bent</i>		\$388.00 ✓
9	1	rear LH Parking sensor <i>Dngd</i>		\$129.00 +
10	1	Rear Bumper Inner Center Bracket <i>new</i>		\$2,510.00 1590
11	1	Rear bumper <i>Distorted</i>		\$276.00 138
12	2	Rear Bumper lower Bracket <i>LH Dngd</i>	\$138.00	\$325.00 X
13	1	rear bumper lower chrome <i>new</i>		\$65.00 30
14	10	Rear bumper clips <i>new</i>	\$6.50	\$1,954.00 ✓
15	1	Rear fender L/H <i>Buckled</i>		\$855.00 +
16	1	Rear Fender Inner Trim Board-LH <i>3me</i>	\$6.50	\$65.00 +
17	10	Rear Fender Inner Trim Board Clips <i>3me</i>		\$188.00 +
18	1	Rear wheel arch -LH		\$755.00 +
19	1	Rear L/H top ventilation flap		\$925.00 ✓
20	1	Rear L/H knuckle <i>knuckle</i> arm <i>Bent</i>		\$1,125.00 X
21	1	Rear driver shaft <i>new</i>		\$852.00 ✓
22	1	Rear shock absorber-LH <i>Bent</i>		\$326.00 ✓
23	1	Rear L/H wheel bearing hup <i>Dngd</i>		\$472.00 ✓
24	1	Rear L/H lower arm <i>Bent</i>		\$650.00 300(SW)
25	1	REAR TYRE -LH <i>ut</i>		\$950.00 750(SW)
26	1	Rear RIM-LH <i>ut</i>		\$2,450.00 X
27	1	Rear Exhaust <i>Repis</i>		\$225.00 ✓
28	1	rear exhaust heat shield <i>Cracked</i>		\$277.00 ✓
29	1	Rear Exhaust chome pipe <i>Bent</i>		
Subtotal :-				\$21,662.00

Rear End Panel *Bent* 1330 ✓
Rear Control Arm *3 Bent* 202 ✓
Rear Stay Arm 198 ✓
Rear Lateral Link (Front) *3 Bent* 214 ✓
Rear Lateral Link (Rear) *3 Bent* 210 ✓
Rear Bumper Lower Garnish 385 ✓

11795 SN: 1050
10615.50

Labour charges

To remove & re-fix cushion

~~\$120.00~~ 80

To remove & re-fix rear undercarriage

~~\$280.00~~ 250

To reset computer

~~\$200.00~~ 150

To check wheel alignment computer

~~\$150.00~~ 80

To Check Wiring System

~~\$60.00~~ 30

Tuff kote

~~\$120.00~~ 80

Panel beating

2780

\$1,000.00 ✓

Spray Painting

120

\$1,000.00 ✓

To remove rear windscreen

~~180~~

Subtotal :- \$2,930.00

Total:- \$24,592.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 14455.50

4/5 = 13K. ✓

12 Days.