



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
6 Benoi Place Singapore 629927  
Tel: 6861 0908 Fax: 6515 2948

Date: 21.02.2019

India International Insurance Pte Ltd  
64 Cecil Street #04/#05  
IOB Building  
Singapore 049711

Attn: Motor Claims Dept

### RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2032D TOYOTA VELLFIRE HYBRID 2.4X (2014)

#### To Supply

1 ) 1pc	Rear bumper	\$	1,050.00 <i>de</i>
2 ) 1set	Rear bumper clips	\$	30.00 <i>ne</i>
3 ) 1pc	Rear bumper right retainer	\$	130.00 <i>ne</i>
4 ) 1pc	Right reverse sensor	\$	290.00 <i>de</i>
5 ) 1pc	Right reverse sensor cover	\$	25.00 <i>ea</i>
6 ) 1pc	Right tail lamp lower corner panel	\$	278.50 <i>Ry</i>
Sub total parts		\$	1,803.50
Less: 25% discount		\$	(450.88)
		\$	1,352.62

#### L/charges

1 )	To remove & replace right reverse sensor. To reset wiring light.	\$	60.00 <i>30</i>
2 )	To remove & replace rear bumper & right corner panel. Align & adjust rear bumper & tail gate.	\$	500.00 <i>300</i>
3 )	To putty, respray painting rear bumper & right tail lamp lower corner panel in pearl white. To polish.	\$	500.00 <i>300</i>
Sub total L/charges		\$	1,060.00
Estimated Grand total		\$	2,412.62

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Tanpin 97495749*  
*WP*  
*lumpsum 26/2/19 & 240*  
*Resurvey after repair*  
*sure 1/1/2019*  
*02 days*