

Kp

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
 #03-11 AMK Autopoint Singapore 568047
 Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Notarized ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way,
 AIG Building #09-16
 Singapore 079120
 Attn: Motor Claims Department

11 Sep 8 6450h
Recovery After Rain
6 days

Date : 22/02/2019
 Vehicle No : SKA553K
 Veh Make/Model : Volk. New Golf 1.4 TSI AT
 YOM : 2010
 Chassis No : WVWZZZ1KZBW145341
 Date of Accident : 21/02/2019

No	Qty	Description	Amount \$	
		<u>List Items:-</u>		
1	1	Tailgate <i>1690-87</i>	\$ <i>Bz</i> 2,299.15	✓
2	1	Tailgate windscreen moulding	\$ <i>rm</i> 100.00	✓
3	1	Tailgate logo handle	\$ <i>Sm</i> 819.33	X
4	1	Tailgate reflector (LH)	\$ <i>Sm</i> 318.25	X
5	1	Tailgate reflector (RH)	\$ <i>Sm</i> 318.25	X
6	1	Tailgate "GOLF" emblem	\$ <i>rm</i> 114.68	✓
7	1	Tailgate "TSI" emblem	\$ <i>rm</i> 64.00	✓
8	1	Tailgate lock	\$ <i>rd</i> 238.28	✓
9	1	Tailgate weatherstrip	\$ <i>196-89Sm</i> 393.78	<i>5091m</i>
10	1	Tailgate inner trim board	\$ <i>Sm</i> 350.40	X
11	1	Rear bumper	\$ <i>Bz</i> 1,660.10	✓
12	2	Rear bumper number plate lamp	\$ <i>Sm</i> 75.16	X
13	1	Rear bumper reflector (LH)	\$ <i>Sm</i> 84.03	X
14	1	Rear bumper reflector (RH)	\$ <i>Sm</i> 84.03	X
15	1	Rear bumper lower lid	\$ <i>Bz</i> 479.98	✓
16	1	Rear bumper tow cover	\$ <i>rd</i> 39.28	✓
17	1	Rear bumper centre bracket	\$ <i>cm</i> 137.58	✓
18	2	Rear bumper side retainer	\$ <i>Old Div</i> 114.96	✓
19	1	Rear bumper reinforcement	\$ <i>Bz</i> 735.63	✓
20	1	End panel	\$ <i>Bz</i> 987.50	✓
21	1	End panel top trim	\$ <i>cm</i> 237.00	✓
		Total - List Item	\$ 9,651.37	
		Less 10%	\$ 965.14	
		Total	\$ 8,686.23	
		Balance b/f	\$ 8,686.23	

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 22/02/2019
Vehicle No : SKA553K
Veh Make/Model : Volk. New Golf 1.4 TSI AT
YOM : 2010
Chassis No : WVWZZZ1KZBW145341
Date of Accident : 21/02/2019

No	Qty	Description	Amount S
		Balance c/f	\$ 8,686.23
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	1	Tailgate windscreen glass gum/sealant	\$ 80.00
4	10	Tailgate inner trim board clip	\$ 50.00
5	10	Rear bumper clip	\$ 70.00
6	6	End panel top trim clip	\$ 42.00
		Total - SN Item	\$ 677.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,000.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,100.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 80.00
5		To remove and reinstall tailgate windscreen glass.	\$ 150.00
6		To transfer tailgate inner compartment, mechanism & assy.	\$ 250.00
7		To check and test tailgate water leaking.	\$ 80.00
8		To remove and replace reverse sensor.	\$ 120.00
9		Computer diagnostic after repair.	\$ 300.00
10		Upholstery details cleaning.	\$ 220.00
		Total - L/C	\$ 3,420.00
		Sub-Total	\$ 12,783.23
		7% GST	\$ 894.83
		Total	\$ 13,678.06

455m

200m

405m

X

✓

✓

700l

600l

80l

20l

120l

60l

15l

50l

X

X