

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 04.03.2019
VEH NO : SJD3715L
MODEL : Toyota Harrier
D O A : 24.02.2019
YR REF : SLL8029K

TPCCR.
Xiao Tony

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJD3715L (TOYOTA HARRIER)

Item	Description	Qty	Amt
<u>NO</u>	<u>LIST ITEMS</u>		
1	Rear Number Plate Garnish <i>reformed</i>	1	66.10 ✓
2	Front Bumper <i>Distorted</i>	1	1,217.80 ✓
3	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
4	Front Bumper Side Holder - LH & RH <i>new</i>	2	161.20 ✓
5	Front Bumper Reinforcement <i>Best</i>	1	549.10 ✓
6	Front Bumper Sponge <i>crushed</i>	1	171.50 ✓
7	Front Bumper Towing Cover <i>new</i>	2	90.40 X
8	Front Bumper Fog Lamp - LH & RH <i>LH cut</i>	2	752.60 376.30 ✓
9	Front Brace Panel <i>Best</i>	1	65.90 ✓
10	Head Lamp - LH & RH <i>crushed</i>	2	3,690.20 ✓
11	Bonnet <i>Distorted</i>	1	1,366.10 ✓
12	Bonnet Lock <i>Damaged</i>	1	77.80 ✓
13	Bonnet Grille <i>crushed</i>	1	591.40 ✓
14	Bonnet Grille Logo <i>new</i>	1	63.90 ✓
15	Bonnet Grille Clips <i>new</i>	1	15.00 ✓
16	Front Support Panel <i>Repair</i>	1	688.10 X
17	Front Support Panel Top Cover <i>Distorted</i>	1	199.50 ✓
18	Front Support Panel Top Cover Clips <i>new</i>	1 set	30.00 20 ✓
19	Horn <i>crushed</i>	1	85.00 ✓
20	Air Con Condenser <i>Dented</i>	1	1,196.40 ✓
21	Air Con Discharge Pipe <i>Best</i>	1	356.00 ✓
22	Radiator <i>Not new</i>	1	2,182.40 X
			10299.20
			7724.40
			13,646.40
Less 25%			(3,411.60)
			\$ 10,234.80
<u>S/NETT ITEMS</u>			
1	Front Number Plate <i>Best</i>	1	30.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SJD3715L (TOYOTA HARRIER)

2	Front Number Plate Holder <i>cracked</i>	1	30.00 ✓
			<i>60</i>
			60.00
	Total Parts	\$	10,294.80

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	1,200.00 <i>600</i>
2	To putty & spray up paint works	\$	1,000.00 <i>600</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To underseal	\$	120.00 <i>+</i>
5	To remove condenser, radiator and re-gas	\$	180.00 <i>120</i>
	Total Labour	\$	2,550.00
	Grand Total	\$	12,844.80

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 9134.40
L/S: 7.3K.
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: