



Date: 01 March 2019

To : LKK

Attn : Bryan Ang

By Fax: 6256-4315

Tel: 97237799

VEHICLE NO : FBF 7637L

Yamaha FZ 16

ACCIDENT DATE: 22 February 2019

Description	Qty	Quotation \$
1 Head Lamp LH Guard <i>broken missing</i>	1	285.00 ✓
2 Handle Bar <i>bat</i>	1	165.00 ✓
3 Head Lamp <i>cut</i>	1	235.00 ✓
4 Fork Guard RH <i>HL</i>	1	190.00 X
5 Fork Tube <i>distorted</i>	1 set	480.00 ✓
6 Gear Lever <i>not broken</i>	1	85.00 ✓
7 Front Mudguard <i>broken</i>	1	170.00 ✓
8 Front Left Signal Light1 <i>switched</i>	1	250.00 ✓

Sub-Total	1,860.00
Less 10%	186.00
Sub-Total	1,674.00

Nett Items

1 Labour to remove & replace parts, align & etc	220.00 150/-
2 Remove & replace fork tube & top up fork oil	130.00 80/-

Special Nett Items

1 IU Unit <i>HL</i>	170.00 X
---------------------	----------

Sub-Total	520.00
Nett Total	2,194.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

28/02/2019 @ 1400m

HLA Antenn

2/Smr

2 days.

[Signature]

2KK Auto