


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 13:55

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013897 Date : 13/06/2019 Order : SBN8881Z Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
Regn No: SBN8881Z (V 37742)	Regn Date: 17/05/2018	Mileage: 4863	WIP No.: 43259
Model: Q5 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZZF3J2141016	Engine: DAX 033228	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1500.00	1.00	-1,500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGES	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER ASSY. TO INSPECT END PANELLING.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH COVER	1500.00	1.00	1,500.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
	A80A807434B TB2	(A) (G) SPOILER 07/03/	Less 020%	1.00	753.50
	A80A853817A GRU	(A) (G) COVER 07/03/19	Less 020%	1.00	487.00
X	A80A807527 GRU	(A) (G) COVER 07/03/19	Less 020%	1.00	1077.00
X	A80A807067A GRU	(A) (SK) COVER 07/03/1	Less 020%	1.00	1571.00
X	A80A945069	(A) (SK) TAILLIGHT 07/	Less 020%	1.00	627.00
X	A80A853818A GRU	(A) (SK) COVER 07/03/1	Less 020%	1.00	487.00

Parts 4,002.00
Labour 0.00
Sublet 2,552.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,054.00

7% GST 353.78

Grand Total 5,407.78



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SBN 8881 Z

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0243/2019/KK
3 April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 SPORT 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZF3J2141016
Vehicle Regn No. : **SBN 8881 Z**
Vehicle Mileage : 4863 KM
Vehicle Owner : Ms. Cheok Suat Lee
Certificate No : 1800055715
Own Damage Excess : \$1605.00 (Inclusive 7%GST)
Accident Date : 18/2/2019
Place : Skyline 360 Car Park
Repair Cost : \$ 5,407.78
WIP No. : 43259
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 4/4 _____