

Surveyor

ASSIGNMENT (Office)

From (Person)

Hui, Yinnal

of

AIG

Date/Time

26/2/19 @ 10:21am.

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKH 4836G

Insured

SKG 501D

at Workshop m/s

Ah Cheng Motor

Tel:

6483 5434

of

10 Amk Ind. Park 2A #03-16

Policy No.

1800114310

Claim No.

288278722556

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

20/2/19

CA / REV / REP. / REV 24 HRS

4/3/19

H.O.D. Endorsement

Date/Time

10:30am @ 26/2/19

Person Contacted

Diana

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction (X) Estimate

SKH 4836G-CC3/CAT/500211/Gbk3

D.O.A: 2/2/15

SKG 501D-X

1/Lm 8250d email

270d Cabram. (Red B 14041. 95, 84%)

ASS. REC. BY:

REF:

A/G-1

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

RECEIVED 10 APR 2010

Veh No:

SKH 48366

Yr Regn:

11, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Volks wagan

Tisuan

c.c

1984

Colour:

n. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

189862

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVG 2885N 88W 03688

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

20/2/19

D.O.I.

4/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1) 10/4/19

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

250

S + R.S. SI

10

Photos

Others

260

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I: (\$

2700

**- Pre-Repair Inspection Request – SKH4836G vs SKG501D (OI) on D.O.A.: 20/02/2019**

From: Hor, Yinrul  
To: Admin A (admin-a@lkkauto.com), 'assignments@lkkauto.com'  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur  
Sent: 26/2/2019 10:21:52 AM  
Attachments: 90181 (NOA).pdf; 90181 (NOA).pdf

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Cheonghoh Law [mailto:mail@cheonghoh.sg]

**Sent:** Tuesday, February 26, 2019 10:05 AM

**To:** Hor, Yinrul

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

**Subject:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG501D AND SKH4836G ON 20/02/2019 (Our ref: LCH.my/AMK10-90181.19)

**\*\* Please quote our reference no when replying**

Dear Sirs,

We refer to the above matter and to your email of 25 February 2019.

Our client hereby nominate Marcus Chua of LKK Auto Consultants Pte Ltd named in paragraph 2 of your said email for the pre-repair survey ("PRS") of the damages to our client's vehicle.

Please be informed that our client's vehicle, SKH 4836 G is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo kio Point #03-16 Singapore 568047. Kindly proceed to do the needful and you may contact the person in charge Mr Ng/Diana at 64835434 before your surveyor attend at the said workshop.

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

On 25 Feb 2019, at 10:00 AM, Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-03-04 10:00 +08 to read your message. After that, open the attachment.

[More info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul Hor@aiig.com

To: mail@cheonghoh.sg

Cc: Andy-SY.Fong@aiig.com, Lee-

Ying.Chin@aiig.com, Baljit.Kaur@aiig.com, NoorMariesa.AbuKassim@aiig.com, Syazeirdina.Azlan@aiig.com, yokeshi.chan@aiig.com, ShengYang.Lim@aiig.com, Aashweenje

etkaur.Mithoosingh@aiig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG501D AND SKH4836G ON 20/02/2019

Date: Mon, 25 Feb 2019 02:00:16 +0000

Without Prejudice

Your Reference : LCH.my/AMK10-90181.19  
Our Reference : SKG501D

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Friday, February 22, 2019 7:20 PM

To: Abu Kassim, Noor Mariesa; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi;

Supramaniam, Darshene

**Subject:** Notice of Accident - Traffic accident involving SKH 4836 G and SKG 501 D (your insured) on 20 February 2019 at/along Cavenagh Road towards Bukit Timah Road ; Our ref: LCH.my/AMK10-90181.19

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Thanks & regards,

Melody

**CHEONGHOH LAW CORPORATION**

Blk 53 Chin Swee Road #03-05 Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)


> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	6201D
<b>Vehicle Details</b>	
Vehicle No.:	SKH4836G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN 2.0L TSI AT 5N12K9
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CCZ085697
Chassis No.:	WVGZZZ5NZBW036890
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$25,959.00
Original Registration Date:	08 Nov 2010
First Registration Date:	08 Nov 2010
Transfer Count:	4
Actual ARF Paid:	\$25,959.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2020
PARF Rebate Amount:	\$14,277.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 Nov 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,501.00
COE Rebate Amount:	\$6,697.00
<b>Total Rebate Amount:</b>	<b>\$20,974.00</b>

The information contained herein is correct as at 10 Apr 2019

OK



# AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C


page 1/2  
NOT authorised  
Liby B2500k  
Kenny after pain  
3 days

Car Plate No. SKH 4836G

Date of Accident : 20-02-2019

Model Volkswagen Tiguan

No.	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy - upper	ACM \$ 1,289.00 ✓
2	1	Rear bumper assy - lower 464.23	\$ Bu 1,055.00 ✓
3	2	Rear bumper retainer	\$ R 288.00 X
4	2	Rear bumper bracket	\$ R 286.00 X
5	2	Rear bumper lower lamp	\$ R 624.00 X
6	2	Rear bumper tow cover	\$ R 180.00 X
7	1	Rear bumper reinforcement 554.95	\$ B 689.00 ✓
8	1	Rear bumper inner beam	\$ R 280.00 X
9	1	Rear bumper lower garnish	\$ R 840.00 X
10	1	Rear bumper lower garnish grille	\$ R 430.00 X
11	1	Rear tailgate assy	\$ R 3,276.00 X
12	1	Rear tailgate lock mechanism	\$ R 269.00 X
13	2	Rear tailgate rubber stopper	\$ R 68.00 X
14	1	Rear tailgate centre logo	\$ R 138.00 X
15	1	Rear tailgate "Tiguan" emblem	\$ R 128.00 X
16	1	Rear tailgate "4.2" emblem - RH side	\$ R 128.00 X
17	1	Rear tailgate "quattro" emblem	\$ R 128.00 X
18	1	Rear left tail lamp	\$ R 879.00 X
19	1	Rear right tail lamp	\$ R 879.00 X
20	1	Rear end lower panel	\$ R 1,527.00 X
			\$ 13,381.00
Less 5%			\$ 669.05
			<u>\$ 12,711.95</u>
<u>Special Nett Items</u>			
1	12	Rear bumper clips	\$ R 60.00 ✓
2	1	Rear windscreen sealant	\$ R 80.00 X
3	1	Rear windscreen inner seal	\$ R 80.00 X
4	1	Rear number plate with garnish	\$ R 80.00 X
5	1	Rear bumper reverse sensor	\$ CM 1,000.00 2000
			<u>\$ 1,300.00</u>
Total Parts			\$ 14,011.95

**AH CHANG MOTOR SERVICE CENTRE**

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Car Plate No. **SKH 4836G**Date of Accident : **20-02-2019**Model **Volkswagen Tiguan**

<u>No.</u>	<u>Parts Description</u>	<u>Labour Charges</u>
1	Labour for panel beating, cut, weld , straighten rear affected area and replace rear damage parts	\$ 1,000.00 <sup>400</sup> <del>350</del>
2	To putty & spray painting rear portion	\$ <sup>450</sup> 1,000.00 <del>250</del>
3	To check rear lighting and wiring	\$ 50.00 <sup>10</sup>
4	To remove and install rear tailgate lock mechanism	\$ <sup>un</sup> 80.00 X
5	To remove and install rear inner trim to facilitate the repair	\$ <sup>un</sup> 140.00 X
6	To apply anti rust proofing to rear affected area	\$ <sup>un</sup> 140.00 X
7	To remove and install rear windscreen to facilitate the repair	\$ <sup>un</sup> 140.00 X
8	To remove and install rear bumper reverse sensor	\$ 80.00 <sup>50</sup>
9	Towing service	\$ <sup>un</sup> 100.00 X

<b>Total Labour</b>	\$	<b>2,730.00</b>
---------------------	----	-----------------

<b>Total Parts</b>	\$	<b>14,011.95</b>
--------------------	----	------------------

<b>Total Labour</b>	\$	<b>2,730.00</b>
---------------------	----	-----------------

<b>Total Repair Cost</b>	\$	<b>16,741.95</b>
--------------------------	----	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification is allowed
- Supplementary items should be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003610/KQD3N2

Date: 12/04/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800114310  
 Claimant Vehicle No: SKH4836G Insured Vehicle No: SKG501D  
 Date of Loss: 20/02/2019 Nature of Claim: TP Claim No: 2882787225SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKH4836G  
 Make & Model: VOLKSWAGEN TIGUAN, 2.0 TSI (5N12K9) (A) Engine No: CCZ085697  
 Reg. Date: 08/11/2010 (Man. Year: 2010) Chassis No: WVGZZZ5NZBW036890  
 Colour: Metallic Black Odometer: 189662 km  
 Engine Capacity: 1984 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/65R16 Rear Tyre Size: 215/65R16  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,011.95	2,452.77	11,559.18	82.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	910.00	1,820.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,741.95</b>	<b>3,362.77</b>	<b>13,379.18</b>	<b>79.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>(S\$)</b>	16,741.95	2,700.00	14,041.95	83.87
<b>+ GST 7.00/7.00% (S\$)</b>	1,171.94	189.00	982.94	83.87
<b>Nett Amount (S\$)</b>	<b>17,913.89</b>	<b>2,889.00</b>	<b>15,024.89</b>	<b>83.87</b>

## INSPECTION

Date of Assignment: 26/02/2019

Date Inspected: 04/03/2019 Inspected At:

Ah Chang Motor Service Centre (HQ)  
 10 ANG MO KIO INDUSTRIAL PARK  
 2A, ANG MO KIO POINT #03-16  
 Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY-UPPER	Mtg Cracked	1,289.00 FL	*1,289.00 FL
2	1		*REAR BUMPER ASSY-LOWER	Buckled	1,055.00 FL	*464.23 FL
3	2		*REAR BUMPER RETAINER	Serviceable	288.00 FL	*- FL
4	2		*REAR BUMPER BRACKET	Repair	286.00 FL	*- FL
5	2		*REAR BUMPER LOWER LAMP	Serviceable	624.00 FL	*- FL
6	2		*REAR BUMPER TOW COVER	Serviceable	180.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	689.00 FL	*554.95 FL
8	1		*REAR BUMPER INNER BEAM	Repair	280.00 FL	*- FL
9	1		*REAR BUMPER ;PWER GARNISH	Serviceable	840.00 FL	*- FL
10	1		*REAR BUMPER ;PWER GARNISH GRILLE	Serviceable	430.00 FL	*- FL
11	1		*REAR TAILGATE ASSY	Repair	3,276.00 FL	*- FL
12	1		*REAR TAILGATE LOCK MECHANISM	Repair	269.00 FL	*- FL
13	2		*REAR TAILGATE RUBBER STOPPER	Serviceable	68.00 FL	*- FL
14	1		*REAR TAILGATE CENTRE LOGO	Not Necessary	138.00 FL	*- FL
15	1		*REAR TAILGATE TIGUAN EMBLEM	Not Necessary	128.00 FL	*- FL
16	1		*REAR TAILGATE 4.2 EMBLEM-RH SIDE	Not Necessary	128.00 FL	*- FL
17	1		*REAR TAILGATE QUATTRO EMBLEM	Not Necessary	128.00 FL	*- FL
18	1		*REAR LEFT TAIL LAMP	Serviceable	879.00 FL	*- FL
19	1		*REAR RIGHT TAIL LAMP	Serviceable	879.00 FL	*- FL
20	1		*REAR END LOWER PANEL	Repair	1,527.00 FL	*- FL
21	12		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
22	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
24	1		*REAR NUMBER PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS
25	1		*REAR BUMPER REVERSE SENSOR	Cracked	1,000.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,681.00</b>	<b>2,568.18</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	<b>669.05</b>	<b>115.41</b>
<b>Total Parts (\$\$)</b>	<b>14,011.95</b>	<b>2,452.77</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGE PARTS	New	1,000.00	400.00
2	TO PUTTY & SPRAY PAINTING REAR PORTION	New	1,000.00	450.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	10.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL REAR INNER TRIM TO FACILITATE THE REPAIR	New	140.00	0.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	0.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN TO FACILITATE THE REPAIR	New	140.00	0.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
9	TOWING SERVICE	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,730.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >