

22/03/2002

ASS. REC. BY:

REF: CS/FCI/9003626/Kgd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

cuts

Meninachia

of

FCI

Date/Time:

3:10pm @ 26/2/19

Estimated Cost:

Bill to:

OD ☒ TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

81p30022

Insured:

SHB 3623C

at Workshop m/s

BH Auto

Tel:

6559 8944

of

Blkl, Sin Ming Ind. Est. sec. C # 01-111

Policy No:

Claim No:

D19001385MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/2/2019

CA / REV / REP. / REV 24 HRS

sup

H.O.D. Endorsement:

Date/Time:

3:10pm @ 26/2/19

Person Contacted:

Jueelyn

Vehicle IN /

OUT

Date/Time	Action/Instruction (✓) Estimate
	81p30022 - X
	SHB 3623C - CS/FCI/18010198/Urban2
11/3/19 @	12:09pm Revised to Meninachia by email.
01/7/19 @	4:39pm Wen Zheng (WKS) informed that the TP owner already convert to claim OD by email.
05/7/19	Submit prelim. report.

convert

REF:

CS/FC119003626/d3

## ASSIGNMENT

From

Date:

05/3/19

Veh No

SLP 3002E

Yr Regn

12 13

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLP 3002E

Make:

Mer E 200

C.C

1991

at Workshop m/s

BH Auto

Colour:

M.D. Blue

A/C

Insured / Std / NI / NA

of

Sp Reading

92713

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

W00 2120342A 872596

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / M/Rim or

(Policy Condition)

Tyre Size:

F:

R:

245/40R18

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

893k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

02

days

Res.: Yes or No

D.O.A.

23/2/19

D.O.L.

5/3/19

Lump Sum:

%

3 Val.: Yes or No

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 05 JUL 2019

Date/Time, File Pass to?



Preli. Report

1) 05/7/19



Final Report

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / L.B.L. (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S.C.P.S. \$

) Photo:

) Other:

) Total:

1215=60

170+60

50

14

294

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	25-02-2019	<b>Our Ref No.</b> D19001385MFSH
<b>Accident Date</b>	23-02-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB3623C	<b>Third Party Vehicle.</b> SLP3002Z
<b>Survey Location</b>	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115	
<b>Contact Person.</b>	JACELYN LOH	
<b>Contact No.</b>	65598944/ 0	<b>Fax No.</b> 65153144
<b>Survey Type</b>	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	BH AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MERINA CHIA SAN SAN	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>  
**Sent:** Monday, 1 July 2019 4:39 PM  
**To:** Shiau Chan (LKKAuto)  
**Cc:** BHAS - Bernard Kee; BHAS - Chan Yun Shi  
**Subject:** RE: KINDLY ADVISE THE STATUS OF VEHICLE SLP 3002Z (DOA: 23/02/2019)

Dear Shiau Chan,

Our insured has been changed to claim own insurance since liability is not clear.

Your side may can close the file.

Thank you.

Best Regards,

Wen Zheng  
Senior Claim Estimator



**BH AUTO SERVICES PTE LTD**

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117  
SINGAPORE 575636 TEL: (65) 6559 8944 FAX: (65) 6269 2404  
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

(W) +65-6559 8945 (F) +65-6269 2404 (HP) +65 9621 2084  
(E) [wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg) <http://www.bhauto.com.sg>



---

**From:** BHAS - Jacelyn Loh  
**Sent:** Monday, 1 July 2019 4:09 PM  
**To:** BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>  
**Cc:** BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>  
**Subject:** FW: KINDLY ADVISE THE STATUS OF VEHICLE SLP 3002Z (DOA: 23/02/2019)

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Monday, 17 June 2019 11:55 AM  
**To:** BHAS - Jacelyn Loh <[Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)>  
**Subject:** KINDLY ADVISE THE STATUS OF VEHICLE SLP 3002Z (DOA: 23/02/2019)

Dear Jacelyn,

Kindly assist to check the status of vehicle.

If done of repair, kindly send us the final bill for finalise.

Best Regards,

**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 11 March 2019 12:09 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Merina Chia San San'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19001385MFSH/1  
**Attachments:** CSFCI19003626Kqd3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SLP 3002Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 26 February 2019 3:51 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Merina Chia San San' <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19001385MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 26 February 2019 3:10 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Merina Chia San San <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19001385MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001385MFSH

Date: 11 March 2019

Our Ref: CS/FCI19003626/Kqd3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 3002Z .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/03/2019 at the premises of M/s BH AUTO. and have the following to report:-

Workshop Estimate Amount	: S\$ 14,699.90 .
Revised Estimate Amount	: S\$ 7,136.80 .
"Check" Items Amount	: S\$ 3,528.70 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:  
The vehicle sustained damages  
at the front o/s portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 8713Z

**Vehicle Details**

Vehicle No.: SLP3002Z  
Vehicle to be Exported: No  
Intended Deregistration Date: 25 Feb 2019  
Vehicle Make: MERCEDES BENZ  
Vehicle Model: E200 SEDAN (R18)  
Primary Colour: Blue  
Manufacturing Year: 2013  
Engine No.: 27492030094475  
Chassis No.: WDD2120342A872596  
Maximum Power Output: 135.0 kW (181 bhp)  
Open Market Value: \$45,943.00  
Original Registration Date: 27 Dec 2013  
First Registration Date: 27 Dec 2013  
Transfer Count: 1  
Actual ARF Paid: \$51,321.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Dec 2023  
PARF Rebate Amount: \$35,924.00

**Intended COE Rebate Details**

COE Expiry Date: 26 Dec 2023  
COE Category: B - Car (1601cc & above)  
COE Period(Years): 10  
QP Paid: \$75,700.00  
COE Rebate Amount: \$36,608.00  
**Total Rebate Amount: \$72,532.00**

The information contained herein is correct as at 25 Feb 2019

OK

# FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coo Renewal Toyota Estima 2.4A



2.38%PA Low Interest@Gv  
Finance, \$0 Admin Fees, \$480/  
Downpayment Monthly \$988  
GV Credit Pte Ltd Size A4



Browse by Category









Sort by Date Posted

20 results/page

10 vehicles

Mercedes Benz E200

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Mercedes Benz E200		Any	Any	2013	Any	Any	Any	Available
	Mercedes-Benz E-Class E200		\$94,800	\$14,800 /yr	19-Dec-2013	1,991 cc	65,100 km	Luxury	Available
Cheapest Unit. Only 1 Owner. Loan Available. Trade In Welcome. Comes With Warranty, 3 Free Servicing Package. Call Now For Viewing.									
Performance Carz Pte Ltd									
Posted: 24-Feb-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									
	Mercedes-Benz E-Class E200		\$91,800	\$14,980 /yr	10-Sep-2013	1,991 cc	99,600 km	Luxury	Available
Posted: 19-Feb-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									
	Mercedes-Benz E-Class E200		\$87,888	\$14,960 /yr	14-Jun-2013	1,991 cc	102,000 km	Luxury	Available
Meticulously Maintained By Owner. Regularly Groomed By EA Detailer Using Top Of Range Products. A Great Workhorse For The Working Professional And Doubles Up As A Family Car. Loan And Trade In Available...									
Posted: 19-Feb-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									
	Mercedes-Benz E-Class E200		\$95,800	\$14,950 /yr	20-Dec-2013	1,991 cc	36,000 km	Luxury	Available
Super Low Mileage! Fully Maintained By Cycle & Carriage. Extremely Smooth Drive, Immaculate Condition, Attractive Interest Rate Of 2.28% Available, High Loan/Trade In Welcome, Contact Us For An Appoin...									
Posted: 15-Feb-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									
	<b>New engines for E-Class and GLC</b> Mercedes-Benz has added three new engines to the E-Class Estate lineup - the E200d SE, E350d SE, and AMG E 43 - as well as one for the AMG GLC 43 Coupe. Read this article								
	Mercedes-Benz E-Class E200		\$86,688	\$15,290 /yr	28-Feb-2013	1,796 cc	77,300 km	Luxury	Available
Elegance Blue Unit With Low Mileage Done, Well Taken Care By Previous Owner With 10/10 On Both Interior And Exterior Condition. Full Cycle And Carriage Servicing Done With All Wear And Tear Parts Repl...									
Karz Automobile									
Posted: 10-Feb-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									
	Mercedes-Benz E-Class E200		\$96,800	\$15,250 /yr	12-Dec-2013	1,991 cc	49,000 km	Luxury	Available
1 Owner! Brand New Road Tax! Genuine Low Mileage Done! Full C&C Serviced! Pristine Brown With Elegant Maroon & Beige Interior. Very Well-Maintained By Previous Owner. See To Believe! Drive Away With A...									
Posted: 29-Jan-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									
	Mercedes-Benz E-Class E200 Avantgarde		\$93,800	\$14,610 /yr	30-Oct-2013	1,991 cc	70,000 km	Luxury	Available
1 Owner. R18 Avantgarde Model, Maintained And Full Service History By Cycle & Carriage. Flexible Loan Can Be Arranged. Call Now For Viewing.									
AMS Motors Pte Ltd									
Posted: 21-Jan-2019 Tags: 2013 Mercedes-Benz E200, 2013 mercedes-benz e200, Mercedes-Benz E200, mercedes-benz e200, Mercedes-Benz, E200, e200, Used Mercedes-Benz									

Compare



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/02/2019 17:32
Date Of Accident	23/02/2019 13:30
Exact Location Of Accident	PARK GREEN CONDOMINIUM BASEMENT CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP3002Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AHTI S/O KESAVAN SREEDHRAN
NRIC No	S0598713Z
Email Address	MICHAELAHTI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96538508
Alternative Phone No	OFFICE-96538508

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 SEDAN (R18)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA214312/1
Cover Note Number	

### Driver

Name of Driver	MICHAEL LESLIE AHTI
NRIC No	S7410953E
Date Of Birth	08/04/1974
Occupation	INDOOR
Date Of Driving Pass	17/11/1992
Driving Experience	26 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96369597
Fax Number	
Contact Number	
EMail Address	MICHAELAHTI@GMAIL.COM

Address	203 PONGGOL SEVENTEENTH AVENUE SINGAPORE
Postcode	829663
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DAUGHTER GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE STATEMENT

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3623C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ONG HAI SOON
NRIC/Passport Number	S0633636A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan

## SKETCH PLAN



A - SLP 3002 Z  
B - SHB 3623 C

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 1:30 pm park green condominium basement car park, visibility was clear and road was dry. At a cross junction I stopped at the stop line, driver of Taxi plate SHB 3623 C ONG HAI SOON License Number SO 633636A stopped at hump also, suddenly he moved ahead past the hump towards my car, I honked to warn him but he struck the front of my car SLP 3002 Z, after he realized he had struck the front of SLP 3002 Z he suddenly reversed back again but I stayed put. Damages to my car include the front right light and bumper, SHB 3623 C damage was limited to front left bumper. We took pictures and exchanged particulars, he offered to pay me \$1.8k for the damages because he was afraid to lose his license to drive if we report the accident. But I said the damages would not cost \$1.8k and decided to file for insurance claims. refer to SHB 3623 C video recording device. 5008143 for details.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(I agree to act as policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
Date/Time:

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

## First Capital Insurance Ltd

30 Robinson Road

#16-01 City House

Singapore (068877)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6507 3848 Fax : 6507 3849

DEAR SIR / MADAM :

*Not Notarized  
61 Pp 81, 1.B.1  
Money After Pairs*

ACCIDENT REPAIR ON: SLP3002Z

MODEL : MERCEDES BENZ E200

POLICY NO : GA214312/1

CHASSIS NO : WDD2120342A872596

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT: 23/02/2019 Time: 1330Hrs at PARK GREEN CONDOMINIUM

THIRD PARTY VEHICLE NO: SHB3623C

Date: 04/03/2019

Page : 1 of 2

BASEMENT CARPARK.

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Headlamp assy RH	1	5,122.00	Broken	5,122.00 ✓
2	Headlamp lower bracket RH	1	265.00	Torn	265.00 ?
3	Headlamp ecu unit RH	1	920.00	Malfunction	920.00 ?
4	Headlamp LED module RH	1	1,080.00	Malfunction	1,080.00 ?
5	Headlamp top frame panel RH	1	1,145.00	Bented	1,145.00 X
6	Front bumper	1	1,845.00	Cut	1,845.00 ✓
7	Front bumper side retainer LH	1	81.00	Necessary	81.00 X
8	Front bumper side retainer RH	1	81.00	Necessary	81.00 ?
9	Front bumper clips	10	7.00	Necessary	70.00 ✓
10	Front bumper rivet	10	7.00	Necessary	70.00 ✓
11	Front bumper side grille RH	1	72.00	Scratches	72.00 ?
12	Front bumper side grille lining chrome RH	1	145.00	Scratches	145.00 ✓
13	Front bumper sponge	1	180.00	Broken	180.00 ?
14	Front bumper reinforcement	1	545.00	Bented	545.00 ?
15	Front bumper sensor	3		Malfunction	?
16	Front bumper sensor ring	3		Necessary	?
17	Front fender RH	1	1,260.00	Bented	1,260.00 X
18	Front fender shield RH	1	430.00	Cut	430.00 X

Sub-Total: 13,311.00

Less: 10% discount - 1,331.10

**Total Parts after 10% discount: 11,979.90**

## Special Nett Items

1 Anti-rust coating

80.00 80.00 X

80.00

**Total Parts: 12,059.90**

## Labour Charges For RH Side Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.

900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

2501

2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	900.00	2801
3	Provide skill labour to disconnect and check electrical wiring	60.00	201
4	Provide skill labour to remove and replace bumper sensors.	80.00	601
5	Provide skill labour to reset headlamp code data system with reprogramming	450.00	?
6	Provide skill labour to reset headlamp led lamp code data system adjustment	250.00	?

**Total Labour:**

2,640.00

**Total Parts & Labour:**

14,699.90

**GST 7%**

1,028.99

**Grand Total:**

15,728.89

**Estimate Repair Duration**

06 days

02 days

ACCIDENT VEHICLE OF : SLP3002Z

Page : 2 of 2

**Remark:** Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

\_\_\_\_\_  
ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kennerh  
 Company : CLK  
 Date : 5/3/19  
 Time : 1pm  
 Contact No : 9691 0663  
 Email : \_\_\_\_\_




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003626/Kqd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-07-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 3623C	Veh. Inspected	SLP 3002Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001385MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	26/02/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES E200 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2120342A872596	Colour	METALLIC DARK BLUE	
Odometer	92713	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	PIRELLI	8 mm	
L/H Front Tyre	245/40 R18	PIRELLI	8 mm	
R/H Rear Tyre	245/40 R18	PIRELLI	8 mm	
L/H Rear Tyre	245/40 R18	PIRELLI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/02/2019	Inspection Date	05/03/2019	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 3002Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEADLAMP ASSY RH	CRACKED	5,122.00	5,122.00
1	HEADLAMP LOWER BRACKET RH	* CHECK	265.00	-
1	HEADLAMP ECU UNIT RH	* CHECK	920.00	-
1	HEADLAMP LED MODULE RH	* CHECK	1,080.00	-
1	HEADLAMP TOP FRAME PANEL RH	TO REPAIR SEE LABOUR	1,145.00	-
1	FRONT BUMPER	BUCKLED	1,845.00	1,845.00
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	81.00	-
1	FRONT BUMPER SIDE RETAINER RH	* CHECK	81.00	-
10	FRONT BUMPER CLIPS @\$7.00	NECESSARY	70.00	70.00
10	FRONT BUMPER RIVET @\$7.00	NECESSARY	70.00	70.00
1	FRONT BUMPER SIDE GRILLE RH	* CHECK	72.00	-
1	FRONT BUMPER SIDE GRILLE LINING CHROME RH	DENTED	145.00	145.00
1	FRONT BUMPER SPONGE	* CHECK	180.00	-
1	FRONT BUMPER REINFORCEMENT	* CHECK	545.00	-
3	FRONT BUMPER SENSOR (NPA)	* CHECK	-	-
3	FRONT BUMPER SENSOR RING (NPA)	* CHECK	-	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	1,260.00	-
1	FRONT FENDER SHIELD RH	SERVICEABLE	430.00	-
	LESS 10% DISCOUNT		-1,331.10	-725.20
			11,979.90	6,526.80
<b>LABOUR</b>				
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF HEADLAMP TOP FRAME PANEL RH AND FRONT FENDER RH.		900.00	250.00
	ANTI-RUST COATING.	NOT NECESSARY	80.00	-
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		900.00	280.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK		60.00	20.00

Report Ref No. CS/FCI19003626/Kqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSORS.		80.00	60.00
	PROVIDE SKILL LABOUR TO RESET HEADLAMP CODE DATA SYSTEM WITH REPROGRAMMING.	* CHECK	450.00	-
	PROVIDE SKILL LABOUR TO RESET HEADLAMP LED LAMP CODE DATA SYSTEM ADJUSTMENT.	* CHECK	250.00	-
			2,720.00	610.00
GRAND TOTAL			14,699.90	7,136.80

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,528.70 NETT)				7,136.80
---	--	--	--	----------

Report Ref No. CS/FCI19003626/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.